Area: Area 1				
X Coord Y C	oord Label	Value	Тур	e Historical
679532.993	3082835.582	J-42SD	0	Manual
679552.959	3082868.66	J-43SD	0	Manual
679149.492	3082933.098	TW01-13	30	Manual
679279.776	3083075.632	TW01-14	10	Manual
679293.56	3082950.498	TW01-17	70	Manual
679360.57	3083026.498	TW01-18	30	Manual
679169.076	3082537.351	TW01-27	70	Manual
679495.884	3082940.973	TW01-33	30	Manual
679304.653	3082548.688	TW01-34	10	Manual
679342.741	3082605.319	TW01-35	50	Manual
679382.89	3082667.527	TW01-36	50	Manual
679433.945	3082731.682	TW01-37	70	Manual
679470.357	3082776.735	TW01-38	30	Manual
679497.331	3082840.396	TW01-39	90	Manual
679524.331	3082886.899	TW01-40	00	Manual
679560.611	3082897.258	TW01-41	0 ا	Manual

Area: Area 5				
X Coord Y C	Coord Label	Value	Type	Historical
679133.429	3083306.313	TW01-01	0 N	I anual
679104.245	3083223.262	TW01-02	0 N	I anual
679242.726	3083326.528	TW01-07	0 N	I anual
679181.275	3083178.288	TW01-08	0 N	I anual
679268.77	3083200.326	TW01-11	0 N	I anual
679301.16	3083254.034	TW01-12	0 N	I anual

Area: Area 1				
X Coord Y C	'oord Label	Value	Тур	e Historical
679149.492	3082933.098	J-13S	0	Manual
679279.683	3083075.429	J-14S	0	Manual
679261.098	3083016.351	J-15S	0	Manual
679222.634	3082840.172	J-16S	0	Manual
679293.56	3082950.498	J-17S	0	Manual
679360.57	3083026.498	J-18S	0	Manual
679343.581	3082969.598	J-19S	0	Manual
679382.864	3083009.113	J-20S	0	Manual
679335.002	3082941.172	J-21S	0	Manual
679252.713	3082781.029	J-22S	0	Manual
679297.001	3082840.697	J-23S	0	Manual
679394.807	3082971.83	J-24S	0	Manual
679146.646	3082549.764	J-25S	0	Manual
679224.585	3082683.14	J-26S	0	Manual
679169.076	3082537.351	J-27S	0	Manual
679272.004	3082652.675	J-28S	0	Manual
679329.438	3082711.096	J-29S	0	Manual
679374.442	3082791.33	J-30S	0	Manual
679410.149	3082845.846	J-31S	0	Manual
679453.476	3082914.115	J-32S	0	Manual
679495.884	3082940.973	J-33S	0	Manual
679304.653	3082548.688	J-34S	0	Manual
679342.741	3082605.319	J-35S	0	Manual
679382.89	3082667.527	J-36S	0	Manual
679433.945	3082731.682	J-37S	0	Manual
679470.357	3082776.735	J-38S	0	Manual
679497.331	3082840.396	J-39S	0	Manual
679524.331	3082886.899	J-40S	0	Manual
679560.607	3082897.258	J-41S	0	Manual
Area: Area 5				
X Coord Y C	oord Label	Value	Тур	e Historical
679133.429	3083306.313	J-01S	0	Manual
679104.245	3083223.262	J-02S	0	Manual
679155.074	3083294.696	J-03S	0	Manual
679171.297	3083289.796	J-04S	0	Manual
679225.856	3083359.974	J-05S	0	Manual
679164.806	3083214.71	J-06S	0	Manual
679242.726	3083326.528	J-07S	0	Manual
679181.275	3083178.288	J-08S	0	Manual
679213.773	3083224.973	J-09S	0	Manual
679280.544	3083305.681	J-10S	0	Manual
679268.77	3083200.326	J-11S	0	Manual
679301.16	3083254.034	J-12S	0	Manual

Area: Area 1				
X Coord Y C	oord Label	Value	Тур	be Historical
679149.492	3082933.098	J-13S	0	Manual
679279.683	3083075.429	J-13S J-14S	0	Manual
679261.098	3083016.351	J-14S J-15S	0	Manual
679222.634	3082840.172	J-15S J-16S	0	Manual
679293.56	3082950.498	J-10S J-17S	0	Manual
679360.57	3083026.498	J-17S J-18S	0	Manual
679343.581	3082969.598	J-16S J-19S	0	Manual
679382.864	3083009.113	J-19S J-20S	0	Manual
679335.002	3082941.172	J-20S J-21S	0	Manual
679252.713	3082781.029	J-21S J-22S	0	Manual
679297.001	3082840.697	J-22S J-23S	0	Manual
679394.807	3082971.83	J-23S J-24S	0	Manual
		J-24S J-25S		
679146.646 679224.585	3082549.764		0	Manual Manual
	3082683.14	J-26S	0	
679169.076	3082537.351	J-27S	0	Manual
679272.004	3082652.675	J-28S	0	Manual
679329.438	3082711.096	J-29S	0	Manual
679374.442	3082791.33	J-30S	0	Manual
679410.149	3082845.846	J-31S	0	Manual
679453.476	3082914.115	J-32S	0	Manual
679495.884	3082940.973	J-33S	0	Manual
679304.653	3082548.688	J-34S	0	Manual
679342.741	3082605.319	J-35S	0	Manual
679382.89	3082667.527	J-36S	0	Manual
679433.945	3082731.682	J-37S	0	Manual
679470.357	3082776.735	J-38S	0	Manual
679497.331	3082840.396	J-39S	0	Manual
679524.331	3082886.899	J-40S	0	Manual
679560.607	3082897.258	J-41S	0	Manual
679532.993	3082835.582	J-42SD	0	Manual
679552.959	3082868.66	J-43SD	0	Manual
Area: Area 5		X 7 1	T	TT' 4 ' 1
X Coord Y C		Value	Typ	
679133.429	3083306.313	J-01S	0	Manual
679104.245	3083223.262	J-02S	0	Manual
679155.074	3083294.696	J-03S	0	Manual
679171.297	3083289.796	J-04S	0	Manual
679225.856	3083359.974	J-05S	0	Manual
679164.806	3083214.71	J-06S	0	Manual
679242.726	3083326.528	J-07S	0	Manual
679181.275	3083178.288	J-08S	0	Manual
679213.773	3083224.973	J-09S	0	Manual
679280.544	3083305.681	J-10S	0	Manual
679268.77	3083200.326	J-11S	0	Manual
670201 16	2002254 024	T 12C	Λ	Manual

3083254.034 J-12S

Manual

679301.16

Area: Area 1 X Coord Y Coord Label Value Type Historical 679149.492 3082933.098 J-13S 2590 Manual 679279.683 2710 3083075.429 J-14S Manual 679261.098 3083016.351 J-15S 1440 Manual 679222.634 3082840.172 J-16S 3680 Manual 679293.56 3082950.498 J-17S 7070 Manual 679360.57 3083026.498 J-18S 3030 Manual 679343.581 4375 3082969.598 J-19S Manual 679382.864 3083009.113 J-20S 4570 Manual 3082941.172 J-21S 4470 679335.002 Manual 679252.713 3082781.029 J-22S 5620 Manual 8090 679297.001 3082840.697 J-23S Manual 679394.807 3082971.83 J-24S 2110 Manual 679146.646 3082549.764 J-25S 1105 Manual 679224.585 3082683.14 J-26S 2540.05 Manual 679169.076 3082537.351 J-27S 2550 Manual 3082652.675 J-28S 679272.004 5510 Manual 3082711.096 J-29S 679329.438 12200 Manual 679374.442 J-30S 3082791.33 14400 Manual 3082845.846 J-31S 15650 Manual 679410.149 679453.476 3082914.115 J-32S 14200 Manual 679495.884 3082940.973 J-33S 2600 Manual 679304.653 3082548.688 J-34S 25400 Manual 5130 679342.741 3082605.319 J-35S Manual 679382.89 3082667.527 J-36S 7830 Manual 679433.945 3082731.682 J-37S 6190 Manual 9900 Manual 679470.357 3082776.735 J-38S 679497.331 3082840.396 J-39S 5110 Manual 9850 Manual 679524.331 3082886.899 J-40S 4830 679560.607 3082897.258 J-41S Manual 679532.993 3082835.582 J-42SD 2030 Manual 679552.959 J-43SD 5420 3082868.66 Manual 679133.429 3083306.313 J-01S 3010 Manual 3083223.262 J-02S 820 Manual 679104.245 659.5 679155.074 3083294.696 J-03S Manual 679171.297 3083289.796 J-04S 786 Manual 679225.856 3083359.974 J-05S 1250 Manual 609 Manual 679164.806 3083214.71 J-06S 2900 679242.726 3083326.528 J-07S Manual 679181.275 3083178.288 J-08S 5020 Manual 3083224.973 J-09S 679213.773 5460 Manual 679280.544 3083305.681 J-10S 1670 Manual 679268.77 3083200.326 J-11S 14300 Manual 679301.16 3083254.034 J-12S 3550 Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN								
Primary Objective of Design	Compare a site mean to a fixed threshold							
Type of Sampling Design	Parametric							
Sample Placement (Location) in the Field	Simple random sampling							
Working (Null) Hypothesis	The mean value at the site exceeds the threshold							
Formula for calculating number of sampling locations	Student's t-test							
Calculated total number of samples	2							
Number of samples on map ^a	23							
Number of selected sample areas b	2							
Specified sampling area ^c	188054.34 m ²							
Total cost of sampling d	\$2,000.00							

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1											
X Coord	Y Coord	Label	Value	Type	Historical						
679133.4290	3083306.3130	TW01-01	0.0102	Manual	Т						
679104.2450	3083223.2620	TW01-02	0.00105	Manual	Т						
679242.7260	3083326.5280	TW01-07	0.00105	Manual	Т						
679181.2750	3083178.2880	TW01-08	0.00105	Manual	Т						
679268.7700	3083200.3260	TW01-11	0.0625	Manual	Т						
679301.1600	3083254.0340	TW01-12	0.0168	Manual	Т						
679286.9817	3083255.2625	J-42SD	0.001	Random							

Area: Area 3										
X Coord Y Coord		Label	Value	Туре	Historical					
679532.9930	3082835.5820	J-42SD	0.001	Manual	Т					
679552.9590	3082868.6600	J-43SD	0.001	Manual	Т					
679149.4920	3082933.0980	TW01-13	0.001	Manual	Т					
679279.7760	3083075.6320	TW01-14	0.001	Manual	Т					
679293.5600	3082950.4980	TW01-17	0.001025	Manual	Т					
679360.5700	3083026.4980	TW01-18	0.001	Manual	Т					

679169.0760	3082537.3510	TW01-27	0.001	Manual	Т
679495.8840	3082940.9730	TW01-33	0.001	Manual	Т
679304.6530	3082548.6880	TW01-34	0.001	Manual	Т
679342.7410	3082605.3190	TW01-35	0.001	Manual	Т
679382.8900	3082667.5270	TW01-36	0.001	Manual	Т
679433.9450	3082731.6820	TW01-37	0.001	Manual	Т
679470.3570	3082776.7350	TW01-38	0.001	Manual	Т
679497.3310	3082840.3960	TW01-39	0.001	Manual	Т
679524.3310	3082886.8990	TW01-40	0.001	Manual	Т
679560.6110	3082897.2580	TW01-41	0.001	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,S is the estimated standard

is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .


The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_			Para	ame	ter	
Analyte	11	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	2	0.013125	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),

True Mean

- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

b This value is automatically calculated by VSP based upon the user defined value of β.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	Number of Samples										
AL=0.0	12	α	;= 5	α:	=10	α=	=15				
AL=U.	JS	s=0.02625	s=0.013125	s=0.02625	s=0.013125	s=0.02625	s=0.013125				
	β=5	830	209	657	165	551	139				
LBGR=90	β=10	658	166	504	127	412	104				
	β=15	552	139	413	104	330	83				
	β=5	209	54	165	42	139	35				
LBGR=80	β=10	166	43	127	33	104	27				
	β=15	139	36	104	27	83	22				
	β=5	94	25	74	20	62	16				
LBGR=70	β=10	75	20	57	15	47	12				
	β=15	63	17	47	13	38	10				

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	2 Samples						
Field collection costs		\$100.00	\$200.00						
Analytical costs	\$400.00	\$400.00	\$800.00						
Sum of Field & Analytical costs		\$500.00	\$1,000.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$2,000.00						

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0.001	0.001	0.001	0.001	0.001	0.001	0.001	0.001	0.001	0.001
10	0.001	0.001	0.001	0.001	0.001	0.001	0.001025	0.00105	0.00105	0.00105
20	0.0102	0.0168	0.0625							

SUMMARY STATISTICS

n			23				
Min			0.001				
Max	(0.0625				
Rang	nge		0.0615				
Mean			0.0047685				
Media	an		0.001				
Varian	Variance		0.00017227				
StdDe	ev		0.013125				
Std Err	ror		0.0027368				
Skewness			4.2551				
Interquartile Range			5e-005				
	Perc	entiles					
1% 5% 10	0%	25%	50% 75% 90% 95% 99%				
0.001 0.001 0.	.001	0.001	0.001	0.00105	0.01416	0.05336	0.0625

Outlier Test

Dixon's extreme value test was performed to test whether the lowest value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

DIXON'S OUTLIER TEST			
Dixon Test Statistic 0			
Dixon 5% Critical Value	0.421		

The calculated test statistic does not exceed the critical value, so the test cannot reject the null hypothesis that there are no outliers in the data, and concludes that the minimum value 0.001 is not an outlier at the 5% significance level.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Dixon's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION T	EST (excluding outliers)
Shapiro-Wilk Test Statistic	0.3359
Shapiro-Wilk 5% Critical Value	0.911

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the minimum value 0.001, do not appear to follow a normal distribution at the 5% level of significance. Dixon's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each

bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST			
Shapiro-Wilk Test Statistic	0.3281		
Shapiro-Wilk 5% Critical Value	0.914		

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN			
95% Parametric UCL	0.009468		
95% Non-Parametric (Chebyshev) UCL	0.0167		

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.0167) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=23 data, AL is the action level or threshold (0.03).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=22 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST			
t-statistic	Critical Value t _{0.95}	Null Hypothesis	
-9.2194	1.7171	Reject	

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+)	95% Critical Value	Null Hypothesis		
22	15	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp
Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1				
X Coord Y Co	oord Label	Value	Type	Historical
679532.993	3082835.582	J-42SD	0.001	Manual
679552.959	3082868.66	J-43SD	0.001	Manual
679149.492	3082933.098	TW01-13	0.001	Manual
679279.776	3083075.632	TW01-14	0.001	Manual
679293.56	3082950.498	TW01-17	0.001025	Manual
679360.57	3083026.498	TW01-18	0.001	Manual
679169.076	3082537.351	TW01-27	0.001	Manual
679495.884	3082940.973	TW01-33	0.001	Manual
679304.653	3082548.688	TW01-34	0.001	Manual
679342.741	3082605.319	TW01-35	0.001	Manual
679382.89	3082667.527	TW01-36	0.001	Manual
679433.945	3082731.682	TW01-37	0.001	Manual
679470.357	3082776.735	TW01-38	0.001	Manual
679497.331	3082840.396	TW01-39	0.001	Manual
679524.331	3082886.899	TW01-40	0.001	Manual
679560.611	3082897.258	TW01-41	0.001	Manual

Area: Area 5

X Coord Y C	loord Label	Value	Type	Historical	
679133.429	3083306.313	TW01-0	10.0102	Manual	
679104.245	3083223.262	TW01-0	20.00105	Manual	
679242.726	3083326.528	TW01-0	70.00105	Manual	
679181.275	3083178.288	TW01-0	80.00105	Manual	
679268.77	3083200.326	TW01-1	10.0625	Manual	
679301.16	3083254.034	TW01-1	20.0168	Manual	

Area: Area 1 X Coord Y Coord Label Value Type Historical 679532.993 3082835.582 J-42SD 43 Manual 679552.959 3082868.66 J-43SD 100 Manual 679149.492 3082933.098 TW01-1343 Manual 3083075.632 TW01-1491.1 Manual 679279.776 679293.56 3082950.498 TW01-1743 Manual 3083026.498 TW01-184280 679360.57 Manual 679169.076 3082537.351 TW01-2743 Manual 3082940.973 TW01-3343 Manual 679495.884 3082548.688 TW01-34113 Manual 679304.653 3082605.319 TW01-3543 Manual 679342.741 3082667.527 TW01-3643 Manual 679382.89 679433.945 3082731.682 TW01-3743 Manual 679470.357 3082776.735 TW01-3843 Manual 679497.331 3082840.396 TW01-39113 Manual 3082886.899 TW01-40777 Manual 679524.331 679560.611 3082897.258 TW01-4143 Manual

Area: Area 5

X Coord Y C	Coord Label	Value	Type	Historical
679133.429	3083306.313	TW01-0	11630	Manual
679104.245	3083223.262	TW01-0	2372	Manual
679242.726	3083326.528	TW01-0	7709	Manual
679181.275	3083178.288	TW01-0	8680	Manual
679268.77	3083200.326	TW01-1	1354	Manual
679301.16	3083254.034	TW01-1	2558	Manual

Area: Area 1				
X Coord Y C	Coord Label	Value	Type	Historical
679149.492	3082933.098	J-13S	5140	Manual
679279.683	3083075.429	J-14S	917 Ma	
679261.098	3083016.351	J-15S	5880	Manual
679222.634	3082840.172	J-16S	3640	Manual
679293.56	3082950.498	J-17S	1130	Manual
679360.57	3083026.498	J-18S	3510	Manual
679343.581	3082969.598	J-19S	1760	Manual
679382.864	3083009.113	J-20S	915 Mai	
679335.002	3082941.172	J-21S	648 Mai	
679252.713	3082781.029	J-22S	1960	Manual
679297.001	3082840.697	J-23S	4180	Manual
679394.807	3082971.83	J-24S	790 Mai	
679146.646	3082549.764	J-25S	13800	Manual
679224.585	3082683.14	J-26S	2800	Manual
679169.076	3082537.351	J-20S J-27S	4660	Manual
679272.004	3082652.675	J-28S	9150	Manual
679329.438	3082711.096	J-29S	3630	Manual
679374.442	3082711.030	J-30S	1770	Manual
679410.149	3082845.846	J-31S	1390	Manual
679453.476	3082914.115	J-31S	2460	Manual
679495.884	3082940.973	J-32S	1240	Manual
679304.653	3082548.688	J-34S	1830	Manual
679342.741	3082605.319	J-35S	2140	Manual
679382.89	3082667.527	J-36S	7640	Manual
679433.945	3082731.682	J-30S	8450	Manual
679470.357	3082776.735	J-38S	3310	Manual
679497.331	3082840.396	J-39S	1160	Manual
679524.331	3082886.899	J-40S	1495	Manual
679560.607	3082897.258	J-41S	2480	Manual
07/300.007	3002071.230	1-410	2 4 60	Manuai
Area: Area 5				
X Coord Y C	Coord Label	Value	Type	Historical
679133.429	3083306.313	J-01S	1200	Manual
679104.245	3083223.262	J-02S	7690	Manual
679155.074	3083294.696	J-03S	2250	Manual
679171.297	3083289.796	J-04S	747 Mai	nual
679225.856	3083359.974	J-05S	959 Ma	nual
679164.806	3083214.71	J-06S	6880	Manual
679242.726	3083326.528	J-07S	11400	Manual
679181.275	3083178.288	J-08S	10900	Manual
679213.773	3083224.973	J-09S	858 Mai	nual
679280.544	3083305.681	J-10S	1090	Manual
679268.77	3083200.326	J-11S	1110	Manual
679301.16	3083254.034	J-12S	748 Mai	nual

Aron Aron 1				
Area: Area 1 X Coord Y C	loord Labol	Value	Tuno	Historical
679149.492	3082933.098	J-13S	Type 2590	Manual
679279.683	3082933.098	J-13S J-14S	2390	Manual
679261.098	3083075.429	J-14S J-15S	1440	
679222.634	3082840.172			Manual
		J-16S	3680	Manual
679293.56	3082950.498	J-17S	7070	Manual
679360.57	3083026.498	J-18S	3030	Manual
679343.581	3082969.598	J-19S	4375	Manual
679382.864	3083009.113	J-20S	4570	Manual
679335.002	3082941.172	J-21S	4470	Manual
679252.713	3082781.029	J-22S	5620	Manual
679297.001	3082840.697	J-23S	8090	Manual
679394.807	3082971.83	J-24S	2110	Manual
679146.646	3082549.764	J-25S	1105	Manual
679224.585	3082683.14	J-26S	2540.05	Manual
679169.076	3082537.351	J-27S	2550	Manual
679272.004	3082652.675	J-28S	5510	Manual
679329.438	3082711.096	J-29S	12200	Manual
679374.442	3082791.33	J-30S	14400	Manual
679410.149	3082845.846	J-31S	15650	Manual
679453.476	3082914.115	J-32S	14200	Manual
679495.884	3082940.973	J-33S	2600	Manual
679304.653	3082548.688	J-34S	25400	Manual
679342.741	3082605.319	J-35S	5130	Manual
679382.89	3082667.527	J-36S	7830	Manual
679433.945	3082731.682	J-37S	6190	Manual
679470.357	3082776.735	J-38S	9900	Manual
679497.331	3082840.396	J-39S	5110	Manual
679524.331	3082886.899	J-40S	9850	Manual
679560.607	3082897.258	J-41S	4830	Manual
679532.993	3082835.582	J-42SD	2030	Manual
679552.959	3082868.66	J-43SD	5420	Manual
Area: Area 5				
X Coord Y C		Value	Type	Historical
679133.429	3083306.313	J-01S	3010	Manual
679104.245	3083223.262	J-02S	820 Mar	nual
679155.074	3083294.696	J-03S	659.5	Manual
679171.297	3083289.796	J-04S	786 Mar	nual
679225.856	3083359.974	J-05S	1250	Manual
679164.806	3083214.71	J-06S	609 Mar	nual
679242.726	3083326.528	J-07S	2900	Manual
679181.275	3083178.288	J-08S	5020	Manual
679213.773	3083224.973	J-09S	5460	Manual
679280.544	3083305.681	J-10S	1670	Manual
679268.77	3083200.326		14300	Manual
679301.16	3083254.034		3550	Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	3
Number of samples on map ^a	23
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling ^d	\$2,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Y Coord	Label	Value	Type	Historical				
679133.4290	3083306.3130	TW01-01	1630	Manual	Т				
679104.2450	3083223.2620	TW01-02	372	Manual	Т				
679242.7260	3083326.5280	TW01-07	709	Manual	Т				
679181.2750	3083178.2880	TW01-08	680	Manual	Т				
679268.7700	3083200.3260	TW01-11	354	Manual	Т				
679301.1600	3083254.0340	TW01-12	558	Manual	Т				
679316.5522	3083281.7965	J-42SD	43	Random					

Area: Area 3										
X Coord	Y Coord	Label	Value	Туре	Historical					
679532.9930	3082835.5820	J-42SD	43	Manual	Т					
679552.9590	3082868.6600	J-43SD	100	Manual	Т					
679149.4920	3082933.0980	TW01-13	43	Manual	Т					
679279.7760	3083075.6320	TW01-14	91.1	Manual	Т					
679293.5600	3082950.4980	TW01-17	43	Manual	Т					
679360.5700	3083026.4980	TW01-18	4280	Manual	Т					
679169.0760	3082537.3510	TW01-27	43	Manual	Т					

679495.8840	3082940.9730	TW01-33	43	Manual	Т
679304.6530	3082548.6880	TW01-34	113	Manual	Т
679342.7410	3082605.3190	TW01-35	43	Manual	Т
679382.8900	3082667.5270	TW01-36	43	Manual	Т
679433.9450	3082731.6820	TW01-37	43	Manual	Т
679470.3570	3082776.7350	TW01-38	43	Manual	Т
679497.3310	3082840.3960	TW01-39	113	Manual	Т
679524.3310	3082886.8990	TW01-40	777	Manual	Т
679560.6110	3082897.2580	TW01-41	43	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,S is the estimated standard

is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyte n	Parameter
-----------	-----------


s	Δ	α	β	$Z_{1-\alpha}^{a}$	Z_{1-β} b	
3	920.76	2436.2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at $1-\alpha$ on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at $1-\alpha$. If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability

b This value is automatically calculated by VSP based upon the user defined value of β.

of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples										
AL=244	4.0	α=	:5	α=	10	α=15				
AL=244	4.2	s=1841.52	s=920.76	s=1841.52	s=920.76	s=1841.52	s=920.76			
	β=5	616	155	487	123	409	103			
LBGR=90	β=10	488	123	374	95	306	77			
	β=15	410	104	306	78	245	62			
	β=5	155	40	123	32	103	27			
LBGR=80	β=10	123	32	95	25	77	20			
	β=15	104	27	78	20	62	16			
	β=5	70	19	55	15	46	12			
LBGR=70	β=10	56	15	43	12	35	10			
	β=15	47	13	35	10	28	8			

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,500.00, which averages out to a per sample cost of \$833.33. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	3 Samples						
Field collection costs		\$100.00	\$300.00						
Analytical costs	\$400.00	\$400.00	\$1,200.00						
Sum of Field & Analytical costs		\$500.00	\$1,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$2,500.00						

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	43	43	43	43	43	43	43	43	43
10	43	43	91.1	100	113	113	354	372	558	680
20	709	777	1630	4280						

SUMMARY STATISTICS				
n	24			

l	Min		0					
l l	<i>l</i> lax				4280			
Ra	ange				4280			
M	lean			4	27.09			
Me	edian			(67.05			
Vai	iance			8.17	'64e+0	05		
St	dDev		904.23					
Std Error				1	84.58			
Ske	wness			3	3.7327			
Interqua	rtile Ra	nge	468.5					
		Pe	rcentil	es				
1% 5%	10%	25%	50%	75%	90%	95%	99%	
0 10.7	5 43	43	67.05	511.5	1204	3618	4280	

Outlier Test

Dixon's extreme value test was performed to test whether the lowest value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

DIXON'S OUTLIER TEST				
Dixon Test Statistic 0.055341				
Dixon 5% Critical Value	0.421			

The calculated test statistic does not exceed the critical value, so the test cannot reject the null hypothesis that there are no outliers in the data, and concludes that the minimum value 0 is not an outlier at the 5% significance level.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Dixon's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.4994				
Shapiro-Wilk 5% Critical Value	0.911				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the minimum value 0, do not appear to follow a normal distribution at the 5% level of significance. Dixon's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally

distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was

conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.4854			
Shapiro-Wilk 5% Critical Value	0.916			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	743.4
95% Non-Parametric (Chebyshev) UCL	1232

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (1232) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SR}$$

where

x is the sample mean of the n=24 data, AL is the action level or threshold (2444.2),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=23 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic Critical Value $t_{0.95}$ Null Hypothesis						
-10.928	1.7139	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothesis						
23	16	Reject				

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.

SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	4
Number of samples on map ^a	42
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling ^d	\$3,000.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1										
X Coord	X Coord Y Coord Label Value Type History									
679133.4290	3083306.3130	J-01S	1200	Manual	Т					
679104.2450	3083223.2620	J-02S	7690	Manual	Т					
679155.0740	3083294.6960	J-03S	2250	Manual	Т					
679171.2970	3083289.7960	J-04S	747	Manual	Т					
679225.8560	3083359.9740	J-05S	959	Manual	Т					
679164.8060	3083214.7100	J-06S	6880	Manual	Т					
679242.7260	3083326.5280	J-07S	11400	Manual	Т					
679181.2750	3083178.2880	J-08S	10900	Manual	Т					
679213.7730	3083224.9730	J-09S	858	Manual	Т					
679280.5440	3083305.6810	J-10S	1090	Manual	Т					
679268.7700	3083200.3260	J-11S	1110	Manual	Т					
679301.1600	3083254.0340	J-12S	748	Manual	Т					

Area: Area 3							
X Coord Y Coord Label Value Type History							
679149.4920	3082933.0980	J-13S	5140	Manual	Т		
679279.6830	3083075.4290	J-14S	917	Manual	Т		

679261.0980 3083016.3510 J-15S 5880 Manual T 679222.6340 3082840.1720 J-16S 3640 Manual T 679293.5600 3082950.4980 J-17S 1130 Manual T 679360.5700 3083026.4980 J-18S 3510 Manual T 679343.5810 3082969.5980 J-19S 1760 Manual T 679382.8640 3083009.1130 J-20S 915 Manual T 679335.0020 3082941.1720 J-21S 648 Manual T 679252.7130 3082781.0290 J-22S 1960 Manual T 679297.0010 3082840.6970 J-23S 4180 Manual T 679394.8070 3082549.7640 J-24S 790 Manual T 679169.0760 3082537.3510 J-26S 2800 Manual T 679329.4380 3082711.0960 J-29S 3630 Manual T 679379.4.4420 308						
679293.5600 3082950.4980 J-17S 1130 Manual T 679360.5700 3083026.4980 J-18S 3510 Manual T 679343.5810 3082969.5980 J-19S 1760 Manual T 679382.8640 3083009.1130 J-20S 915 Manual T 679335.0020 3082941.1720 J-21S 648 Manual T 679252.7130 3082781.0290 J-22S 1960 Manual T 679297.0010 3082840.6970 J-23S 4180 Manual T 679394.8070 3082971.8300 J-24S 790 Manual T 679146.6460 3082549.7640 J-25S 13800 Manual T 679169.0760 3082537.3510 J-27S 4660 Manual T 679329.4380 3082711.0960 J-29S 3630 Manual T 679329.4380 3082791.3300 J-30S 1770 Manual T 679410.1490 3082	679261.0980	3083016.3510	J-15S	5880	Manual	Т
679360.5700 3083026.4980 J-18S 3510 Manual T 679343.5810 3082969.5980 J-19S 1760 Manual T 679382.8640 3083009.1130 J-20S 915 Manual T 679252.7130 3082941.1720 J-21S 648 Manual T 679297.0010 3082840.6970 J-22S 1960 Manual T 679394.8070 3082971.8300 J-24S 790 Manual T 679146.6460 3082549.7640 J-25S 13800 Manual T 679224.5850 3082683.1400 J-26S 2800 Manual T 679272.0040 3082537.3510 J-27S 4660 Manual T 679329.4380 3082711.0960 J-29S 3630 Manual T 679329.4380 3082711.0960 J-29S 3630 Manual T 679374.4420 3082879.3300 J-30S 1770 Manual T 679453.4760 3082914.1150 J-32S 2460 Manual T 679453.4760 3082914.1150 J-32S 2460 Manual T 679342.7410 3082605.3190 J-33S 1240 Manual T 679342.7410 3082605.3190 J-35S 2140 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679433.9450 3082716.820 J-37S 8450 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679497.3310 3082886.8990 J-40S 1495 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T	679222.6340	3082840.1720	J-16S	3640	Manual	Т
679343.5810 3082969.5980 J-19S 1760 Manual T 679382.8640 3083009.1130 J-20S 915 Manual T 679252.7130 3082941.1720 J-21S 648 Manual T 679297.0010 3082840.6970 J-22S 1960 Manual T 679394.8070 3082971.8300 J-24S 790 Manual T 679146.6460 3082549.7640 J-25S 13800 Manual T 679272.0040 3082683.1400 J-26S 2800 Manual T 679272.0040 3082652.6750 J-28S 9150 Manual T 679374.4420 308271.3000 J-29S 3630 Manual T 679374.4420 308271.3000 J-29S 3630 Manual T 679374.4420 3082971.3300 J-30S 1770 Manual T 679410.1490 3082845.8460 J-31S 1390 Manual T 679495.8840 3082914.1150 J-32S 2460 Manual T 679342.7410 3082605.3190 J-33S 1240 Manual T 679342.7410 3082605.3190 J-33S 1240 Manual T 679342.7410 3082605.3190 J-35S 2140 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679497.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679293.5600	3082950.4980	J-17S	1130	Manual	Т
679382.8640 3083009.1130 J-20S 915 Manual T 679335.0020 3082941.1720 J-21S 648 Manual T 679252.7130 3082781.0290 J-22S 1960 Manual T 679297.0010 3082840.6970 J-23S 4180 Manual T 679394.8070 3082971.8300 J-24S 790 Manual T 679146.6460 3082549.7640 J-25S 13800 Manual T 679224.5850 3082683.1400 J-26S 2800 Manual T 679169.0760 3082537.3510 J-27S 4660 Manual T 679272.0040 3082652.6750 J-28S 9150 Manual T 679374.4420 3082711.0960 J-29S 3630 Manual T 679410.1490 3082845.8460 J-31S 1390 Manual T 679453.4760 3082914.1150 J-32S 2460 Manual T 679304.6530 3082	679360.5700	3083026.4980	J-18S	3510	Manual	Т
679335.0020 3082941.1720 J-21S 648 Manual T 679252.7130 3082840.6970 J-22S 1960 Manual T 679394.8070 3082840.6970 J-23S 4180 Manual T 679394.8070 3082849.7640 J-25S 13800 Manual T 679146.6460 3082549.7640 J-25S 13800 Manual T 679224.5850 3082683.1400 J-26S 2800 Manual T 679169.0760 3082537.3510 J-27S 4660 Manual T 679272.0040 3082652.6750 J-28S 9150 Manual T 679329.4380 3082711.0960 J-29S 3630 Manual T 679374.4420 3082791.3300 J-30S 1770 Manual T 679410.1490 3082845.8460 J-31S 1390 Manual T 679453.4760 3082914.1150 J-32S 2460 Manual T 679495.8840 3082914.1150 J-32S 2460 Manual T 679304.6530 3082548.6880 J-34S 1830 Manual T 679342.7410 3082605.3190 J-35S 2140 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679470.3570 308276.7350 J-38S 3310 Manual T 679470.3570 308276.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679343.5810	3082969.5980	J-19S	1760	Manual	Т
679252.7130 3082781.0290 J-22S 1960 Manual T 679297.0010 3082840.6970 J-23S 4180 Manual T 679394.8070 3082971.8300 J-24S 790 Manual T 679146.6460 3082549.7640 J-25S 13800 Manual T 679224.5850 3082683.1400 J-26S 2800 Manual T 679169.0760 3082537.3510 J-27S 4660 Manual T 679272.0040 3082652.6750 J-28S 9150 Manual T 679329.4380 3082711.0960 J-29S 3630 Manual T 679374.4420 3082791.3300 J-30S 1770 Manual T 679453.4760 3082845.8460 J-31S 1390 Manual T 679495.8840 3082914.1150 J-32S 2460 Manual T 679304.6530 3082548.6880 J-34S 1830 Manual T 679382.8900 30	679382.8640	3083009.1130	J-20S	915	Manual	Т
679297.0010 3082840.6970 J-23S 4180 Manual T 679394.8070 3082971.8300 J-24S 790 Manual T 679146.6460 3082549.7640 J-25S 13800 Manual T 679224.5850 3082683.1400 J-26S 2800 Manual T 679169.0760 3082537.3510 J-27S 4660 Manual T 679272.0040 3082652.6750 J-28S 9150 Manual T 679329.4380 3082711.0960 J-29S 3630 Manual T 679374.4420 3082791.3300 J-30S 1770 Manual T 679410.1490 3082845.8460 J-31S 1390 Manual T 679495.8840 3082914.1150 J-32S 2460 Manual T 679304.6530 3082940.9730 J-33S 1240 Manual T 679342.7410 3082605.3190 J-35S 2140 Manual T 679433.9450 30	679335.0020	3082941.1720	J-21S	648	Manual	Т
679394.8070 3082971.8300 J-24S 790 Manual T 679146.6460 3082549.7640 J-25S 13800 Manual T 679169.0760 3082537.3510 J-27S 4660 Manual T 679272.0040 3082652.6750 J-28S 9150 Manual T 679329.4380 3082711.0960 J-29S 3630 Manual T 679374.4420 3082791.3300 J-30S 1770 Manual T 679453.4760 3082914.1150 J-32S 2460 Manual T 679495.8840 3082914.1150 J-32S 2460 Manual T 679304.6530 3082548.6880 J-34S 1830 Manual T 679342.7410 3082667.5270 J-36S 7640 Manual T 679433.9450 308276.7350 J-37S 8450 Manual T 679497.3310 3082840.3960 J-37S 8450 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679252.7130	3082781.0290	J-22S	1960	Manual	Т
679146.6460 3082549.7640 J-25S 13800 Manual T 679224.5850 3082683.1400 J-26S 2800 Manual T 679169.0760 3082537.3510 J-27S 4660 Manual T 679272.0040 3082652.6750 J-28S 9150 Manual T 679329.4380 3082711.0960 J-29S 3630 Manual T 679374.4420 3082791.3300 J-30S 1770 Manual T 679410.1490 3082845.8460 J-31S 1390 Manual T 679453.4760 3082914.1150 J-32S 2460 Manual T 679495.8840 3082940.9730 J-33S 1240 Manual T 679304.6530 3082548.6880 J-34S 1830 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3	679297.0010	3082840.6970	J-23S	4180	Manual	Т
679224.5850 3082683.1400 J-26S 2800 Manual T 679169.0760 3082537.3510 J-27S 4660 Manual T 679272.0040 3082652.6750 J-28S 9150 Manual T 679374.4420 3082791.3300 J-30S 1770 Manual T 679410.1490 3082845.8460 J-31S 1390 Manual T 679495.8840 3082914.1150 J-32S 2460 Manual T 679304.6530 3082940.9730 J-33S 1240 Manual T 679342.7410 3082605.3190 J-34S 1830 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679433.9450 3082731.6820 J-37S 8450 Manual T 679470.3570 308276.7350 J-38S 3310 Manual T 679497.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679394.8070	3082971.8300	J-24S	790	Manual	Т
679169.0760 3082537.3510 J-27S 4660 Manual T 679272.0040 3082652.6750 J-28S 9150 Manual T 679329.4380 3082711.0960 J-29S 3630 Manual T 679374.4420 3082791.3300 J-30S 1770 Manual T 679410.1490 3082845.8460 J-31S 1390 Manual T 679453.4760 3082914.1150 J-32S 2460 Manual T 679495.8840 3082940.9730 J-33S 1240 Manual T 679304.6530 3082548.6880 J-34S 1830 Manual T 679382.8900 3082605.3190 J-35S 2140 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679470.3570 3082731.6820 J-37S 8450 Manual T 679470.3570 308276.7350 J-38S 3310 Manual T 679497.3310 3082886.8990 J-40S 11495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679146.6460	3082549.7640	J-25S	13800	Manual	Т
679272.0040 3082652.6750 J-28S 9150 Manual T 679329.4380 3082711.0960 J-29S 3630 Manual T 679374.4420 3082791.3300 J-30S 1770 Manual T 679410.1490 3082845.8460 J-31S 1390 Manual T 679453.4760 3082914.1150 J-32S 2460 Manual T 679495.8840 3082940.9730 J-33S 1240 Manual T 679304.6530 3082548.6880 J-34S 1830 Manual T 679342.7410 3082605.3190 J-35S 2140 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679433.9450 3082731.6820 J-37S 8450 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679224.5850	3082683.1400	J-26S	2800	Manual	Т
679329.4380 3082711.0960 J-29S 3630 Manual T 679410.1490 3082845.8460 J-31S 1390 Manual T 679495.8840 3082940.9730 J-33S 1240 Manual T 679304.6530 3082548.6880 J-34S 1830 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679470.3570 3082731.6820 J-37S 8450 Manual T 679497.3310 3082840.3960 J-38S 3310 Manual T 679497.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679169.0760	3082537.3510	J-27S	4660	Manual	Т
679374.4420 3082791.3300 J-30S 1770 Manual T 679410.1490 3082845.8460 J-31S 1390 Manual T 679453.4760 3082914.1150 J-32S 2460 Manual T 679495.8840 3082940.9730 J-33S 1240 Manual T 679304.6530 3082548.6880 J-34S 1830 Manual T 679342.7410 3082605.3190 J-35S 2140 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679433.9450 3082731.6820 J-37S 8450 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679272.0040	3082652.6750	J-28S	9150	Manual	Т
679410.1490 3082845.8460 J-31S 1390 Manual T 679453.4760 3082914.1150 J-32S 2460 Manual T 679495.8840 3082940.9730 J-33S 1240 Manual T 679304.6530 3082548.6880 J-34S 1830 Manual T 679342.7410 3082605.3190 J-35S 2140 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679470.3570 3082731.6820 J-37S 8450 Manual T 679470.3570 308276.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679329.4380	3082711.0960	J-29S	3630	Manual	Т
679453.4760 3082914.1150 J-32S 2460 Manual T 679495.8840 3082940.9730 J-33S 1240 Manual T 679304.6530 3082548.6880 J-34S 1830 Manual T 679342.7410 3082605.3190 J-35S 2140 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679433.9450 3082731.6820 J-37S 8450 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679374.4420	3082791.3300	J-30S	1770	Manual	Т
679495.8840 3082940.9730 J-33S 1240 Manual T 679304.6530 3082548.6880 J-34S 1830 Manual T 679342.7410 3082605.3190 J-35S 2140 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679433.9450 3082731.6820 J-37S 8450 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679410.1490	3082845.8460	J-31S	1390	Manual	Т
679304.6530 3082548.6880 J-34S 1830 Manual T 679342.7410 3082605.3190 J-35S 2140 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679433.9450 3082731.6820 J-37S 8450 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679453.4760	3082914.1150	J-32S	2460	Manual	Т
679342.7410 3082605.3190 J-35S 2140 Manual T 679382.8900 3082667.5270 J-36S 7640 Manual T 679433.9450 3082731.6820 J-37S 8450 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679495.8840	3082940.9730	J-33S	1240	Manual	Т
679382.8900 3082667.5270 J-36S 7640 Manual T 679433.9450 3082731.6820 J-37S 8450 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679304.6530	3082548.6880	J-34S	1830	Manual	Т
679433.9450 3082731.6820 J-37S 8450 Manual T 679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679342.7410	3082605.3190	J-35S	2140	Manual	Т
679470.3570 3082776.7350 J-38S 3310 Manual T 679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679382.8900	3082667.5270	J-36S	7640	Manual	Т
679497.3310 3082840.3960 J-39S 1160 Manual T 679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679433.9450	3082731.6820	J-37S	8450	Manual	Т
679524.3310 3082886.8990 J-40S 1495 Manual T 679560.6070 3082897.2580 J-41S 2480 Manual T	679470.3570	3082776.7350	J-38S	3310	Manual	Т
679560.6070 3082897.2580 J-41S 2480 Manual T	679497.3310	3082840.3960	J-39S	1160	Manual	Т
	679524.3310	3082886.8990	J-40S	1495	Manual	Т
679328.5397 3082643.5206 0 Random	679560.6070	3082897.2580	J-41S	2480	Manual	Т
	679328.5397	3082643.5206		0	Random	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples

are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_		Parameter							
Analyte	"	S Δ α β $Z_{1-\alpha}$ α $Z_{1-\beta}$								
	4	3329.4	6513.2	0.05	0.1	1.64485	1.28155			


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	Number of Samples								
AL=6521.2		α=5		α=10		α=15			
		s=6658.8	s=3329.4	s=6658.8	s=3329.4	s=6658.8	s=3329.4		
	β=5	1130	284	894	225	751	188		
LBGR=90	β=10	895	225	686	173	561	141		
	β=15	751	189	562	141	449	113		
	β=5	284	72	225	57	188	48		
LBGR=80	β=10	225	58	173	44	141	36		
	β=15	189	49	141	36	113	29		
LBGR=70	β=5	127	33	101	26	84	22		

β=10	101	27	77	20	63	17
β=15	85	23	64	17	51	13

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$3,000.00, which averages out to a per sample cost of \$750.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	4 Samples			
Field collection costs		\$100.00	\$400.00			
Analytical costs	\$400.00	\$400.00	\$1,600.00			
Sum of Field & Analytical costs		\$500.00	\$2,000.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$3,000.00			

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	648	747	748	790	858	915	917	959	1090
10	1110	1130	1160	1200	1240	1390	1495	1760	1770	1830
20	1960	2140	2250	2460	2480	2800	3310	3510	3630	3640
30	4180	4660	5140	5140	5880	6880	7640	7690	8450	9150
40	1.09e+004	1.14e+004	1.38e+004							

SUMMARY STATISTICS				
n	43			
Min	0			
Max	13800			
Range	13800			
Mean	3508.1			
Median	2140			
Variance	1.1121e+007			
StdDev	3334.8			
Std Error	508.56			
Skewness	1.4617			
Interquartile Range	4030			

	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	667.8	764.8	1110	2140	5140	8870	1.13e+004	1.38e+004

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	3.066	3.06	Yes		

The test statistic 3.066 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS				
1	13800			

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Shapiro-Wilk Test Statistic	0.8126			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.816			
Shapiro-Wilk 5% Critical Value	0.943			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	4363
95% Non-Parametric (Chebyshev) UCL	5725

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (5725) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=43 data,

AL is the action level or threshold (6521.2),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=42 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic	Critical Value t _{0.95}	Null Hypothesis			
-5.9249	1.682	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+)	95% Critical Value	Null Hypothesis			
35	27	Reject			

This report was automatically produced * by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN	
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	7
Number of samples on map ^a	44
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling ^d	\$4,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical					
679133.4290	3083306.3130	J-01S	3010	Manual	Т					
679104.2450	3083223.2620	J-02S	820	Manual	Т					
679155.0740	3083294.6960	J-03S	659.5	Manual	Т					
679171.2970	3083289.7960	J-04S	786	Manual	Т					
679225.8560	3083359.9740	J-05S	1250	Manual	Т					
679164.8060	3083214.7100	J-06S	609	Manual	Т					
679242.7260	3083326.5280	J-07S	2900	Manual	Т					
679181.2750	3083178.2880	J-08S	5020	Manual	Т					
679213.7730	3083224.9730	J-09S	5460	Manual	Т					
679280.5440	3083305.6810	J-10S	1670	Manual	Т					
679268.7700	3083200.3260	J-11S	14300	Manual	Т					
679301.1600	3083254.0340	J-12S	3550	Manual	Т					

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			
679149.4920	3082933.0980	J-13S	2590	Manual	Т			
679279.6830	3083075.4290	J-14S	2710	Manual	Т			

679261.0980	3083016.3510	J-15S	1440	Manual	Т
679222.6340	3082840.1720	J-16S	3680	Manual	Т
679293.5600	3082950.4980	J-17S	7070	Manual	Т
679360.5700	3083026.4980	J-18S	3030	Manual	Т
679343.5810	3082969.5980	J-19S	4375	Manual	Т
679382.8640	3083009.1130	J-20S	4570	Manual	Т
679335.0020	3082941.1720	J-21S	4470	Manual	Т
679252.7130	3082781.0290	J-22S	5620	Manual	Т
679297.0010	3082840.6970	J-23S	8090	Manual	Т
679394.8070	3082971.8300	J-24S	2110	Manual	Т
679146.6460	3082549.7640	J-25S	1105	Manual	Т
679224.5850	3082683.1400	J-26S	2540.05	Manual	Т
679169.0760	3082537.3510	J-27S	2550	Manual	Т
679272.0040	3082652.6750	J-28S	5510	Manual	Т
679329.4380	3082711.0960	J-29S	12200	Manual	Т
679374.4420	3082791.3300	J-30S	14400	Manual	Т
679410.1490	3082845.8460	J-31S	15650	Manual	Т
679453.4760	3082914.1150	J-32S	14200	Manual	Т
679495.8840	3082940.9730	J-33S	2600	Manual	Т
679304.6530	3082548.6880	J-34S	25400	Manual	Т
679342.7410	3082605.3190	J-35S	5130	Manual	Т
679382.8900	3082667.5270	J-36S	7830	Manual	Т
679433.9450	3082731.6820	J-37S	6190	Manual	Т
679470.3570	3082776.7350	J-38S	9900	Manual	Т
679497.3310	3082840.3960	J-39S	5110	Manual	Т
679524.3310	3082886.8990	J-40S	9850	Manual	Т
679560.6070	3082897.2580	J-41S	4830	Manual	Т
679532.9930	3082835.5820	J-42SD	2030	Manual	Т
679552.9590	3082868.6600	J-43SD	5420	Manual	Т
679445.8435	3082826.2860		0	Random	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at

the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-R) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

 $\begin{array}{l} \mathcal{S} \\ \Delta \\ \alpha \\ \beta \\ Z_{1-\alpha} \\ Z_{1-\beta} \end{array}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_			Parar	nete	er	
Analyte	n	S	Δ	α	β	Z _{1-α} ^a	Z_{1-β} b
	7	5094.2	6513.2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	Number of Samples									
AL=652	1 0	α=	:5	α=	10	α=	15			
AL=032	1.2	s=10188.4	s=5094.2	s=10188.4	s=5094.2	s=10188.4	s=5094.2			
	β=5	2643	662	2092	524	1756	440			
LBGR=90	β=10	2092	524	1605	402	1313	329			
	β=15	1757	441	1313	329	1050	263			
	β=5	662	167	524	132	440	111			
LBGR=80	β=10	524	133	402	102	329	83			
-	β=15	441	112	329	83	263	67			
LBGR=70	β=5	295	75	234	59	196	50			

β=10	234	60	179	46	147	37
β=15	197	51	147	38	118	30

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$4,500.00, which averages out to a per sample cost of \$642.86. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	7 Samples					
Field collection costs		\$100.00	\$700.00					
Analytical costs	\$400.00	\$400.00	\$2,800.00					
Sum of Field & Analytical costs		\$500.00	\$3,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$4,500.00					

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	609	659.5	786	820	1105	1250	1440	1670	2030
10	2110	2540	2550	2590	2600	2710	2900	3010	3030	3550
20	3680	4375	4470	4570	4830	5020	5110	5130	5420	5460
30	5510	5620	6190	7070	7830	8090	9850	9900	1.22e+004	1.42e+004
40	1.43e+004	1.44e+004	1.565e+004	2.54e+004						

SUMMARY ST	SUMMARY STATISTICS					
n	44					
Min	0					
Max	25400					
Range	25400					
Mean	5505.3					
Median	4422.5					
Variance	2.5951e+007					
StdDev	5094.2					
Std Error	767.98					
Skewness	1.8979					
Interquartile Range	4632.5					

	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	621.6	803	2218	4423	6850	1.425e+004	1.534e+004	2.54e+004

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST						
I	k	Test Statistic R _k 5% Critical Value C _k Significant?					
-	1	3.905	3.08	Yes			

The test statistic 3.905 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	25400

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Shapiro-Wilk Test Statistic	0.8597					
Shapiro-Wilk 5% Critical Value	0.943					

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic	0.8167				
Shapiro-Wilk 5% Critical Value	0.944				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	6796				
95% Non-Parametric (Chebyshev) UCL	8853				

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (8853) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=44 data,

AL is the action level or threshold (6521.2),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=43 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic Critical Value $t_{0.95}$ Null Hypothesis						
-1.3228	1.6811	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+)	95% Critical Value	Null Hypothesis					
33	27	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1 Type X Coord Y Coord Label Value Historical 3082835.582 J-42SD 8.5 Manual 679532.993 J-43SD 7.6 Manual 679552.959 3082868.66 679149.492 3082933.098 TW01-131.35 Manual 3083075.632 TW01-142.7 Manual 679279.776 679293.56 3082950.498 TW01-174.6 Manual 3083026.498 TW01-1821.1 Manual 679360.57 679169.076 3082537.351 TW01-2716.65 Manual 3082940.973 TW01-339.5 Manual 679495.884 3082548.688 TW01-348.2 Manual 679304.653 679342.741 3082605.319 TW01-3519.5 Manual 3082667.527 TW01-3643.7 Manual 679382.89 679433.945 3082731.682 TW01-376.6 Manual 679470.357 3082776.735 TW01-3810.5 Manual 679497.331 3082840.396 TW01-391.35 Manual 3082886.899 TW01-401.35 Manual 679524.331 679560.611 3082897.258 TW01-417.5 Manual

Area: Area 5

X Coord Y	Coord Label	Value	Туре	e Historical
679133.429	3083306.313	TW01-01	1.35	Manual
679104.245	3083223.262	TW01-02	22.8	Manual
679242.726	3083326.528	TW01-07	71.35	Manual
679181.275	3083178.288	TW01-08	33.8	Manual
679268.77	3083200.326	TW01-11	13.5	Manual
679301.16	3083254.034	TW01-12	21.35	Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	3
Number of samples on map ^a	42
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling ^d	\$2,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1								
X Coord	Y Coord	Label	Value	Туре	Historical				
679133.4290	3083306.3130	J-01S	0.14	Manual	Т				
679104.2450	3083223.2620	J-02S	0.34	Manual	Т				
679155.0740	3083294.6960	J-03S	0.1	Manual	Т				
679171.2970	3083289.7960	J-04S	0.115	Manual	Т				
679225.8560	3083359.9740	J-05S	0.08	Manual	Т				
679164.8060	3083214.7100	J-06S	0.23	Manual	Т				
679242.7260	3083326.5280	J-07S	0.47	Manual	Т				
679181.2750	3083178.2880	J-08S	0.29	Manual	Т				
679213.7730	3083224.9730	J-09S	0.105	Manual	Т				
679280.5440	3083305.6810	J-10S	0.105	Manual	Т				
679268.7700	3083200.3260	J-11S	0.26	Manual	Т				
679301.1600	3083254.0340	J-12S	0.09	Manual	Т				

Area: Area 3							
X Coord Y Coord Label Value Type Historic							
679149.4920	3082933.0980	J-13S	0.54	Manual	Т		

679279.6830 3083075.4290 J-14S 0.115 Manual	T
679261.0980 3083016.3510 J-15S 0.38 Manua	l T
679222.6340 3082840.1720 J-16S 0.33 Manua	T
679293.5600 3082950.4980 J-17S 0.41 Manua	Т
679360.5700 3083026.4980 J-18S 0.44 Manua	Т
679343.5810 3082969.5980 J-19S 1.7 Manua	Т
679382.8640 3083009.1130 J-20S 0.12 Manua	Т
679335.0020 3082941.1720 J-21S 0.1 Manual	Т
679252.7130 3082781.0290 J-22S 0.74 Manual	Т
679297.0010 3082840.6970 J-23S 1.4 Manual	Т
679394.8070 3082971.8300 J-24S 0.3 Manual	Т
679146.6460 3082549.7640 J-25S 1 Manual	Т
679224.5850 3082683.1400 J-26S 0.11 Manual	Т
679169.0760 3082537.3510 J-27S 1 Manual	Т
679272.0040 3082652.6750 J-28S 1.2 Manual	Т
679329.4380 3082711.0960 J-29S 0.58 Manual	Т
679374.4420 3082791.3300 J-30S 0.54 Manual	Т
679410.1490 3082845.8460 J-31S 0.23 Manua	Т
679453.4760 3082914.1150 J-32S 1.1 Manual	Т
679495.8840 3082940.9730 J-33S 0.81 Manua	Т
679304.6530 3082548.6880 J-34S 0.8 Manual	Т
679342.7410 3082605.3190 J-35S 0.78 Manual	Т
679382.8900 3082667.5270 J-36S 1.7 Manual	Т
679433.9450 3082731.6820 J-37S 2.1 Manual	Т
679470.3570 3082776.7350 J-38S 2.2 Manual	Т
679497.3310 3082840.3960 J-39S 0.7 Manual	Т
679524.3310 3082886.8990 J-40S 0.62 Manual	Т
679560.6070 3082897.2580 J-41S 1.7 Manual	Т
679330.0243 3082973.9575 0 Randon	m

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is $1-\beta$.

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter					
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	3	0.58481	2	0.05	0.1	1.64485	1.28155


 $^{\text{a}}$ This value is automatically calculated by VSP based upon the user defined value of α

^b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=0.39		α=5		α=	10	α=15		
		s=1.16962	s=0.58481	s=1.16962	s=0.58481	s=1.16962	s=0.58481	
	β=5	9735	2435	7704	1927	6467	1618	
LBGR=90	β=10	7704	1927	5910	1478	4834	1209	
	β=15	6468	1618	4834	1209	3866	967	
	β=5	2435	610	1927	483	1618	405	
LBGR=80	β=10	1927	483	1478	371	1209	303	
	β=15	1618	406	1209	303	967	243	
LBGR=70	β=5	1083	272	857	215	720	181	

β=10	858	216	658	165	538	135
β=15	720	181	538	136	430	108

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,500.00, which averages out to a per sample cost of \$833.33. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	3 Samples		
Field collection costs		\$100.00	\$300.00		
Analytical costs	\$400.00	\$400.00	\$1,200.00		
Sum of Field & Analytical costs		\$500.00	\$1,500.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$2,500.00		

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.08	0.09	0.1	0.1	0.105	0.105	0.11	0.115	0.115
10	0.12	0.14	0.23	0.23	0.26	0.29	0.3	0.33	0.34	0.38
20	0.41	0.44	0.47	0.54	0.54	0.58	0.62	0.7	0.74	0.78
30	0.8	0.81	1	1	1.1	1.2	1.4	1.7	1.7	1.7
40	2.1	2.2								

SUMMARY STATISTICS				
n	42			
Min	0			
Max	2.2			
Range	2.2			
Mean	0.62071			
Median	0.425			
Variance	0.342			
StdDev	0.58481			
Std Error	0.090238			
Skewness	1.2555			
Interquartile Range	0.73875			

	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.0815	0.1	0.1187	0.425	0.8575	1.7	2.04	2.2

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	2.701	3.06	No		

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Shapiro-Wilk Test Statistic	0.8515			
Shapiro-Wilk 5% Critical Value	0.941			

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.8046			
Shapiro-Wilk 5% Critical Value	0.942			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that

assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.7726
95% Non-Parametric (Chebyshev) UCL	1.014

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (1.014) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=42 data, AL is the action level or threshold (0.39),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=41 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
2.5567	1.6829	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test			
Test Statistic (S+) 95% Critical Value Null Hypothesis			
20	26	Cannot Reject	

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1			
X Coord Y C	Coord Label	Value	Type Historical
679149.492	3082933.098	J-13S	0.54 Manual
679279.683	3083075.429	J-14S	0.115 Manual
679261.098	3083016.351	J-15S	0.38 Manual
679222.634	3082840.172	J-16S	0.33 Manual
679293.56	3082950.498	J-17S	0.41 Manual
679360.57	3083026.498	J-18S	0.44 Manual
679343.581	3082969.598	J-19S	1.7 Manual
679382.864	3083009.113	J-20S	0.12 Manual
679335.002	3082941.172	J-21S	0.1 Manual
679252.713	3082781.029	J-22S	0.74 Manual
679297.001	3082840.697	J-23S	1.4 Manual
679394.807	3082971.83	J-24S	0.3 Manual
679146.646	3082549.764	J-25S	1 Manual
679224.585	3082683.14	J-26S	0.11 Manual
679169.076	3082537.351	J-20S J-27S	1 Manual
679272.004	3082652.675	J-27S J-28S	1.2 Manual
679329.438	3082711.096	J-29S	0.58 Manual
679374.442	3082711.090	J-29S J-30S	0.54 Manual
679410.149	3082845.846	J-30S J-31S	0.23 Manual
679453.476	3082914.115	J-32S	1.1 Manual
679495.884	3082940.973	J-33S	0.81 Manual
679304.653	3082548.688	J-34S	0.8 Manual
679342.741	3082605.319	J-35S	0.78 Manual
679382.89	3082667.527	J-36S	1.7 Manual
679433.945	3082731.682	J-37S	2.1 Manual
679470.357	3082776.735	J-38S	2.2 Manual
679497.331	3082840.396	J-39S	0.7 Manual
679524.331	3082886.899	J-40S	0.62 Manual
679560.607	3082897.258	J-41S	1.7 Manual
Area: Area 5			
X Coord Y C		Value	Type Historical
679133.429	3083306.313	J-01S	0.14 Manual
679104.245	3083223.262	J-02S	0.34 Manual
679155.074	3083294.696	J-03S	0.1 Manual
679171.297	3083289.796	J-04S	0.115 Manual
679225.856	3083359.974	J-05S	0.08 Manual
679164.806	3083214.71	J-06S	0.23 Manual
679242.726	3083326.528	J-07S	0.47 Manual
679181.275	3083178.288	J-08S	0.29 Manual
679213.773	3083224.973	J-09S	0.105 Manual
679280.544	3083305.681	J-10S	0.105 Manual
679268.77	3083200.326	J-11S	0.26 Manual
679301.16	3083254.034	J-12S	0.09 Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	45
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1										
X Coord	Y Coord	Label	Value	Туре	Historical						
679133.4290	3083306.3130	J-01S	0.51	Manual	Т						
679104.2450	3083223.2620	J-02S	0.18	Manual	Т						
679155.0740	3083294.6960	J-03S	0.23	Manual	Т						
679171.2970	3083289.7960	J-04S	0.23	Manual	Т						
679225.8560	3083359.9740	J-05S	0.29	Manual	Т						
679164.8060	3083214.7100	J-06S	0.24	Manual	Т						
679242.7260	3083326.5280	J-07S	2	Manual	Т						
679181.2750	3083178.2880	J-08S	0.83	Manual	Т						
679213.7730	3083224.9730	J-09S	1.2	Manual	Т						
679280.5440	3083305.6810	J-10S	0.31	Manual	Т						
679268.7700	3083200.3260	J-11S	2.6	Manual	Т						
679301.1600	3083254.0340	J-12S	0.57	Manual	Т						
679187.9026	3083236.6179	J-13S	0.22	Random							

Area: Area 3									
X Coord	Y Coord	Label	Value	Туре	Historical				

679149.4920	3082933.0980	J-13S	0.22	Manual	Т
679279.6830	3083075.4290	J-14S	0.66	Manual	Т
679261.0980	3083016.3510	J-15S	2.6	Manual	Т
679222.6340	3082840.1720	J-16S	0.72	Manual	Т
679293.5600	3082950.4980	J-17S	2	Manual	Т
679360.5700	3083026.4980	J-18S	0.58	Manual	Т
679343.5810	3082969.5980	J-19S	1.8	Manual	Т
679382.8640	3083009.1130	J-20S	0.86	Manual	Т
679335.0020	3082941.1720	J-21S	0.93	Manual	Т
679252.7130	3082781.0290	J-22S	1.035	Manual	Т
679297.0010	3082840.6970	J-23S	1.7	Manual	Т
679394.8070	3082971.8300	J-24S	0.35	Manual	Т
679146.6460	3082549.7640	J-25S	0.305	Manual	Т
679224.5850	3082683.1400	J-26S	0.27805	Manual	Т
679169.0760	3082537.3510	J-27S	0.53	Manual	Т
679272.0040	3082652.6750	J-28S	1.1	Manual	Т
679329.4380	3082711.0960	J-29S	1.3	Manual	Т
679374.4420	3082791.3300	J-30S	3.1	Manual	Т
679410.1490	3082845.8460	J-31S	1.6	Manual	Т
679453.4760	3082914.1150	J-32S	2.5	Manual	Т
679495.8840	3082940.9730	J-33S	1.4	Manual	Т
679304.6530	3082548.6880	J-34S	3	Manual	Т
679342.7410	3082605.3190	J-35S	2	Manual	Т
679382.8900	3082667.5270	J-36S	1.45	Manual	Т
679433.9450	3082731.6820	J-37S	2.2	Manual	Т
679470.3570	3082776.7350	J-38S	2.4	Manual	Т
679497.3310	3082840.3960	J-39S	1.5	Manual	Т
679524.3310	3082886.8990	J-40S	2.8	Manual	Т
679560.6070	3082897.2580	J-41S	1.3	Manual	Т
679532.9930	3082835.5820	J-42SD	2.5	Manual	Т
679552.9590	3082868.6600	J-43SD	7.2	Manual	Т
679223.3445	3082776.2867		0	Random	Т
			-		-

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-β) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples.

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	"	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples									
A1 _0.3		α=	5	α=	10	α=′	15		
AL=0.3	9	s=6	s=3	s=6	s=3	s=6	s=3		
	β=5	256148	64038	202696	50675	170162	42541		
LBGR=90	β=10	202696	50676	155492	38874	127174	31794		
	β=15	170163	42542	127174	31795	101700	25426		
	β=5	64038	16011	50675	12670	42541	10636		
LBGR=80	β=10	50676	12670	38874	9720	31794	7949		
	β=15	42542	10637	31795	7950	25426	6357		
LBGR=70	β=5	28463	7117	22523	5632	18908	4728		

β=10	22523	5632	17278	4321	14131	3534
β=15	18909	4729	14132	3534	11301	2826

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	21 Samples						
Field collection costs		\$100.00	\$2,100.00						
Analytical costs	\$400.00	\$400.00	\$8,400.00						
Sum of Field & Analytical costs		\$500.00	\$10,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$11,500.00						

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0	0.18	0.22	0.22	0.23	0.23	0.24	0.2781	0.29
10	0.305	0.31	0.35	0.51	0.53	0.57	0.58	0.66	0.72	0.83
20	0.86	0.93	1.035	1.1	1.2	1.3	1.3	1.4	1.45	1.5
30	1.6	1.7	1.8	2	2	2	2.2	2.4	2.5	2.5
40	2.6	2.6	2.8	3	3.1	7.2				

SUMMARY STATISTICS						
n	46					
Min	0					
Max	7.2					
Range	7.2					
Mean	1.3332					
Median	1.0675					
Variance	1.6103					
StdDev	1.269					
Std Error	0.1871					
Skewness	2.3208					
Interquartile Range	1.6913					

	Percentiles										
1%	1% 5% 10% 25% 50% 75% 90% 95% 99%										
0	0.063	0.22	0.3087	1.067	2	2.66	3.065	7.2			

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST									
k Test Statistic R _k 5% Critical Value C _k Significant										
	1	4.593	3.09	Yes						

The test statistic 4.593 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	7.2

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.9124				
Shapiro-Wilk 5% Critical Value	0.944				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic	0.805				
Shapiro-Wilk 5% Critical Value	0.945				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	1.647				
95% Non-Parametric (Chebyshev) UCL	2.149				

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (2.149) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SF}$$

where

x is the sample mean of the n=46 data,

AL is the action level or threshold (0.39),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=45 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic Critical Value t _{0.95} Null Hypothesis						
5.0412	1.6794	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+) 95% Critical Value Null Hypothe							
13	29	Cannot Reject					

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

```
Area: Area 1
X Coord Y Coord Label
                          Value
                                   Type
                                            Historical
                                   0.22 Manual
679149.492
             3082933.098 J-13S
                                   0.66 Manual
679279.683
             3083075.429 J-14S
679261.098
             3083016.351 J-15S
                                   2.6 Manual
679222.634
             3082840.172 J-16S
                                   0.72 Manual
679293.56
             3082950.498 J-17S
                                        Manual
679360.57
             3083026.498 J-18S
                                   0.58 Manual
679343.581
             3082969.598 J-19S
                                   1.8 Manual
             3083009.113 J-20S
679382.864
                                   0.86 Manual
679335.002
             3082941.172 J-21S
                                   0.93 Manual
679252.713
             3082781.029 J-22S
                                   1.035
                                            Manual
679297.001
             3082840.697 J-23S
                                   1.7 Manual
679394.807
             3082971.83
                          J-24S
                                   0.35 Manual
             3082549.764 J-25S
                                   0.305
679146.646
                                            Manual
679224.585
             3082683.14
                          J-26S
                                   0.27805 Manual
679169.076
             3082537.351 J-27S
                                   0.53 Manual
679272.004
             3082652.675 J-28S
                                   1.1 Manual
679329.438
             3082711.096 J-29S
                                   1.3
                                       Manual
679374.442
             3082791.33
                          J-30S
                                   3.1
                                       Manual
                                       Manual
679410.149
             3082845.846 J-31S
                                   1.6
679453.476
             3082914.115 J-32S
                                   2.5
                                       Manual
679495.884
             3082940.973 J-33S
                                   1.4
                                       Manual
679304.653
             3082548.688 J-34S
                                   3
                                        Manual
679342.741
             3082605.319 J-35S
                                   2
                                        Manual
679382.89
             3082667.527 J-36S
                                   1.45 Manual
679433.945
             3082731.682 J-37S
                                   2.2 Manual
679470.357
             3082776.735 J-38S
                                   2.4
                                       Manual
                                       Manual
679497.331
             3082840.396 J-39S
                                   1.5
679524.331
             3082886.899 J-40S
                                   2.8
                                      Manual
679560.607
             3082897.258 J-41S
                                   1.3
                                       Manual
679532.993
             3082835.582 J-42SD
                                   2.5
                                       Manual
679552.959
                          J-43SD
                                   7.2 Manual
             3082868.66
Area: Area 5
X Coord Y Coord Label
                          Value
                                   Type
                                            Historical
679133.429
             3083306.313 J-01S
                                   0.51 Manual
679104.245
             3083223.262 J-02S
                                   0.18 Manual
679155.074
             3083294.696 J-03S
                                   0.23 Manual
679171.297
             3083289.796 J-04S
                                   0.23 Manual
679225.856
             3083359.974
                         J-05S
                                   0.29 Manual
679164.806
             3083214.71
                          J-06S
                                   0.24 Manual
679242.726
             3083326.528 J-07S
                                        Manual
679181.275
             3083178.288 J-08S
                                   0.83 Manual
             3083224.973
679213.773
                         J-09S
                                   1.2 Manual
679280.544
             3083305.681 J-10S
                                   0.31 Manual
679268.77
             3083200.326 J-11S
                                   2.6 Manual
```

3083254.034 J-12S

0.57 Manual

679301.16

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	2
Number of samples on map ^a	23
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$2,000.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	X Coord Y Coord Label Value Type								
679133.4290	3083306.3130	TW01-01	0.000115	Manual	Т				
679104.2450	3083223.2620	TW01-02	0.00065	Manual	Т				
679242.7260	3083326.5280	TW01-07	0.0145	Manual	Т				
679181.2750	3083178.2880	TW01-08	0.000115	Manual	Т				
679268.7700	3083200.3260	TW01-11	0.003	Manual	Т				
679301.1600	3083254.0340	TW01-12	0.000115	Manual	Т				
679118.0448	3083264.3844	J-42SD	0.00023	Random					

Area: Area 3								
X Coord	Historical							
679532.9930	3082835.5820	J-42SD	0.00023	Manual	Т			
679552.9590	3082868.6600	J-43SD	0.00023	Manual	Т			
679149.4920	3082933.0980	TW01-13	0.000115	Manual	Т			
679279.7760	3083075.6320	TW01-14	0.000115	Manual	Т			
679293.5600	3082950.4980	TW01-17	0.00023	Manual	Т			
679360.5700	3083026.4980	TW01-18	0.0012	Manual	Т			

679169.0760	3082537.3510	TW01-27	0.00023	Manual	Т
679495.8840	3082940.9730	TW01-33	0.00023	Manual	Т
679304.6530	3082548.6880	TW01-34	0.00023	Manual	Т
679342.7410	3082605.3190	TW01-35	0.00023	Manual	Т
679382.8900	3082667.5270	TW01-36	0.00023	Manual	Т
679433.9450	3082731.6820	TW01-37	0.00023	Manual	Т
679470.3570	3082776.7350	TW01-38	0.00023	Manual	Т
679497.3310	3082840.3960	TW01-39	0.00023	Manual	Т
679524.3310	3082886.8990	TW01-40	0.00023	Manual	Т
679560.6110	3082897.2580	TW01-41	0.00023	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region.

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .


The values of these inputs that result in the calculated number of sampling locations are:

Anglista	_	Parameter						
	Analyte	"	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
		2	0.0030078	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

b This value is automatically calculated by VSP based upon the user defined value of β.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=0.00035		α=5		α=	α=10		α=15	
		s=0.0060156	s=0.0030078	s=0.0060156	s=0.0030078	s=0.0060156	s=0.0030078	
	β=5 319697 7992		79926	252984	63247	212378	53095	
LBGR=90	β=10	252984	63248	194069	48518	158725	39682	
	β=15	212379	53096	158725	39682	126931	31734	
	β=5	79926	19983	63247	15813	53095	13275	
LBGR=80	β=10	63248	15813	48518	12131	39682	9921	
	β=15	53096	13275	39682	9922	31734	7934	
	β=5	35524	8882	28111	7029	23599	5900	
LBGR=70	β=10	28111	7029	21564	5392	17637	4410	
	β=15	23599	5901	17637	4410	14104	3527	

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION							
Cost Details	Per Analysis	Per Sample	2 Samples				
Field collection costs		\$100.00	\$200.00				
Analytical costs	\$400.00	\$400.00	\$800.00				
Sum of Field & Analytical costs		\$500.00	\$1,000.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$2,000.00				

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.000115	0.000115	0.000115	0.000115	0.000115	0.00023	0.00023	0.00023	0.00023
10	0.00023	0.00023	0.00023	0.00023	0.00023	0.00023	0.00023	0.00023	0.00023	0.00023
20	0.00065	0.0012	0.003	0.0145						

SUMMARY STATISTICS

		24						
Min				0				
Max				0.0145				
Range				0.0145				
Mean				0.00096437				
Median				0.00023				
Variance				8.6782e-006				
StdDev				0.0029459				
Std Error				0.00060133				
Skewness				4.599				
	Interquartile Range				8.625e-005			
Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	2.875e-005	0.000115	0.0001438	0.00023	0.00023	0.0021	0.01163	0.0145

Outlier Test

Dixon's extreme value test was performed to test whether the lowest value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

DIXON'S OUTLIER TEST					
Dixon Test Statistic	0.095833				
Dixon 5% Critical Value	0.421				

The calculated test statistic does not exceed the critical value, so the test cannot reject the null hypothesis that there are no outliers in the data, and concludes that the minimum value 0 is not an outlier at the 5% significance level.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Dixon's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Shapiro-Wilk Test Statistic	0.3173					
Shapiro-Wilk 5% Critical Value	0.911					

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the minimum value 0, do not appear to follow a normal distribution at the 5% level of significance. Dixon's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The

sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution.

The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST						
Shapiro-Wilk Test Statistic	0.3078					
Shapiro-Wilk 5% Critical Value	0.916					

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.001995
95% Non-Parametric (Chebyshev) UCL	0.003585

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.003585) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=24 data,

AL is the action level or threshold (0.00035),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=23 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic Critical Value t _{0.95} Null Hypothesis						
1.0217	1.7139	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+) 95% Critical Value Null Hypothesis							
20	16	Reject					

Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1 X Coord Y Coord Label Value Type Historical 679532.993 3082835.582 J-42SD 0.00023 Manual 679552.959 3082868.66 J-43SD 0.00023 Manual 679149.492 3082933.098 TW01-130.000115 Manual 679279.776 3083075.632 TW01-140.000115 Manual 679293.56 3082950.498 TW01-170.00023 Manual 3083026.498 TW01-180.0012 679360.57 Manual 679169.076 3082537.351 TW01-270.00023 Manual 679495.884 3082940.973 TW01-330.00023 Manual 3082548.688 TW01-340.00023 Manual 679304.653 3082605.319 TW01-350.00023 Manual 679342.741 3082667.527 TW01-360.00023 Manual 679382.89 679433.945 3082731.682 TW01-370.00023 Manual 679470.357 3082776.735 TW01-380.00023 Manual 679497.331 3082840.396 TW01-390.00023 Manual 3082886.899 TW01-400.00023 Manual 679524.331 679560.611 3082897.258 TW01-410.00023 Manual

Area: Area 5

X Coord Y	Coord Label	Value	Type	Historical
679133.429	3083306.313	TW01-0	10.000115	Manual
679104.245	3083223.262	TW01-0	20.00065	Manual
679242.726	3083326.528	TW01-0	70.0145	Manual
679181.275	3083178.288	TW01-0	80.000115	Manual
679268.77	3083200.326	TW01-1	10.003	Manual
679301 16	3083254 034	TW01-1	20 000115	Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	3
Number of samples on map ^a	44
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$2,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1										
X Coord	Y Coord	Label	Value	Туре	Historical						
679133.4290	3083306.3130	J-01S	0.042	Manual	Т						
679104.2450	3083223.2620	J-02S	0.035	Manual	Т						
679155.0740	3083294.6960	J-03S	2.07	Manual	Т						
679171.2970	3083289.7960	J-04S	3.97	Manual	Т						
679225.8560	3083359.9740	J-05S	0.0395	Manual	Т						
679164.8060	3083214.7100	J-06S	0.037	Manual	Т						
679242.7260	3083326.5280	J-07S	0.37	Manual	Т						
679181.2750	3083178.2880	J-08S	0.0365	Manual	Т						
679213.7730	3083224.9730	J-09S	0.648	Manual	Т						
679280.5440	3083305.6810	J-10S	0.037	Manual	Т						
679268.7700	3083200.3260	J-11S	0.041	Manual	Т						
679301.1600	3083254.0340	J-12S	0.121	Manual	Т						

Area: Area 3							
X Coord Y Coord Label Value Type Historic							
679149.4920	3082933.0980	J-13S	0.037	Manual	Т		

679279.6830 3083075.4290 J-14S 0.142 Manual 679261.0980 3083016.3510 J-15S 0.038 Manual 679222.6340 3082840.1720 J-16S 0.038 Manual 679293.5600 3082950.4980 J-17S 0.0405 Manual 679360.5700 3083026.4980 J-18S 0.039 Manual 679343.5810 3082969.5980 J-19S 0.3975 Manual 679382.8640 3083009.1130 J-20S 0.355 Manual 679335.0020 3082941.1720 J-21S 0.39 Manual 679252.7130 3082781.0290 J-22S 0.0375 Manual	al T
679222.6340 3082840.1720 J-16S 0.038 Manual 679293.5600 3082950.4980 J-17S 0.0405 Manual 679360.5700 3083026.4980 J-18S 0.039 Manual 679343.5810 3082969.5980 J-19S 0.3975 Manual 679382.8640 3083009.1130 J-20S 0.355 Manual 679335.0020 3082941.1720 J-21S 0.39 Manual	al T
679293.5600 3082950.4980 J-17S 0.0405 Manual 679360.5700 3083026.4980 J-18S 0.039 Manual 679343.5810 3082969.5980 J-19S 0.3975 Manual 679382.8640 3083009.1130 J-20S 0.355 Manual 679335.0020 3082941.1720 J-21S 0.39 Manual	al T al T al T al T al T
679360.5700 3083026.4980 J-18S 0.039 Manual 679343.5810 3082969.5980 J-19S 0.3975 Manual 679382.8640 3083009.1130 J-20S 0.355 Manual 679335.0020 3082941.1720 J-21S 0.39 Manual	al T al T al T al T
679343.5810 3082969.5980 J-19S 0.3975 Manual 679382.8640 3083009.1130 J-20S 0.355 Manual 679335.0020 3082941.1720 J-21S 0.39 Manual	al T al T
679382.8640 3083009.1130 J-20S 0.355 Manua 679335.0020 3082941.1720 J-21S 0.39 Manua	al T
679335.0020 3082941.1720 J-21S 0.39 Manua	al T
670252 7130 3082781 0200 1 229 0 0275 Manua	٦ اد
013232.1130 3002101.0230 J-223 0.0313 Wallua	וג ו
679297.0010 3082840.6970 J-23S 0.036 Manua	al T
679394.8070 3082971.8300 J-24S 0.36 Manua	al T
679146.6460 3082549.7640 J-25S 0.04 Manua	al T
679224.5850 3082683.1400 J-26S 0.03775 Manua	al T
679169.0760 3082537.3510 J-27S 0.039 Manua	al T
679272.0040 3082652.6750 J-28S 0.04 Manua	al T
679329.4380 3082711.0960 J-29S 0.0375 Manua	al T
679374.4420 3082791.3300 J-30S 0.0425 Manua	al T
679410.1490 3082845.8460 J-31S 0.03875 Manua	al T
679453.4760 3082914.1150 J-32S 0.042 Manua	al T
679495.8840 3082940.9730 J-33S 0.037 Manua	al T
679304.6530 3082548.6880 J-34S 0.055 Manua	al T
679342.7410 3082605.3190 J-35S 0.0385 Manua	al T
679382.8900 3082667.5270 J-36S 0.04 Manua	al T
679433.9450 3082731.6820 J-37S 0.036 Manua	al T
679470.3570 3082776.7350 J-38S 0.036 Manua	al T
679497.3310 3082840.3960 J-39S 0.041 Manua	al T
679524.3310 3082886.8990 J-40S 0.038 Manua	al T
679560.6070 3082897.2580 J-41S 0.034 Manua	al T
679532.9930 3082835.5820 J-42SD 0.047 Manua	al T
679552.9590 3082868.6600 J-43SD 0.06 Manua	al T
679243.2941 3082775.8683 0 Rando	om

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Anglista	Paran				rame	eter	
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	3	0.66334	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples									
AL 0.4		α	=5	α=	10	α=15			
AL=0.	1	s=1.32668	s=0.66334	s=1.32668	s=0.66334	s=1.32668	s=0.66334		
	β=5	190481	47622	150732	37684	126538	31635		
LBGR=90	β=10	150732	37684	115630	28908	94571	23644		
	β=15	126539	31636	94571	23644	75628	18908		
	β=5	47622	11907	37684	9422	31635	7910		
LBGR=80	β=10	37684	9423	28908	7228	23644	5912		
	β=15	31636	7910	23644	5912	18908	4728		
LBGR=70	β=5	21166	5293	16749	4188	14061	3516		

β=10	16750	4189	12849	3213	10509	2628
β=15	14062	3517	10509	2628	8404	2102

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,500.00, which averages out to a per sample cost of \$833.33. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	3 Samples		
Field collection costs		\$100.00	\$300.00		
Analytical costs	\$400.00	\$400.00	\$1,200.00		
Sum of Field & Analytical costs		\$500.00	\$1,500.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$2,500.00		

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.034	0.035	0.036	0.036	0.036	0.0365	0.037	0.037	0.037
10	0.037	0.0375	0.0375	0.03775	0.038	0.038	0.038	0.0385	0.03875	0.039
20	0.039	0.0395	0.04	0.04	0.04	0.0405	0.041	0.041	0.042	0.042
30	0.0425	0.047	0.055	0.06	0.121	0.142	0.355	0.36	0.37	0.39
40	0.3975	0.648	2.07	3.97						

SUMMARY STATISTICS				
n 44				
Min	0			
Max	3.97			
Range	3.97			
Mean	0.2304			
Median	0.03975			
Variance	0.44002			
StdDev	0.66334			
Std Error	0.1			
Skewness	4.872			
Interquartile Range	0.021625			

	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.03425	0.036	0.03712	0.03975	0.05875	0.3938	1.714	3.97

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST						
k	Test Statistic R _k	5% Critical Value C _k	Significant?			
1	5.638	3.08	Yes			

The test statistic 5.638 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS					
1	3.97				

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION T	EST (excluding outliers)
Shapiro-Wilk Test Statistic	0.3823
Shapiro-Wilk 5% Critical Value	0.943

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.3421			
Shapiro-Wilk 5% Critical Value	0.944			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.3985
95% Non-Parametric (Chebyshev) UCL	0.6663

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.6663) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=44 data,

AL is the action level or threshold (0.1),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=43 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic	Critical Value t _{0.95}	Null Hypothesis			
1.304	1.6811	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+)	95% Critical Value	Null Hypothesis				
34	27	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1				
X Coord Y C	oord Label	Value	Type	Historical
679149.492	3082933.098	J-13S	0.037	Manual
679279.683	3083075.429	J-13S J-14S	0.037	Manual
679261.098	3083016.351	J-14S J-15S	0.142	Manual
679222.634	3082840.172	J-15S J-16S	0.038	Manual
679293.56	3082950.498	J-10S J-17S	0.038	Manual
679360.57	3083026.498	J-17S J-18S	0.0403	Manual
679343.581	3082969.598	J-10S J-19S	0.039	Manual
679382.864	3083009.113	J-19S J-20S	0.3575	Manual
679335.002	3082941.172	J-20S J-21S	0.333 0.39 Mar	
679252.713	3082941.172	J-21S J-22S		
			0.0375	Manual
679297.001	3082840.697	J-23S	0.036	Manual
679394.807	3082971.83	J-24S	0.36 Mar	
679146.646	3082549.764	J-25S	0.04 Mar	
679224.585	3082683.14	J-26S	0.03775	Manual
679169.076	3082537.351	J-27S	0.039	Manual
679272.004	3082652.675	J-28S	0.04 Mar	
679329.438	3082711.096	J-29S	0.0375	Manual
679374.442	3082791.33	J-30S	0.0425	Manual
679410.149	3082845.846	J-31S	0.03875	Manual
679453.476	3082914.115	J-32S	0.042	Manual
679495.884	3082940.973	J-33S	0.037	Manual
679304.653	3082548.688	J-34S	0.055	Manual
679342.741	3082605.319	J-35S	0.0385	Manual
679382.89	3082667.527	J-36S	0.04 Mar	
679433.945	3082731.682	J-37S	0.036	Manual
679470.357	3082776.735	J-38S	0.036	Manual
679497.331	3082840.396	J-39S	0.041	Manual
679524.331	3082886.899	J-40S	0.038	Manual
679560.607	3082897.258	J-41S	0.034	Manual
679532.993	3082835.582	J-42SD	0.047	Manual
679552.959	3082868.66	J-43SD	0.06 Mar	nual
Area: Area 5				
	Coord Label		Type	Historical
679133.429	3083306.313		0.042	Manual
679104.245	3083223.262	J-02S	0.035	Manual
679155.074	3083294.696	J-03S	2.07 Mar	
679171.297	3083289.796		3.97 Mar	
679225.856	3083359.974	J-05S	0.0395	Manual
679164.806	3083214.71	J-06S	0.037	Manual
679242.726	3083326.528	J-07S	0.37 Mar	
679181.275	3083178.288	J-08S	0.0365	Manual
679213.773	3083224.973	J-09S	0.648	Manual
679280.544	3083305.681	J-10S	0.037	Manual
679268.77	3083200.326		0.041	Manual
679301.16	3083254.034	J-12S	0.121	Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	44
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1								
X Coord	Historical								
679133.4290	3083306.3130	J-01S	0.037	Manual	Т				
679104.2450	3083223.2620	J-02S	0.031	Manual	Т				
679155.0740	3083294.6960	J-03S	0.1025	Manual	Т				
679171.2970	3083289.7960	J-04S	0.766	Manual	Т				
679225.8560	3083359.9740	J-05S	0.035	Manual	Т				
679164.8060	3083214.7100	J-06S	0.03275	Manual	Т				
679242.7260	3083326.5280	J-07S	0.325	Manual	Т				
679181.2750	3083178.2880	J-08S	0.032	Manual	Т				
679213.7730	3083224.9730	J-09S	0.775	Manual	Т				
679280.5440	3083305.6810	J-10S	0.0325	Manual	Т				
679268.7700	3083200.3260	J-11S	0.036	Manual	Т				
679301.1600	3083254.0340	J-12S	0.172	Manual	Т				
679160.0527	3083210.1074	J-13S	0.0325	Random					

Area: Area 3							
X Coord	Y Coord	Label	Value	Туре	Historical		

679149.4920 3082933.0980 J-13S 0.0325 Manual T 679279.6830 3083075.4290 J-14S 0.0985 Manual T 679261.0980 3083016.3510 J-15S 0.0335 Manual T 679223.5600 3082950.4980 J-17S 0.0355 Manual T 679360.5700 3083026.4980 J-18S 0.034 Manual T 679343.5810 3082969.5980 J-19S 0.3475 Manual T 679335.0020 3082941.1720 J-21S 0.34 Manual T 679352.7130 3082871.0290 J-22S 0.0315 Manual T 679297.0010 3082840.6970 J-23S 0.0315 Manual T 679346.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082652.6750 J-28S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.0345 Manual T 679379.44420						
679261.0980 3083016.3510 J-15S 0.033 Manual T 679222.6340 3082840.1720 J-16S 0.0335 Manual T 679293.5600 3082950.4980 J-17S 0.0355 Manual T 679360.5700 3083026.4980 J-18S 0.034 Manual T 679343.5810 3082969.5980 J-19S 0.3475 Manual T 679382.8640 3083009.1130 J-20S 0.31 Manual T 679335.0020 3082941.1720 J-21S 0.34 Manual T 679297.0010 3082840.6970 J-22S 0.03275 Manual T 679394.8070 3082840.6970 J-23S 0.0315 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679453.4760 <td>679149.4920</td> <td>3082933.0980</td> <td>J-13S</td> <td>0.0325</td> <td>Manual</td> <td>Т</td>	679149.4920	3082933.0980	J-13S	0.0325	Manual	Т
679222.6340 3082840.1720 J-16S 0.0335 Manual T 679293.5600 3082950.4980 J-17S 0.0355 Manual T 679360.5700 3083026.4980 J-18S 0.034 Manual T 679343.5810 3082969.5980 J-19S 0.3475 Manual T 679382.8640 3083009.1130 J-20S 0.31 Manual T 679335.0020 3082941.1720 J-21S 0.34 Manual T 679252.7130 3082781.0290 J-22S 0.03275 Manual T 679297.0010 3082840.6970 J-23S 0.0315 Manual T 679394.8070 3082971.8300 J-24S 0.315 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082683.1400 J-26S 0.0345 Manual T 679329.4380 3082711.0960 J-29S 0.035 Manual T 679470.1490 <td>679279.6830</td> <td>3083075.4290</td> <td>J-14S</td> <td>0.0985</td> <td>Manual</td> <td>Т</td>	679279.6830	3083075.4290	J-14S	0.0985	Manual	Т
679293.5600 3082950.4980 J-17S 0.0355 Manual T 679360.5700 3083026.4980 J-18S 0.034 Manual T 679343.5810 3082969.5980 J-19S 0.3475 Manual T 679382.8640 3083009.1130 J-20S 0.31 Manual T 679335.0020 3082941.1720 J-21S 0.34 Manual T 679252.7130 3082781.0290 J-22S 0.03275 Manual T 679297.0010 3082840.6970 J-23S 0.0315 Manual T 679394.8070 3082549.7640 J-25S 0.035 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679349.4380 3082711.0960 J-29S 0.033 Manual T 679453.4760 <td>679261.0980</td> <td>3083016.3510</td> <td>J-15S</td> <td>0.033</td> <td>Manual</td> <td>Т</td>	679261.0980	3083016.3510	J-15S	0.033	Manual	Т
679360.5700 3083026.4980 J-18S 0.034 Manual T 679343.5810 3082969.5980 J-19S 0.3475 Manual T 679382.8640 3083009.1130 J-20S 0.31 Manual T 679335.0020 3082941.1720 J-21S 0.34 Manual T 679252.7130 3082781.0290 J-22S 0.03275 Manual T 679297.0010 3082840.6970 J-23S 0.0315 Manual T 679394.8070 3082971.8300 J-24S 0.315 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679410.1490 3082845.8460 J-31S 0.0375 Manual T 679453.4760 <td>679222.6340</td> <td>3082840.1720</td> <td>J-16S</td> <td>0.0335</td> <td>Manual</td> <td>Т</td>	679222.6340	3082840.1720	J-16S	0.0335	Manual	Т
679343.5810 3082969.5980 J-19S 0.3475 Manual T 679382.8640 3083009.1130 J-20S 0.31 Manual T 679335.0020 3082941.1720 J-21S 0.03275 Manual T 679252.7130 3082840.6970 J-22S 0.0315 Manual T 679297.0010 3082840.6970 J-23S 0.0315 Manual T 679394.8070 3082971.8300 J-24S 0.315 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679453.4760 3082945.8460 J-31S 0.0375 Manual T 679495.8840 3082940.9730 J-32S 0.037 Manual T 679342.7410<	679293.5600	3082950.4980	J-17S	0.0355	Manual	Т
679382.8640 3083009.1130 J-20S 0.31 Manual T 679335.0020 3082941.1720 J-21S 0.34 Manual T 679252.7130 3082781.0290 J-22S 0.03275 Manual T 679297.0010 3082840.6970 J-23S 0.0315 Manual T 679394.8070 3082971.8300 J-24S 0.315 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679374.4420 3082711.0960 J-29S 0.033 Manual T 679410.1490 3082845.8460 J-31S 0.0375 Manual T 679495.8840 3082941.1150 J-32S 0.037 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679342.7410 <td>679360.5700</td> <td>3083026.4980</td> <td>J-18S</td> <td>0.034</td> <td>Manual</td> <td>Т</td>	679360.5700	3083026.4980	J-18S	0.034	Manual	Т
679335.0020 3082941.1720 J-21S 0.34 Manual T 679252.7130 3082781.0290 J-22S 0.03275 Manual T 679297.0010 3082840.6970 J-23S 0.0315 Manual T 679394.8070 3082971.8300 J-24S 0.315 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679224.5850 3082683.1400 J-26S 0.0345 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082871.3300 J-30S 0.0375 Manual T 679453.4760 3082914.1150 J-31S 0.0375 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679382.8900<	679343.5810	3082969.5980	J-19S	0.3475	Manual	Т
679252.7130 3082781.0290 J-22S 0.03275 Manual T 679297.0010 3082840.6970 J-23S 0.0315 Manual T 679394.8070 3082971.8300 J-24S 0.315 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679224.5850 3082683.1400 J-26S 0.0345 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679453.4760 3082845.8460 J-31S 0.0375 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679342.7410 3082667.5270 J-36S 0.035 Manual T 679433.9450	679382.8640	3083009.1130	J-20S	0.31	Manual	Т
679297.0010 3082840.6970 J-23S 0.0315 Manual T 679394.8070 3082971.8300 J-24S 0.315 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679224.5850 3082683.1400 J-26S 0.03325 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679410.1490 3082845.8460 J-31S 0.0375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679342.7410 3082667.5270 J-36S 0.035 Manual T 679433.9450<	679335.0020	3082941.1720	J-21S	0.34	Manual	Т
679394.8070 3082971.8300 J-24S 0.315 Manual T 679146.6460 3082549.7640 J-25S 0.035 Manual T 679224.5850 3082683.1400 J-26S 0.03325 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679410.1490 3082845.8460 J-31S 0.0375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679470.3570<	679252.7130	3082781.0290	J-22S	0.03275	Manual	Т
679146.6460 3082549.7640 J-25S 0.035 Manual T 679224.5850 3082683.1400 J-26S 0.03325 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679410.1490 3082845.8460 J-31S 0.0375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679470.3570 3082731.6820 J-37S 0.0315 Manual T 679497.3310	679297.0010	3082840.6970	J-23S	0.0315	Manual	Т
679224.5850 3082683.1400 J-26S 0.03325 Manual T 679169.0760 3082537.3510 J-27S 0.0345 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679433.9450 3082731.6820 J-37S 0.0315 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679524.33	679394.8070	3082971.8300	J-24S	0.315	Manual	Т
679169.0760 3082537.3510 J-27S 0.0345 Manual T 679272.0040 3082652.6750 J-28S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679342.7410 3082605.3190 J-35S 0.035 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T 679524.3310 3082840.3960 J-39S 0.036 Manual T 679560.6070<	679146.6460	3082549.7640	J-25S	0.035	Manual	Т
679272.0040 3082652.6750 J-28S 0.035 Manual T 679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679470.3570 3082731.6820 J-37S 0.0315 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679532.9930	679224.5850	3082683.1400	J-26S	0.03325	Manual	Т
679329.4380 3082711.0960 J-29S 0.033 Manual T 679374.4420 3082791.3300 J-30S 0.0375 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679433.9450 3082731.6820 J-37S 0.0315 Manual T 679470.3570 308276.7350 J-38S 0.0315 Manual T 6795924.3310 3082840.3960 J-39S 0.036 Manual T 679560.6070 3082887.2580 J-40S 0.0335 Manual T 679532.993	679169.0760	3082537.3510	J-27S	0.0345	Manual	Т
679374.4420 3082791.3300 J-30S 0.0375 Manual T 679410.1490 3082845.8460 J-31S 0.03375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679433.9450 3082731.6820 J-37S 0.0315 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679272.0040	3082652.6750	J-28S	0.035	Manual	Т
679410.1490 3082845.8460 J-31S 0.03375 Manual T 679453.4760 3082914.1150 J-32S 0.037 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679433.9450 3082731.6820 J-37S 0.0315 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679329.4380	3082711.0960	J-29S	0.033	Manual	Т
679453.4760 3082914.1150 J-32S 0.037 Manual T 679495.8840 3082940.9730 J-33S 0.0325 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679433.9450 3082731.6820 J-37S 0.0315 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679374.4420	3082791.3300	J-30S	0.0375	Manual	Т
679495.8840 3082940.9730 J-33S 0.0325 Manual T 679304.6530 3082548.6880 J-34S 0.0485 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679433.9450 3082731.6820 J-37S 0.0315 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679410.1490	3082845.8460	J-31S	0.03375	Manual	Т
679304.6530 3082548.6880 J-34S 0.0485 Manual T 679342.7410 3082605.3190 J-35S 0.0335 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679433.9450 3082731.6820 J-37S 0.0315 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679453.4760	3082914.1150	J-32S	0.037	Manual	Т
679342.7410 3082605.3190 J-35S 0.0335 Manual T 679382.8900 3082667.5270 J-36S 0.035 Manual T 679433.9450 3082731.6820 J-37S 0.0315 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679495.8840	3082940.9730	J-33S	0.0325	Manual	Т
679382.8900 3082667.5270 J-36S 0.035 Manual T 679433.9450 3082731.6820 J-37S 0.0315 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679304.6530	3082548.6880	J-34S	0.0485	Manual	Т
679433.9450 3082731.6820 J-37S 0.0315 Manual T 679470.3570 3082776.7350 J-38S 0.0315 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679342.7410	3082605.3190	J-35S	0.0335	Manual	Т
679470.3570 3082776.7350 J-38S 0.0315 Manual T 679497.3310 3082840.3960 J-39S 0.036 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679382.8900	3082667.5270	J-36S	0.035	Manual	Т
679497.3310 3082840.3960 J-39S 0.036 Manual T 679524.3310 3082886.8990 J-40S 0.0335 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679433.9450	3082731.6820	J-37S	0.0315	Manual	Т
679524.3310 3082886.8990 J-40S 0.0335 Manual T 679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679470.3570	3082776.7350	J-38S	0.0315	Manual	Т
679560.6070 3082897.2580 J-41S 0.03 Manual T 679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679497.3310	3082840.3960	J-39S	0.036	Manual	Т
679532.9930 3082835.5820 J-42SD 0.0415 Manual T	679524.3310	3082886.8990	J-40S	0.0335	Manual	Т
0.000=10000 000=000100=0 0.1=0 0.1=0 1.1=0	679560.6070	3082897.2580	J-41S	0.03	Manual	Т
679552.9590 3082868.6600 J-43SD 0.05 Manual T	679532.9930	3082835.5820	J-42SD	0.0415	Manual	Т
	679552.9590	3082868.6600	J-43SD	0.05	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
A1 0.4		α=	:5	α=	10	α='	15
AL=0.1	10	s=6	s=3	s=6	s=3	s=6	s=3
	β=5	1731550	432889	1370217	342555	1150289	287573
LBGR=90	β=10	1370217	342556	1051121	262781	859690	214923
	β=15	1150290	287574	859690	214923	687485	171872
	β=5	432889	108224	342555	85640	287573	71894
LBGR=80	β=10	342556	85640	262781	65696	214923	53732
	β=15	287574	71895	214923	53732	171872	42969
LBGR=70	β=5	192396	48100	152247	38063	127811	31953

β=10	152248	38063	116792	29199	95522	23881
β=15	127812	31954	95522	23882	76388	19098

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details Per Analysis Per Sample 21								
Field collection costs		\$100.00	\$2,100.00					
Analytical costs	\$400.00	\$400.00	\$8,400.00					
Sum of Field & Analytical costs		\$500.00	\$10,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$11,500.00					

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.03	0.031	0.0315	0.0315	0.0315	0.032	0.0325	0.0325	0.0325
10	0.0325	0.03275	0.03275	0.033	0.033	0.03325	0.0335	0.0335	0.0335	0.03375
20	0.034	0.0345	0.035	0.035	0.035	0.035	0.0355	0.036	0.036	0.037
30	0.037	0.0375	0.0415	0.0485	0.05	0.0985	0.1025	0.172	0.31	0.315
40	0.325	0.34	0.3475	0.766	0.775					

SUMMARY STATISTICS					
n	45				
Min	0				
Max	0.775				
Range	0.775				
Mean	0.10523				
Median	0.035				
Variance	0.029954				
StdDev	0.17307				
Std Error	0.0258				
Skewness 2.898					
Interquartile Range	0.016625				

	Percentiles							
1% 5% 10% 25% 50					75%	90%	95%	99%
0	0.0303	0.0315	0.03263	0.035	0.04925	0.331	0.6405	0.775

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST							
k	Test Statistic R _k	5% Critical Value C _k	Significant?				
1	3.824	3.08	Yes				

The test statistic 3.824 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS				
1	0.775			

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION T	EST (excluding outliers)
Shapiro-Wilk Test Statistic	0.5126
Shapiro-Wilk 5% Critical Value	0.943

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic 0.5075				
Shapiro-Wilk 5% Critical Value	0.945			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.1486
95% Non-Parametric (Chebyshev) UCL	0.2177

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.2177) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=45 data,

AL is the action level or threshold (0.15),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=44 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
-1.7351	1.6802	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+)	95% Critical Value	Null Hypothesis				
37	28	Reject				

This report was automatically produced * by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1				
X Coord Y C	Coord Label	Value	Type	Historical
679149.492	3082933.098	J-13S	0.0325	Manual
679279.683	3083075.429	J-13S J-14S	0.0323	Manual
679261.098	3083016.351	J-14S J-15S	0.033	Manual
679222.634	3082840.172	J-15S J-16S	0.033	Manual
679293.56	3082950.498	J-10S J-17S	0.0355	Manual
679360.57	3083026.498	J-17S J-18S	0.0333	Manual
679343.581	3082969.598	J-10S J-19S	0.034	Manual
679382.864	3083009.113	J-19S J-20S	0.3473 0.31 Mar	
679335.002	3082941.172	J-20S J-21S	0.31 Mai	
679252.713	3082941.172	J-21S J-22S	0.34 Mai 0.03275	Manual
679297.001	3082840.697	J-23S	0.0315	Manual
679394.807	3082971.83	J-24S	0.315	Manual
679146.646	3082549.764	J-25S	0.035	Manual
679224.585	3082683.14	J-26S	0.03325	Manual
679169.076	3082537.351	J-27S	0.0345	Manual
679272.004	3082652.675	J-28S	0.035	Manual
679329.438	3082711.096	J-29S	0.033	Manual
679374.442	3082791.33	J-30S	0.0375	Manual
679410.149	3082845.846	J-31S	0.03375	Manual
679453.476	3082914.115	J-32S	0.037	Manual
679495.884	3082940.973	J-33S	0.0325	Manual
679304.653	3082548.688	J-34S	0.0485	Manual
679342.741	3082605.319	J-35S	0.0335	Manual
679382.89	3082667.527	J-36S	0.035	Manual
679433.945	3082731.682	J-37S	0.0315	Manual
679470.357	3082776.735	J-38S	0.0315	Manual
679497.331	3082840.396	J-39S	0.036	Manual
679524.331	3082886.899	J-40S	0.0335	Manual
679560.607	3082897.258	J-41S	0.03 Mar	
679532.993	3082835.582	J-42SD	0.0415	Manual
679552.959	3082868.66	J-43SD	0.05 Mar	nual
Area: Area 5				
X Coord Y C		Value	Type	Historical
679133.429	3083306.313	J-01S	0.037	Manual
679104.245	3083223.262	J-02S	0.031	Manual
679155.074	3083294.696	J-03S	0.1025	Manual
679171.297	3083289.796	J-04S	0.766	Manual
679225.856	3083359.974	J-05S	0.035	Manual
679164.806	3083214.71	J-06S	0.03275	Manual
679242.726	3083326.528	J-07S	0.325	Manual
679181.275	3083178.288	J-08S	0.032	Manual
679213.773	3083224.973	J-09S	0.775	Manual
679280.544	3083305.681	J-10S	0.0325	Manual
679268.77	3083200.326	J-11S	0.036	Manual
679301.16	3083254.034	J-12S	0.172	Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold				
Type of Sampling Design	Parametric				
Sample Placement (Location) in the Field	Simple random sampling				
Working (Null) Hypothesis	The mean value at the site exceeds the threshold				
Formula for calculating number of sampling locations	Student's t-test				
Calculated total number of samples	21				
Number of samples on map ^a	44				
Number of selected sample areas b	2				
Specified sampling area ^c	188054.34 m ²				
Total cost of sampling d	\$11,500.00				

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1								
X Coord	Y Coord	Label	Value	Туре	Historical			
679133.4290	3083306.3130	J-01S	0.048	Manual	Т			
679104.2450	3083223.2620	J-02S	0.04	Manual	Т			
679155.0740	3083294.6960	J-03S	0.135	Manual	Т			
679171.2970	3083289.7960	J-04S	0.465	Manual	Т			
679225.8560	3083359.9740	J-05S	0.045	Manual	Т			
679164.8060	3083214.7100	J-06S	0.04225	Manual	Т			
679242.7260	3083326.5280	J-07S	0.42	Manual	Т			
679181.2750	3083178.2880	J-08S	0.0415	Manual	Т			
679213.7730	3083224.9730	J-09S	1.03	Manual	Т			
679280.5440	3083305.6810	J-10S	0.042	Manual	Т			
679268.7700	3083200.3260	J-11S	0.0465	Manual	Т			
679301.1600	3083254.0340	J-12S	0.218	Manual	Т			

Area: Area 3						
X Coord	Y Coord	Label	Value	Туре	Historical	
679149.4920	3082933.0980	J-13S	0.042	Manual	Т	

679279.6830 3083075.4290 J-14S 0.181 Manual T 679261.0980 3083016.3510 J-15S 0.043 Manual T 679222.6340 3082840.1720 J-16S 0.0435 Manual T 679293.5600 3082950.4980 J-17S 0.046 Manual T 679360.5700 3083026.4980 J-18S 0.044 Manual T 679343.5810 3082969.5980 J-19S 0.45 Manual T 679382.8640 3083009.1130 J-20S 0.405 Manual T 679385.0020 3082941.1720 J-21S 0.44 Manual T 679297.0010 3082840.6970 J-22S 0.0425 Manual T 679146.6460 3082549.7640 J-25S 0.04275 Manual T 679169.0760 3082537.3510 J-27S 0.0445 Manual T 679329.4380 3082711.0960 J-29S 0.0425 Manual T 679329.4380
679222.6340 3082840.1720 J-16S 0.0435 Manual T 679293.5600 3082950.4980 J-17S 0.046 Manual T 679360.5700 3083026.4980 J-18S 0.044 Manual T 679343.5810 3082969.5980 J-19S 0.45 Manual T 679382.8640 3083009.1130 J-20S 0.405 Manual T 679355.0020 3082941.1720 J-21S 0.44 Manual T 679252.7130 3082781.0290 J-22S 0.0425 Manual T 679297.0010 3082840.6970 J-23S 0.041 Manual T 679394.8070 3082971.8300 J-24S 0.041 Manual T 679146.6460 3082549.7640 J-25S 0.0455 Manual T 679272.0040 3082652.6750 J-28S 0.045 Manual T 679374.4420 308271.3300 J-27S 0.045 Manual T 679374.4420 3082791.3300 J-30S 0.045 Manual T 679453.4760 3082941.1150 J-29S 0.0425 Manual T 679453.4760 3082941.1150 J-32S 0.048 Manual T 679304.6530 3082685.3190 J-33S 0.042 Manual T 679342.7410 3082605.3190 J-35S 0.045 Manual T 679382.8900 3082657.5270 J-36S 0.0455 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679342.7410 3082605.3190 J-35S 0.045 Manual T 679433.9450 308271.6820 J-37S 0.0445 Manual T 679470.3570 3082776.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.045 Manual T 679497.3310 3082840.3960 J-39S 0.0445 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679560.6070 3082877.2580 J-41S 0.0385 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679293.5600 3082950.4980 J-17S
679360.5700 3083026.4980 J-18S 0.044 Manual T 679343.5810 3082969.5980 J-19S 0.45 Manual T 679382.8640 3083009.1130 J-20S 0.405 Manual T 679335.0020 3082941.1720 J-21S 0.44 Manual T 679252.7130 3082781.0290 J-22S 0.0425 Manual T 679297.0010 3082840.6970 J-23S 0.041 Manual T 679394.8070 3082971.8300 J-24S 0.41 Manual T 679146.6460 3082549.7640 J-25S 0.04525 Manual T 679169.0760 3082537.3510 J-27S 0.0445 Manual T 679329.4380 3082711.0960 J-29S 0.0425 Manual T 679329.4380 3082791.3300 J-30S 0.0485 Manual T 679340.4420 3082845.8460 J-31S 0.0435 Manual T 679453.4760
679343.5810 3082969.5980 J-19S
679382.8640 3083009.1130 J-20S 0.405 Manual 7679335.0020 3082941.1720 J-21S 0.44 Manual 7679252.7130 3082781.0290 J-22S 0.0425 Manual 7679297.0010 3082840.6970 J-23S 0.041 Manual 7679394.8070 3082971.8300 J-24S 0.41 Manual 7679146.6460 3082549.7640 J-25S 0.04525 Manual 7679146.6460 3082549.7640 J-25S 0.04525 Manual 7679169.0760 3082537.3510 J-27S 0.0445 Manual 7679169.0760 3082537.3510 J-27S 0.0445 Manual 7679272.0040 3082652.6750 J-28S 0.045 Manual 7679329.4380 3082711.0960 J-29S 0.0425 Manual 7679374.4420 3082791.3300 J-30S 0.0485 Manual 7679470.1490 3082845.8460 J-31S 0.04375 Manual 7679453.4760 3082914.1150 J-32S 0.048 Manual 7679495.8840 3082940.9730 J-33S 0.042 Manual 7679304.6530 3082548.6880 J-34S 0.065 Manual 7679342.7410 3082605.3190 J-35S 0.0435 Manual 7679382.8900 3082667.5270 J-36S 0.0455 Manual 7679470.3570 3082776.7350 J-38S 0.041 Manual 7679477.3370 3082776.7350 J-38S 0.044 Manual 7679497.3310 3082886.8990 J-40S 0.0435 Manual 7679560.6070 3082897.2580 J-41S 0.0385 Manual 7679560.6070 3082897.2580 J-41S
679335.0020 3082941.1720 J-21S
679252.7130 3082781.0290 J-22S
679297.0010 3082840.6970 J-23S 0.041 Manual T 679394.8070 3082971.8300 J-24S 0.41 Manual T 679146.6460 3082549.7640 J-25S 0.04525 Manual T 679224.5850 3082683.1400 J-26S 0.04275 Manual T 679169.0760 3082537.3510 J-27S 0.0445 Manual T 679272.0040 3082652.6750 J-28S 0.045 Manual T 679329.4380 3082711.0960 J-29S 0.0425 Manual T 679374.4420 3082791.3300 J-30S 0.0485 Manual T 679453.4760 3082914.1150 J-31S 0.04375 Manual T 679495.8840 3082914.1150 J-32S 0.048 Manual T 679392.8900 3082548.6880 J-34S 0.065 Manual T 679342.7410 3082667.5270 J-36S 0.0455 Manual T 679433.945
679394.8070 3082971.8300 J-24S 0.41 Manual T 679146.6460 3082549.7640 J-25S 0.04525 Manual T 679224.5850 3082683.1400 J-26S 0.04275 Manual T 679169.0760 3082537.3510 J-27S 0.0445 Manual T 679272.0040 3082652.6750 J-28S 0.045 Manual T 679329.4380 3082711.0960 J-29S 0.0425 Manual T 679374.4420 3082791.3300 J-30S 0.0485 Manual T 679410.1490 3082845.8460 J-31S 0.04375 Manual T 679453.4760 3082914.1150 J-32S 0.048 Manual T 679495.8840 3082940.9730 J-33S 0.042 Manual T 679304.6530 3082548.6880 J-34S 0.065 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679470.357
679146.6460 3082549.7640 J-25S 0.04525 Manual T 679224.5850 3082683.1400 J-26S 0.04275 Manual T 679169.0760 3082537.3510 J-27S 0.0445 Manual T 679272.0040 3082652.6750 J-28S 0.045 Manual T 679329.4380 3082711.0960 J-29S 0.0425 Manual T 679374.4420 3082791.3300 J-30S 0.0485 Manual T 679410.1490 3082845.8460 J-31S 0.04375 Manual T 679453.4760 3082914.1150 J-32S 0.048 Manual T 679495.8840 3082940.9730 J-33S 0.042 Manual T 679304.6530 3082548.6880 J-34S 0.065 Manual T 679342.7410 3082605.3190 J-35S 0.0435 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679433.9450 3082731.6820 J-37S 0.041 Manual T 679470.3570 308276.7350 J-38S 0.041 Manual T 679497.3310 3082886.8990 J-39S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679224.5850 3082683.1400 J-26S 0.04275 Manual T 679169.0760 3082537.3510 J-27S 0.0445 Manual T 679272.0040 3082652.6750 J-28S 0.045 Manual T 679329.4380 3082711.0960 J-29S 0.0425 Manual T 679374.4420 3082791.3300 J-30S 0.0485 Manual T 679410.1490 3082845.8460 J-31S 0.04375 Manual T 679453.4760 3082914.1150 J-32S 0.048 Manual T 679495.8840 3082940.9730 J-33S 0.042 Manual T 679304.6530 3082548.6880 J-34S 0.065 Manual T 679382.8900 3082605.3190 J-35S 0.0435 Manual T 679470.3570 308276.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310
679169.0760 3082537.3510 J-27S 0.0445 Manual T 679272.0040 3082652.6750 J-28S 0.045 Manual T 679329.4380 3082711.0960 J-29S 0.0425 Manual T 679374.4420 3082791.3300 J-30S 0.0485 Manual T 679410.1490 3082845.8460 J-31S 0.04375 Manual T 679453.4760 3082914.1150 J-32S 0.048 Manual T 679495.8840 3082940.9730 J-33S 0.042 Manual T 679304.6530 3082548.6880 J-34S 0.065 Manual T 679342.7410 3082605.3190 J-35S 0.0435 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679470.3570 3082776.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310
679272.0040 3082652.6750 J-28S 0.045 Manual T 679329.4380 3082711.0960 J-29S 0.0425 Manual T 679374.4420 3082791.3300 J-30S 0.0485 Manual T 679410.1490 3082845.8460 J-31S 0.04375 Manual T 679453.4760 3082914.1150 J-32S 0.048 Manual T 679495.8840 3082940.9730 J-33S 0.042 Manual T 679304.6530 3082548.6880 J-34S 0.065 Manual T 679342.7410 3082605.3190 J-35S 0.0435 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679470.3570 3082776.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070<
679329.4380 3082711.0960 J-29S 0.0425 Manual T 679374.4420 3082791.3300 J-30S 0.0485 Manual T 679410.1490 3082845.8460 J-31S 0.04375 Manual T 679453.4760 3082914.1150 J-32S 0.048 Manual T 679495.8840 3082940.9730 J-33S 0.042 Manual T 679304.6530 3082548.6880 J-34S 0.065 Manual T 679342.7410 3082605.3190 J-35S 0.0435 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679433.9450 3082731.6820 J-37S 0.041 Manual T 679470.3570 3082776.7350 J-38S 0.041 Manual T 679524.3310 3082840.3960 J-39S 0.0465 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679374.4420 3082791.3300 J-30S 0.0485 Manual T 679410.1490 3082845.8460 J-31S 0.04375 Manual T 679453.4760 3082914.1150 J-32S 0.048 Manual T 679495.8840 3082940.9730 J-33S 0.042 Manual T 679304.6530 3082548.6880 J-34S 0.065 Manual T 679342.7410 3082605.3190 J-35S 0.0435 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679433.9450 3082731.6820 J-37S 0.041 Manual T 679497.3310 3082840.3960 J-38S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679410.1490 3082845.8460 J-31S 0.04375 Manual T 679453.4760 3082914.1150 J-32S 0.048 Manual T 679495.8840 3082940.9730 J-33S 0.042 Manual T 679304.6530 3082548.6880 J-34S 0.065 Manual T 679342.7410 3082605.3190 J-35S 0.0435 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679470.3570 3082731.6820 J-37S 0.041 Manual T 679470.3570 3082776.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679453.4760 3082914.1150 J-32S 0.048 Manual T 679495.8840 3082940.9730 J-33S 0.042 Manual T 679304.6530 3082548.6880 J-34S 0.065 Manual T 679342.7410 3082605.3190 J-35S 0.0435 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679433.9450 3082731.6820 J-37S 0.041 Manual T 679470.3570 3082776.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679495.8840 3082940.9730 J-33S 0.042 Manual T 679304.6530 3082548.6880 J-34S 0.065 Manual T 679342.7410 3082605.3190 J-35S 0.0435 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679433.9450 3082731.6820 J-37S 0.041 Manual T 679470.3570 3082776.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679304.6530 3082548.6880 J-34S 0.065 Manual T 679342.7410 3082605.3190 J-35S 0.0435 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679433.9450 3082731.6820 J-37S 0.041 Manual T 679470.3570 3082776.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679342.7410 3082605.3190 J-35S 0.0435 Manual T 679382.8900 3082667.5270 J-36S 0.0455 Manual T 679433.9450 3082731.6820 J-37S 0.041 Manual T 679470.3570 3082776.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679382.8900 3082667.5270 J-36S 0.0455 Manual T 679433.9450 3082731.6820 J-37S 0.041 Manual T 679470.3570 3082776.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679433.9450 3082731.6820 J-37S 0.041 Manual T 679470.3570 3082776.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679470.3570 3082776.7350 J-38S 0.041 Manual T 679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679497.3310 3082840.3960 J-39S 0.0465 Manual T 679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679524.3310 3082886.8990 J-40S 0.043 Manual T 679560.6070 3082897.2580 J-41S 0.0385 Manual T
679560.6070 3082897.2580 J-41S 0.0385 Manual T
679532.9930 3082835.5820 J-42SD 0.055 Manual T
679552.9590 3082868.6600 J-43SD 0.065 Manual T
679456.8675 3082907.2053 0 Random

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter					
Analyte	n	$S \Delta \alpha \beta Z_{1-\alpha}^{a} Z_{1-\beta}^{b}$					Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=10	n	α=5		α=10		α=15	
AL=I	U	s=6	s=3	s=6	s=3	s=6	s=3
	β=5	391	99	310	78	260	66
LBGR=90	β=10	310	79	238	60	194	49
	β=15	261	67	195	50	156	40
	β=5	99	26	78	21	66	17
LBGR=80	β=10	79	21	60	16	49	13
	β=15	67	18	50	13	40	11
LBGR=70	β=5	45	13	36	10	30	8

β=10	36	10	28	8	23	6
β=15	31	9	23	7	18	5

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	21 Samples		
Field collection costs		\$100.00	\$2,100.00		
Analytical costs	\$400.00	\$400.00	\$8,400.00		
Sum of Field & Analytical costs		\$500.00	\$10,500.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$11,500.00		

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.0385	0.04	0.041	0.041	0.041	0.0415	0.042	0.042	0.042
10	0.042	0.04225	0.0425	0.0425	0.04275	0.043	0.043	0.0435	0.0435	0.04375
20	0.044	0.0445	0.045	0.045	0.04525	0.0455	0.046	0.0465	0.0465	0.048
30	0.048	0.0485	0.055	0.065	0.065	0.135	0.181	0.218	0.405	0.41
40	0.42	0.44	0.45	0.465	1.03					

SUMMARY STATISTICS			
n	45		
Min	0		
Max	1.03		
Range	1.03		
Mean	0.12643		
Median	0.045		
Variance	0.037077		
StdDev	0.19255		
Std Error	0.028704		
Skewness	2.9694		
Interquartile Range	0.022875		

Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.03895	0.041	0.04213	0.045	0.065	0.428	0.4605	1.03

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k Test Statistic R _k 5% Critical Value C _k Significant					
1	4.647	3.08	Yes		

The test statistic 4.647 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS			
1	1.03		

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)			
Shapiro-Wilk Test Statistic	0.5298		
Shapiro-Wilk 5% Critical Value	0.943		

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.5382			
Shapiro-Wilk 5% Critical Value	0.945			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN			
95% Parametric UCL	0.1747		
95% Non-Parametric (Chebyshev) UCL	0.2516		

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.2516) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=45 data,

AL is the action level or threshold (10),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=44 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-343.97	1.6802	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+)	95% Critical Value	Null Hypothesis			
45	28	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1				
	loord Labol	Value	Tuno	Historical
X Coord Y Coord Label 679149.492 3082933.098		J-13S	Type 0.042	
679149.492	3082933.098	J-13S J-14S	0.042	Manual Manual
679261.098		J-14S J-15S		Manual
	3083016.351		0.043	
679222.634	3082840.172	J-16S	0.0435	Manual
679293.56	3082950.498	J-17S	0.046	Manual
679360.57	3083026.498	J-18S	0.044	Manual
679343.581	3082969.598	J-19S	0.45 Mar	
679382.864	3083009.113	J-20S	0.405	Manual
679335.002	3082941.172	J-21S	0.44 Mar	
679252.713	3082781.029	J-22S	0.0425	Manual
679297.001	3082840.697	J-23S	0.041	Manual
679394.807	3082971.83	J-24S	0.41 Mar	
679146.646	3082549.764	J-25S	0.04525	Manual
679224.585	3082683.14	J-26S	0.04275	Manual
679169.076	3082537.351	J-27S	0.0445	Manual
679272.004	3082652.675	J-28S	0.045	Manual
679329.438	3082711.096	J-29S	0.0425	Manual
679374.442	3082791.33	J-30S	0.0485	Manual
679410.149	3082845.846	J-31S	0.04375	Manual
679453.476	3082914.115	J-32S	0.048	Manual
679495.884	3082940.973	J-33S	0.042	Manual
679304.653	3082548.688	J-34S	0.065	Manual
679342.741	3082605.319	J-35S	0.0435	Manual
679382.89	3082667.527	J-36S	0.0455	Manual
679433.945	3082731.682	J-37S	0.041	Manual
679470.357	3082776.735	J-38S	0.041	Manual
679497.331	3082840.396	J-39S	0.0465	Manual
679524.331	3082886.899	J-40S	0.043	Manual
679560.607	3082897.258	J-41S	0.0385	Manual
679532.993	3082835.582	J-42SD	0.055	Manual
679552.959	3082868.66	J-43SD	0.065	Manual
Area: Area 5				
X Coord Y C		Value	Type	Historical
679133.429	3083306.313	J-01S	0.048	Manual
679104.245	3083223.262	J-02S	0.04 Mar	nual
679155.074	3083294.696	J-03S	0.135	Manual
679171.297	3083289.796	J-04S	0.465	Manual
679225.856	3083359.974	J-05S	0.045	Manual
679164.806	3083214.71	J-06S	0.04225	Manual
679242.726	3083326.528	J-07S	0.42 Mar	nual
679181.275	3083178.288	J-08S	0.0415	Manual
679213.773	3083224.973	J-09S	1.03 Mar	
679280.544	3083305.681	J-10S	0.042	Manual
679268.77	3083200.326		0.0465	Manual
679301.16	3083254.034		0.218	Manual
3,7501.10	2002251.051	3 125	3.210	

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN				
Primary Objective of Design	Compare a site mean to a fixed threshold			
Type of Sampling Design	Parametric			
Sample Placement (Location) in the Field	Simple random sampling			
Working (Null) Hypothesis	The mean value at the site exceeds the threshold			
Formula for calculating number of sampling locations	Student's t-test			
Calculated total number of samples	21			
Number of samples on map ^a	42			
Number of selected sample areas b	2			
Specified sampling area ^c	188054.34 m ²			
Total cost of sampling ^d	\$11,500.00			

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1					
X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.63	Manual	Т
679104.2450	3083223.2620	J-02S	3.9	Manual	Т
679155.0740	3083294.6960	J-03S	1.2	Manual	Т
679171.2970	3083289.7960	J-04S	2.1	Manual	Т
679225.8560	3083359.9740	J-05S	0.8	Manual	Т
679164.8060	3083214.7100	J-06S	3.7	Manual	Т
679242.7260	3083326.5280	J-07S	4.3	Manual	Т
679181.2750	3083178.2880	J-08S	5.2	Manual	Т
679213.7730	3083224.9730	J-09S	1.8	Manual	Т
679280.5440	3083305.6810	J-10S	1	Manual	Т
679268.7700	3083200.3260	J-11S	0.98	Manual	Т
679301.1600	3083254.0340	J-12S	0.58	Manual	Т
679189.3221	3083262.2967	J-13S	4.9	Random	

Area: Area 3					
X Coord	Y Coord	Label	Value	Туре	Historical

679149.4920 3082933.0980 J-13S 4.9 Manua 679279.6830 3083075.4290 J-14S 0.6 Manua	
679279.6830 3083075.4290 J-14S 0.6 Manua	
	I T
679261.0980 3083016.3510 J-15S 3.4 Manua	I T
679222.6340 3082840.1720 J-16S 3.2 Manua	ı T
679293.5600 3082950.4980 J-17S 2.4 Manua	ı T
679360.5700 3083026.4980 J-18S 3.2 Manua	I T
679343.5810 3082969.5980 J-19S 15 Manua	I T
679382.8640 3083009.1130 J-20S 2.5 Manua	I T
679335.0020 3082941.1720 J-21S 0.59 Manua	I T
679252.7130 3082781.0290 J-22S 4.1 Manua	I T
679297.0010 3082840.6970 J-23S 3.5 Manua	ΙT
679394.8070 3082971.8300 J-24S 1.2 Manua	ΙT
679146.6460 3082549.7640 J-25S 7.4 Manua	ΙT
679224.5850 3082683.1400 J-26S 1.7 Manua	I T
679169.0760 3082537.3510 J-27S 3.7 Manua	I T
679272.0040 3082652.6750 J-28S 6.1 Manua	I T
679329.4380 3082711.0960 J-29S 2.7 Manua	I T
679374.4420 3082791.3300 J-30S 2.2 Manua	I T
679410.1490 3082845.8460 J-31S 0.76 Manua	I T
679453.4760 3082914.1150 J-32S 2.9 Manua	I T
679495.8840 3082940.9730 J-33S 1.9 Manua	I T
679304.6530 3082548.6880 J-34S 1.5 Manua	I T
679342.7410 3082605.3190 J-35S 1.8 Manua	I T
679382.8900 3082667.5270 J-36S 6 Manua	l T
679433.9450 3082731.6820 J-37S 8.8 Manua	l T
679470.3570 3082776.7350 J-38S 2.5 Manua	l T
679497.3310 3082840.3960 J-39S 1.4 Manua	l T
679524.3310 3082886.8990 J-40S 2.3 Manua	I T
679560.6070 3082897.2580 J-41S 2.2 Manua	I T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is $1-\beta$.

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


 $^{^{\}text{a}}$ This value is automatically calculated by VSP based upon the user defined value of α

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=0.39		α=	5	α=	10	α=15		
		s=6	s=3	s=6 s=3		s=6	s=3	
	β=5	256148	64038	202696	50675	170162	42541	
LBGR=90	β=10	202696	50676	155492	38874	127174	31794	
	β=15	170163	42542	127174	31795	101700	25426	
	β=5	64038	16011	50675	12670	42541	10636	
LBGR=80	β=10	50676	12670	38874	9720	31794	7949	
	β=15	42542	10637	31795	7950	25426	6357	
LBGR=70	β=5	28463	7117	22523	5632	18908	4728	

β=10	22523	5632	17278	4321	14131	3534
β=15	18909	4729	14132	3534	11301	2826

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION							
Cost Details	Per Analysis	Per Sample	21 Samples				
Field collection costs		\$100.00	\$2,100.00				
Analytical costs	\$400.00	\$400.00	\$8,400.00				
Sum of Field & Analytical costs		\$500.00	\$10,500.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$11,500.00				

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0.58	0.59	0.6	0.63	0.76	0.8	0.98	1	1.2	1.2
10	1.4	1.5	1.7	1.8	1.8	1.9	2.1	2.2	2.2	2.3
20	2.4	2.5	2.5	2.7	2.9	3.2	3.2	3.4	3.5	3.7
30	3.7	3.9	4.1	4.3	4.9	4.9	5.2	6	6.1	7.4
40	8.8	15								

SUMMARY STATISTICS				
n	42			
Min	0.58			
Max	15			
Range	14.42			
Mean	3.1319			
Median	2.45			
Variance	7.1636			
StdDev	2.6765			
Std Error	0.41299			
Skewness	2.4792			
Interquartile Range	2.6			

Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.58	0.5915	0.669	1.35	2.45	3.95	6.07	8.59	15

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST						
k	Test Statistic R _k	5% Critical Value C _k	Significant?			
1	4.434	3.06	Yes			

The test statistic 4.434 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	15

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Shapiro-Wilk Test Statistic	0.9051					
Shapiro-Wilk 5% Critical Value	0.941					

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic	0.7568				
Shapiro-Wilk 5% Critical Value	0.942				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	3.827
95% Non-Parametric (Chebyshev) UCL	4.932

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (4.932) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=42 data,

AL is the action level or threshold (0.39),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=41 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic	Critical Value t _{0.95}	Null Hypothesis				
6.6391	1.6829	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothe						
0	26	Cannot Reject				

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

```
Area: Area 1
X Coord Y Coord Label
                          Value
                                   Type
                                           Historical
                                   4.9 Manual
679149.492
             3082933.098 J-13S
                                   0.6 Manual
679279.683
             3083075.429 J-14S
679261.098
             3083016.351 J-15S
                                   3.4 Manual
679222.634
             3082840.172 J-16S
                                   3.2 Manual
679293.56
             3082950.498 J-17S
                                   2.4 Manual
679360.57
             3083026.498 J-18S
                                   3.2 Manual
679343.581
             3082969.598 J-19S
                                   15
                                       Manual
             3083009.113 J-20S
                                   2.5
                                       Manual
679382.864
679335.002
             3082941.172 J-21S
                                   0.59 Manual
679252.713
             3082781.029 J-22S
                                   4.1
                                      Manual
679297.001
             3082840.697 J-23S
                                   3.5
                                       Manual
679394.807
             3082971.83
                          J-24S
                                   1.2 Manual
             3082549.764 J-25S
                                       Manual
679146.646
                                   7.4
679224.585
             3082683.14
                          J-26S
                                   1.7 Manual
679169.076
             3082537.351 J-27S
                                   3.7
                                       Manual
679272.004
             3082652.675 J-28S
                                   6.1
                                       Manual
679329.438
             3082711.096 J-29S
                                   2.7 Manual
679374.442
             3082791.33
                          J-30S
                                   2.2 Manual
                                   0.76 Manual
679410.149
             3082845.846 J-31S
679453.476
             3082914.115 J-32S
                                   2.9 Manual
679495.884
             3082940.973 J-33S
                                   1.9 Manual
679304.653
             3082548.688 J-34S
                                   1.5
                                       Manual
679342.741
             3082605.319 J-35S
                                   1.8 Manual
679382.89
                                       Manual
             3082667.527 J-36S
679433.945
             3082731.682 J-37S
                                   8.8
                                       Manual
                                       Manual
679470.357
             3082776.735 J-38S
                                   2.5
679497.331
                                   1.4 Manual
             3082840.396 J-39S
679524.331
             3082886.899 J-40S
                                   2.3 Manual
679560.607
             3082897.258 J-41S
                                   2.2 Manual
Area: Area 5
X Coord Y Coord Label
                          Value
                                   Type
                                           Historical
                                   0.63 Manual
679133.429
             3083306.313 J-01S
679104.245
             3083223.262 J-02S
                                   3.9 Manual
679155.074
             3083294.696 J-03S
                                   1.2 Manual
679171.297
                                       Manual
             3083289.796 J-04S
                                   2.1
679225.856
             3083359.974 J-05S
                                   0.8 Manual
679164.806
             3083214.71
                          J-06S
                                   3.7
                                       Manual
679242.726
             3083326.528
                         J-07S
                                   4.3 Manual
679181.275
             3083178.288 J-08S
                                   5.2 Manual
679213.773
             3083224.973 J-09S
                                   1.8 Manual
679280.544
             3083305.681 J-10S
                                       Manual
                                   1
679268.77
                                   0.98 Manual
             3083200.326 J-11S
```

3083254.034 J-12S

0.58 Manual

679301.16

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN							
Primary Objective of Design	Compare a site mean to a fixed threshold						
Type of Sampling Design	Parametric						
Sample Placement (Location) in the Field	Simple random sampling						
Working (Null) Hypothesis	The mean value at the site exceeds the threshold						
Formula for calculating number of sampling locations	Student's t-test						
Calculated total number of samples	21						
Number of samples on map ^a	44						
Number of selected sample areas b	2						
Specified sampling area ^c	188054.34 m ²						
Total cost of sampling d	\$11,500.00						

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical				
679133.4290	3083306.3130	J-01S	2.8	Manual	Т				
679104.2450	3083223.2620	J-02S	0.9	Manual	Т				
679155.0740	3083294.6960	J-03S	1.25	Manual	Т				
679171.2970	3083289.7960	J-04S	0.92	Manual	Т				
679225.8560	3083359.9740	J-05S	0.77	Manual	Т				
679164.8060	3083214.7100	J-06S	0.505	Manual	Т				
679242.7260	3083326.5280	J-07S	13.3	Manual	Т				
679181.2750	3083178.2880	J-08S	3.6	Manual	Т				
679213.7730	3083224.9730	J-09S	4.5	Manual	Т				
679280.5440	3083305.6810	J-10S	2.9	Manual	Т				
679268.7700	3083200.3260	J-11S	11.3	Manual	Т				
679301.1600	3083254.0340	J-12S	2.3	Manual	Т				
679209.8633	3083350.5613	J-13S	1.4	Random					

Area: Area 3						
X Coord	Y Coord	Label	Value	Туре	Historical	

679149.4920 3082933.0980 J-13S 1.4 Manual T 679279.6830 3083075.4290 J-14S 5.1 Manual T 679261.0980 3083016.3510 J-15S 7.4 Manual T 679222.6340 3082840.1720 J-16S 4 Manual T 679293.5600 3082950.4980 J-17S 9 Manual T 679360.5700 3083026.4980 J-18S 2.8 Manual T 679343.5810 3082969.5980 J-19S 3.8 Manual T 679382.8640 3083009.1130 J-20S 4 Manual T 679385.0020 3082941.1720 J-21S 8.3 Manual T 679297.0010 3082840.6970 J-23S 6.9 Manual T 679346.6460 3082549.7640 J-25S 1.45 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679329.4380 3082711.0960					
679261.0980 3083016.3510 J-15S 7.4 Manual T 679222.6340 3082840.1720 J-16S 4 Manual T 679293.5600 3082950.4980 J-17S 9 Manual T 679360.5700 3083026.4980 J-18S 2.8 Manual T 679343.5810 3082969.5980 J-19S 3.8 Manual T 679382.8640 3083009.1130 J-20S 4 Manual T 679335.0020 3082941.1720 J-21S 8.3 Manual T 679252.7130 3082781.0290 J-22S 5.15 Manual T 679297.0010 3082840.6970 J-23S 6.9 Manual T 679348.8070 3082549.7640 J-25S 1.45 Manual T 679146.6460 3082537.3510 J-27S 4.2 Manual T 679329.4380 3082711.0960 J-28S 3.9 Manual T 679453.4760 3082914.1150	679149.4920	3082933.0980	J-13S	1.4	Manual T
679222.6340 3082840.1720 J-16S 4 Manual T 679293.5600 3082950.4980 J-17S 9 Manual T 679360.5700 3083026.4980 J-18S 2.8 Manual T 679343.5810 3082969.5980 J-19S 3.8 Manual T 679382.8640 3083009.1130 J-20S 4 Manual T 679335.0020 3082941.1720 J-21S 8.3 Manual T 679297.0010 3082840.6970 J-22S 5.15 Manual T 679297.0010 3082840.6970 J-23S 6.9 Manual T 679394.8070 3082971.8300 J-24S 1.6 Manual T 679146.6460 3082549.7640 J-25S 1.45 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679329.4380 3082711.0960 J-29S 6.7 Manual T 679470.1490 3082845.8460	679279.6830	3083075.4290	J-14S	5.1	Manual T
679293.5600 3082950.4980 J-17S 9 Manual T 679360.5700 3083026.4980 J-18S 2.8 Manual T 679343.5810 3082969.5980 J-19S 3.8 Manual T 679382.8640 3083009.1130 J-20S 4 Manual T 679335.0020 3082941.1720 J-21S 8.3 Manual T 679252.7130 3082781.0290 J-22S 5.15 Manual T 679297.0010 3082840.6970 J-23S 6.9 Manual T 679394.8070 3082971.8300 J-24S 1.6 Manual T 679146.6460 3082549.7640 J-25S 1.45 Manual T 679224.5850 3082683.1400 J-26S 1.714 Manual T 679329.4380 3082711.0960 J-29S 6.7 Manual T 679329.4380 3082791.3300 J-30S 10.4 Manual T 679453.4760 3082845.8460<	679261.0980	3083016.3510	J-15S	7.4	Manual T
679360.5700 3083026.4980 J-18S 2.8 Manual T 679343.5810 3082969.5980 J-19S 3.8 Manual T 679382.8640 3083009.1130 J-20S 4 Manual T 679335.0020 3082941.1720 J-21S 8.3 Manual T 679252.7130 3082781.0290 J-22S 5.15 Manual T 679297.0010 3082840.6970 J-23S 6.9 Manual T 679394.8070 3082971.8300 J-24S 1.6 Manual T 679394.8070 3082549.7640 J-25S 1.45 Manual T 679146.6460 3082549.7640 J-26S 1.714 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679372.0040 3082652.6750 J-28S 3.9 Manual T 679374.4420 3082791.3300 J-30S 10.4 Manual T 679495.8840 3082940.973	679222.6340	3082840.1720	J-16S	4	Manual T
679343.5810 3082969.5980 J-19S 3.8 Manual T 679382.8640 3083009.1130 J-20S 4 Manual T 679335.0020 3082941.1720 J-21S 8.3 Manual T 679252.7130 3082781.0290 J-22S 5.15 Manual T 679297.0010 3082840.6970 J-23S 6.9 Manual T 679394.8070 3082971.8300 J-24S 1.6 Manual T 679146.6460 3082549.7640 J-25S 1.45 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679272.0040 3082652.6750 J-28S 3.9 Manual T 679374.4420 3082711.0960 J-29S 6.7 Manual T 679453.4760 3082941.1150 J-31S 9.6 Manual T 679495.8840 3082940.9730 </td <td>679293.5600</td> <td>3082950.4980</td> <td>J-17S</td> <td>9</td> <td>Manual T</td>	679293.5600	3082950.4980	J-17S	9	Manual T
679382.8640 3083009.1130 J-20S 4 Manual T 679335.0020 3082941.1720 J-21S 8.3 Manual T 679252.7130 3082781.0290 J-22S 5.15 Manual T 679297.0010 3082840.6970 J-23S 6.9 Manual T 679394.8070 3082971.8300 J-24S 1.6 Manual T 679146.6460 3082549.7640 J-25S 1.45 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679272.0040 3082652.6750 J-28S 3.9 Manual T 679329.4380 3082791.3300 J-30S 10.4 Manual T 679374.4420 30828791.3300 J-30S 10.4 Manual T 679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082914.1150 J-32S 8.9 Manual T 679304.6530 3082860.973	679360.5700	3083026.4980	J-18S	2.8	Manual T
679335.0020 3082941.1720 J-21S 8.3 Manual T 679252.7130 3082781.0290 J-22S 5.15 Manual T 679297.0010 3082840.6970 J-23S 6.9 Manual T 679394.8070 3082971.8300 J-24S 1.6 Manual T 679146.6460 3082549.7640 J-25S 1.45 Manual T 679224.5850 3082683.1400 J-26S 1.714 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679272.0040 3082652.6750 J-28S 3.9 Manual T 679374.4420 3082791.3300 J-30S 10.4 Manual T 679453.4760 3082945.8460 J-31S 9.6 Manual T 679495.8840 3082940.9730 J-32S 8.9 Manual T 679304.6530 3082548.6880 J-34S 14.9 Manual T 679382.8900 3082667.	679343.5810	3082969.5980	J-19S	3.8	Manual T
679252.7130 3082781.0290 J-22S 5.15 Manual T 679297.0010 3082840.6970 J-23S 6.9 Manual T 679394.8070 3082971.8300 J-24S 1.6 Manual T 679146.6460 3082549.7640 J-25S 1.45 Manual T 679224.5850 3082683.1400 J-26S 1.714 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679272.0040 3082652.6750 J-28S 3.9 Manual T 679374.4420 3082711.0960 J-29S 6.7 Manual T 679470.1490 3082845.8460 J-31S 9.6 Manual T 679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082940.9730 J-33S 2 Manual T 679342.7410 3082667.5270 J-36S 5.05 Manual T 679433.9450 3082731.682	679382.8640	3083009.1130	J-20S	4	Manual T
679297.0010 3082840.6970 J-23S 6.9 Manual T 679394.8070 3082971.8300 J-24S 1.6 Manual T 679146.6460 3082549.7640 J-25S 1.45 Manual T 679224.5850 3082683.1400 J-26S 1.714 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679272.0040 3082652.6750 J-28S 3.9 Manual T 679329.4380 3082711.0960 J-29S 6.7 Manual T 679374.4420 3082791.3300 J-30S 10.4 Manual T 679410.1490 3082845.8460 J-31S 9.6 Manual T 679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082940.9730 J-33S 2 Manual T 679342.7410 3082605.3190 J-35S 3.6 Manual T 679433.9450 3082731.6820	679335.0020	3082941.1720	J-21S	8.3	Manual T
679394.8070 3082971.8300 J-24S 1.6 Manual T 679146.6460 3082549.7640 J-25S 1.45 Manual T 679224.5850 3082683.1400 J-26S 1.714 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679272.0040 3082652.6750 J-28S 3.9 Manual T 679329.4380 3082711.0960 J-29S 6.7 Manual T 679374.4420 3082791.3300 J-30S 10.4 Manual T 679410.1490 3082845.8460 J-31S 9.6 Manual T 679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082940.9730 J-33S 2 Manual T 679304.6530 3082548.6880 J-34S 14.9 Manual T 679382.8900 3082667.5270 J-36S 5.05 Manual T 679470.3570 3082776.73	679252.7130	3082781.0290	J-22S	5.15	Manual T
679146.6460 3082549.7640 J-25S 1.45 Manual T 679224.5850 3082683.1400 J-26S 1.714 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679272.0040 3082652.6750 J-28S 3.9 Manual T 679329.4380 3082711.0960 J-29S 6.7 Manual T 679374.4420 3082791.3300 J-30S 10.4 Manual T 679410.1490 3082845.8460 J-31S 9.6 Manual T 679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082940.9730 J-33S 2 Manual T 679304.6530 3082548.6880 J-34S 14.9 Manual T 679382.8900 3082667.5270 J-36S 5.05 Manual T 679470.3570 3082731.6820 J-37S 4.9 Manual T 679524.3310 3082840.3960 J-39S 4.5 Manual T 679550.6070	679297.0010	3082840.6970	J-23S	6.9	Manual T
679224.5850 3082683.1400 J-26S 1.714 Manual T 679169.0760 3082537.3510 J-27S 4.2 Manual T 679272.0040 3082652.6750 J-28S 3.9 Manual T 679329.4380 3082711.0960 J-29S 6.7 Manual T 679374.4420 3082791.3300 J-30S 10.4 Manual T 679410.1490 3082845.8460 J-31S 9.6 Manual T 679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082940.9730 J-33S 2 Manual T 679304.6530 3082548.6880 J-34S 14.9 Manual T 679342.7410 3082605.3190 J-35S 3.6 Manual T 679433.9450 3082731.6820 J-37S 4.9 Manual T 679470.3570 308276.7350 J-38S 6.4 Manual T 679524.3310 3082840.3960 J-39S 4.5 Manual T 679560.6070 <t< td=""><td>679394.8070</td><td>3082971.8300</td><td>J-24S</td><td>1.6</td><td>Manual T</td></t<>	679394.8070	3082971.8300	J-24S	1.6	Manual T
679169.0760 3082537.3510 J-27S 4.2 Manual T 679272.0040 3082652.6750 J-28S 3.9 Manual T 679329.4380 3082711.0960 J-29S 6.7 Manual T 679374.4420 3082791.3300 J-30S 10.4 Manual T 679410.1490 3082845.8460 J-31S 9.6 Manual T 679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082940.9730 J-33S 2 Manual T 679304.6530 3082548.6880 J-34S 14.9 Manual T 679342.7410 3082605.3190 J-35S 3.6 Manual T 679433.9450 3082731.6820 J-37S 4.9 Manual T 679470.3570 3082776.7350 J-38S 6.4 Manual T 679524.3310 3082840.3960 J-39S 4.5 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 <td< td=""><td>679146.6460</td><td>3082549.7640</td><td>J-25S</td><td>1.45</td><td>Manual T</td></td<>	679146.6460	3082549.7640	J-25S	1.45	Manual T
679272.0040 3082652.6750 J-28S 3.9 Manual T 679329.4380 3082711.0960 J-29S 6.7 Manual T 679374.4420 3082791.3300 J-30S 10.4 Manual T 679410.1490 3082845.8460 J-31S 9.6 Manual T 679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082940.9730 J-33S 2 Manual T 679304.6530 3082548.6880 J-34S 14.9 Manual T 679342.7410 3082605.3190 J-35S 3.6 Manual T 679433.9450 3082667.5270 J-36S 5.05 Manual T 679470.3570 3082776.7350 J-38S 6.4 Manual T 679497.3310 3082840.3960 J-39S 4.5 Manual T 679524.3310 3082886.8990 J-40S 7.8 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679224.5850	3082683.1400	J-26S	1.714	Manual T
679329.4380 3082711.0960 J-29S 6.7 Manual T 679374.4420 3082791.3300 J-30S 10.4 Manual T 679410.1490 3082845.8460 J-31S 9.6 Manual T 679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082940.9730 J-33S 2 Manual T 679304.6530 3082548.6880 J-34S 14.9 Manual T 679342.7410 3082605.3190 J-35S 3.6 Manual T 679382.8900 3082667.5270 J-36S 5.05 Manual T 679433.9450 3082731.6820 J-37S 4.9 Manual T 679470.3570 308276.7350 J-38S 6.4 Manual T 6795924.3310 3082840.3960 J-39S 4.5 Manual T 679560.6070 3082887.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679169.0760	3082537.3510	J-27S	4.2	Manual T
679374.4420 3082791.3300 J-30S 10.4 Manual T 679410.1490 3082845.8460 J-31S 9.6 Manual T 679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082940.9730 J-33S 2 Manual T 679304.6530 3082548.6880 J-34S 14.9 Manual T 679342.7410 3082605.3190 J-35S 3.6 Manual T 679382.8900 3082667.5270 J-36S 5.05 Manual T 679433.9450 3082731.6820 J-37S 4.9 Manual T 679470.3570 3082776.7350 J-38S 6.4 Manual T 679497.3310 3082840.3960 J-39S 4.5 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679272.0040	3082652.6750	J-28S	3.9	Manual T
679410.1490 3082845.8460 J-31S 9.6 Manual T 679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082940.9730 J-33S 2 Manual T 679304.6530 3082548.6880 J-34S 14.9 Manual T 679342.7410 3082605.3190 J-35S 3.6 Manual T 679382.8900 3082667.5270 J-36S 5.05 Manual T 679433.9450 3082731.6820 J-37S 4.9 Manual T 679470.3570 3082776.7350 J-38S 6.4 Manual T 679497.3310 3082840.3960 J-39S 4.5 Manual T 679524.3310 3082886.8990 J-40S 7.8 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679329.4380	3082711.0960	J-29S	6.7	Manual T
679453.4760 3082914.1150 J-32S 8.9 Manual T 679495.8840 3082940.9730 J-33S 2 Manual T 679304.6530 3082548.6880 J-34S 14.9 Manual T 679342.7410 3082605.3190 J-35S 3.6 Manual T 679382.8900 3082667.5270 J-36S 5.05 Manual T 679433.9450 3082731.6820 J-37S 4.9 Manual T 679470.3570 3082776.7350 J-38S 6.4 Manual T 679497.3310 3082840.3960 J-39S 4.5 Manual T 679524.3310 3082886.8990 J-40S 7.8 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679374.4420	3082791.3300	J-30S	10.4	Manual T
679495.8840 3082940.9730 J-33S 2 Manual T 679304.6530 3082548.6880 J-34S 14.9 Manual T 679342.7410 3082605.3190 J-35S 3.6 Manual T 679382.8900 3082667.5270 J-36S 5.05 Manual T 679433.9450 3082731.6820 J-37S 4.9 Manual T 679470.3570 3082776.7350 J-38S 6.4 Manual T 679497.3310 3082840.3960 J-39S 4.5 Manual T 679524.3310 3082886.8990 J-40S 7.8 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679410.1490	3082845.8460	J-31S	9.6	Manual T
679304.6530 3082548.6880 J-34S 14.9 Manual T 679342.7410 3082605.3190 J-35S 3.6 Manual T 679382.8900 3082667.5270 J-36S 5.05 Manual T 679433.9450 3082731.6820 J-37S 4.9 Manual T 679470.3570 3082776.7350 J-38S 6.4 Manual T 679497.3310 3082840.3960 J-39S 4.5 Manual T 679524.3310 3082886.8990 J-40S 7.8 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679453.4760	3082914.1150	J-32S	8.9	Manual T
679342.7410 3082605.3190 J-35S 3.6 Manual T 679382.8900 3082667.5270 J-36S 5.05 Manual T 679433.9450 3082731.6820 J-37S 4.9 Manual T 679470.3570 3082776.7350 J-38S 6.4 Manual T 679497.3310 3082840.3960 J-39S 4.5 Manual T 679524.3310 3082886.8990 J-40S 7.8 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679495.8840	3082940.9730	J-33S	2	Manual T
679382.8900 3082667.5270 J-36S 5.05 Manual T 679433.9450 3082731.6820 J-37S 4.9 Manual T 679470.3570 3082776.7350 J-38S 6.4 Manual T 679497.3310 3082840.3960 J-39S 4.5 Manual T 679524.3310 3082886.8990 J-40S 7.8 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679304.6530	3082548.6880	J-34S	14.9	Manual T
679433.9450 3082731.6820 J-37S 4.9 Manual T 679470.3570 3082776.7350 J-38S 6.4 Manual T 679497.3310 3082840.3960 J-39S 4.5 Manual T 679524.3310 3082886.8990 J-40S 7.8 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679342.7410	3082605.3190	J-35S	3.6	Manual T
679470.3570 3082776.7350 J-38S 6.4 Manual T 679497.3310 3082840.3960 J-39S 4.5 Manual T 679524.3310 3082886.8990 J-40S 7.8 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679382.8900	3082667.5270	J-36S	5.05	Manual T
679497.3310 3082840.3960 J-39S 4.5 Manual T 679524.3310 3082886.8990 J-40S 7.8 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679433.9450	3082731.6820	J-37S	4.9	Manual T
679524.3310 3082886.8990 J-40S 7.8 Manual T 679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679470.3570	3082776.7350	J-38S	6.4	Manual T
679560.6070 3082897.2580 J-41S 3.7 Manual T 679532.9930 3082835.5820 J-42SD 1.7 Manual T	679497.3310	3082840.3960	J-39S	4.5	Manual T
679532.9930 3082835.5820 J-42SD 1.7 Manual T	679524.3310	3082886.8990	J-40S	7.8	Manual T
	679560.6070	3082897.2580	J-41S	3.7	Manual T
679552.9590 3082868.6600 J-43SD 4.9 Manual T	679532.9930	3082835.5820	J-42SD	1.7	Manual T
	679552.9590	3082868.6600	J-43SD	4.9	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter						
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b	
	21	3	2	0.05	0.1	1.64485	1.28155	


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
A1 _0.3		α=5		α=	10	α=15		
AL=0.3	9	s=6	s=3	s=6 s=3		s=6	s=3	
	β=5	256148	64038	202696	50675	170162	42541	
LBGR=90	β=10	202696	50676	155492	38874	127174	31794	
	β=15	170163	42542	127174	31795	101700	25426	
	β=5	64038	16011	50675	12670	42541	10636	
LBGR=80	β=10	50676	12670	38874	9720	31794	7949	
	β=15	42542	10637	31795	7950	25426	6357	
LBGR=70	β=5	28463	7117	22523	5632	18908	4728	

β=10	22523	5632	17278	4321	14131	3534
β=15	18909	4729	14132	3534	11301	2826

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	21 Samples					
Field collection costs		\$100.00	\$2,100.00					
Analytical costs	\$400.00	\$400.00	\$8,400.00					
Sum of Field & Analytical costs		\$500.00	\$10,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$11,500.00					

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.505	0.77	0.9	0.92	1.25	1.4	1.4	1.45	1.6
10	1.7	1.714	2	2.3	2.8	2.8	2.9	3.6	3.6	3.7
20	3.8	3.9	4	4	4.2	4.5	4.5	4.9	4.9	5.05
30	5.1	5.15	6.4	6.7	6.9	7.4	7.8	8.3	8.9	9
40	9.6	10.4	11.3	13.3	14.9					

SUMMARY STATISTICS					
n	45				
Min	0				
Max	14.9				
Range	14.9				
Mean	4.7158				
Median	4				
Variance	12.31				
StdDev	3.5086				
Std Error	0.52303				
Skewness	1.0456				
Interquartile Range	5.093				

Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.5845	0.912	1.707	4	6.8	9.92	12.7	14.9

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST							
k	Test Statistic R _k	5% Critical Value C _k	Significant?				
1	2.878	3.08	No				

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)							
Shapiro-Wilk Test Statistic	0.9332						
Shapiro-Wilk 5% Critical Value	0.943						

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic	0.9105				
Shapiro-Wilk 5% Critical Value	0.945				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that

assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	5.595
95% Non-Parametric (Chebyshev) UCL	6.996

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (6.996) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=45 data, AL is the action level or threshold (0.39),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=44 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic Critical Value $t_{0.95}$ Null Hypothesis						
8.2705	1.6802	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothesis						
1	28	Cannot Reject				

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

```
Area: Area 1
X Coord Y Coord Label
                          Value
                                   Type
                                            Historical
679149.492
             3082933.098 J-13S
                                   1.4 Manual
                                       Manual
679279.683
             3083075.429 J-14S
                                   5.1
679261.098
             3083016.351 J-15S
                                   7.4
                                      Manual
679222.634
             3082840.172 J-16S
                                       Manual
679293.56
             3082950.498 J-17S
                                   9
                                       Manual
679360.57
             3083026.498 J-18S
                                   2.8
                                      Manual
679343.581
             3082969.598 J-19S
                                   3.8
                                      Manual
             3083009.113 J-20S
                                       Manual
679382.864
                                   4
                                   8.3 Manual
679335.002
             3082941.172 J-21S
679252.713
             3082781.029 J-22S
                                   5.15 Manual
679297.001
             3082840.697 J-23S
                                   6.9 Manual
679394.807
             3082971.83
                          J-24S
                                   1.6 Manual
             3082549.764 J-25S
                                   1.45 Manual
679146.646
679224.585
             3082683.14
                          J-26S
                                   1.714
                                           Manual
679169.076
             3082537.351 J-27S
                                   4.2 Manual
679272.004
             3082652.675 J-28S
                                   3.9 Manual
679329.438
             3082711.096 J-29S
                                   6.7 Manual
679374.442
             3082791.33
                          J-30S
                                   10.4 Manual
                                   9.6 Manual
679410.149
             3082845.846 J-31S
679453.476
             3082914.115 J-32S
                                   8.9 Manual
679495.884
             3082940.973 J-33S
                                       Manual
679304.653
             3082548.688 J-34S
                                   14.9 Manual
679342.741
             3082605.319 J-35S
                                   3.6 Manual
679382.89
             3082667.527 J-36S
                                   5.05 Manual
679433.945
             3082731.682 J-37S
                                   4.9 Manual
679470.357
             3082776.735 J-38S
                                   6.4 Manual
679497.331
             3082840.396 J-39S
                                   4.5
                                       Manual
679524.331
             3082886.899 J-40S
                                   7.8 Manual
679560.607
             3082897.258 J-41S
                                   3.7
                                       Manual
679532.993
             3082835.582 J-42SD
                                   1.7
                                       Manual
679552.959
                          J-43SD
             3082868.66
                                   4.9
                                       Manual
Area: Area 5
X Coord Y Coord Label
                          Value
                                   Type
                                            Historical
679133.429
             3083306.313 J-01S
                                   2.8 Manual
679104.245
             3083223.262 J-02S
                                   0.9 Manual
679155.074
             3083294.696 J-03S
                                   1.25 Manual
679171.297
             3083289.796 J-04S
                                   0.92 Manual
679225.856
             3083359.974 J-05S
                                   0.77 Manual
679164.806
             3083214.71
                          J-06S
                                   0.505
                                            Manual
679242.726
             3083326.528 J-07S
                                   13.3 Manual
679181.275
             3083178.288 J-08S
                                   3.6 Manual
679213.773
             3083224.973
                         J-09S
                                   4.5
                                      Manual
679280.544
             3083305.681 J-10S
                                   2.9 Manual
679268.77
             3083200.326 J-11S
                                   11.3 Manual
```

3083254.034 J-12S

2.3 Manual

679301.16

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	23
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1								
X Coord	Y Coord	Label	Value	Туре	Historical			
679133.4290	3083306.3130	TW01-01	5.9	Manual	Т			
679104.2450	3083223.2620	TW01-02	5.9	Manual	Т			
679242.7260	3083326.5280	TW01-07	5.9	Manual	Т			
679181.2750	3083178.2880	TW01-08	5.9	Manual	Т			
679268.7700	3083200.3260	TW01-11	5.9	Manual	Т			
679301.1600	3083254.0340	TW01-12	5.9	Manual	Т			

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			
679532.9930	3082835.5820	J-42SD	7.6	Manual	Т			
679552.9590	3082868.6600	J-43SD	10.1	Manual	Т			
679149.4920	3082933.0980	TW01-13	5.9	Manual	Т			
679279.7760	3083075.6320	TW01-14	5.9	Manual	Т			
679293.5600	3082950.4980	TW01-17	5.9	Manual	Т			
679360.5700	3083026.4980	TW01-18	5.9	Manual	Т			
679169.0760	3082537.3510	TW01-27	5.9	Manual	Т			

679495.8840	3082940.9730	TW01-33	5.9	Manual	Т
679304.6530	3082548.6880	TW01-34	5.9	Manual	Т
679342.7410	3082605.3190	TW01-35	5.9	Manual	Т
679382.8900	3082667.5270	TW01-36	5.9	Manual	Т
679433.9450	3082731.6820	TW01-37	6.7	Manual	Т
679470.3570	3082776.7350	TW01-38	6.4	Manual	Т
679497.3310	3082840.3960	TW01-39	5.9	Manual	Т
679524.3310	3082886.8990	TW01-40	5.9	Manual	Т
679560.6110	3082897.2580	TW01-41	5.9	Manual	Т
679499.9834	3082811.7752		0	Random	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .


The values of these inputs that result in the calculated number of sampling locations are:

Amalasta	_				Para	ameter	
Analyte	11	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

b This value is automatically calculated by VSP based upon the user defined value of β.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=3.6		α=	α=5		α=10		α=15	
		s=6	s=3	s=6	s=3	s=6	s=3	
	β=5	3008	753	2380	596	1998	500	
LBGR=90	β=10	2381	597	1826	458	1494	374	
	β=15	1999	501	1494	374	1195	299	
	β=5	753	190	596	150	500	126	
LBGR=80	β=10	597	151	458	115	374	94	
	β=15	501	127	374	95	299	76	
	β=5	336	85	266	67	223	57	
LBGR=70	β=10	266	68	204	52	167	42	
	β=15	224	57	167	43	134	34	

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION							
Cost Details	Per Analysis	Per Sample	21 Samples				
Field collection costs		\$100.00	\$2,100.00				
Analytical costs	\$400.00	\$400.00	\$8,400.00				
Sum of Field & Analytical costs		\$500.00	\$10,500.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$11,500.00				

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	5.9	5.9	5.9	5.9	5.9	5.9	5.9	5.9	5.9
10	5.9	5.9	5.9	5.9	5.9	5.9	5.9	5.9	5.9	6.4
20	6.7	7.6	10.1							

SUMMARY STATISTICS

n				23					
	Min				0				
	М	ах				10.1			
	Rai	nge				10.1			
	Me	ean			į	5.9565	5		
	Median					5.9			
	Variance			2.5526					
	StdDev			1.5977					
	Std I	Error		0.33314					
Skewness			-1.6512						
Inte	Interquartile Range			0					
Percentiles									
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0	1.18	5.9	5.9	5.9	5.9	7.24	9.6	10.1	

Outlier Test

Dixon's extreme value test was performed to test whether the lowest value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

DIXON'S OUTLIER TEST				
Dixon Test Statistic 0.8806				
Dixon 5% Critical Value	0.421			

The calculated test statistic exceeds the critical value, so the test rejects the null hypothesis that there are no outliers in the data, and concludes that the minimum value 0 is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
Min	0

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Dixon's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.4044				
Shapiro-Wilk 5% Critical Value	0.911				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the minimum value 0, do not appear to follow a normal distribution at the 5% level of significance. Dixon's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through

2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic 0.5252				
Shapiro-Wilk 5% Critical Value	0.914			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	6.529
95% Non-Parametric (Chebyshev) UCL	7.409

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (7.409) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=23 data, AL is the action level or threshold (3.6).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=22 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
7.0737	1.7171	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
1	15	Cannot Reject			

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp
Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1 X Coord Y Coord Label Value Type Historical 679532.993 3082835.582 J-42SD 7.6 Manual 679552.959 3082868.66 J-43SD 10.1 Manual 679149.492 3082933.098 TW01-135.9 Manual 679279.776 3083075.632 TW01-145.9 Manual 679293.56 3082950.498 TW01-175.9 Manual 3083026.498 TW01-185.9 Manual 679360.57 679169.076 3082537.351 TW01-275.9 Manual 679495.884 3082940.973 TW01-335.9 Manual 3082548.688 TW01-345.9 Manual 679304.653 679342.741 3082605.319 TW01-355.9 Manual 3082667.527 TW01-365.9 Manual 679382.89 679433.945 3082731.682 TW01-376.7 Manual 679470.357 3082776.735 TW01-386.4 Manual 679497.331 3082840.396 TW01-395.9 Manual 3082886.899 TW01-405.9 Manual 679524.331 679560.611 3082897.258 TW01-415.9 Manual

Area: Area 5

X Coord Y C	Coord Label	Value	Туре	e Historical
679133.429	3083306.313	TW01-0	15.9	Manual
679104.245	3083223.262	TW01-0	25.9	Manual
679242.726	3083326.528	TW01-0	75.9	Manual
679181.275	3083178.288	TW01-0	85.9	Manual
679268.77	3083200.326	TW01-1	15.9	Manual
679301.16	3083254.034	TW01-1	25.9	Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	44
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical					
679133.4290	3083306.3130	J-01S	0.044	Manual	Т					
679104.2450	3083223.2620	J-02S	0.0365	Manual	Т					
679155.0740	3083294.6960	J-03S	0.1225	Manual	Т					
679171.2970	3083289.7960	J-04S	0.425	Manual	Т					
679225.8560	3083359.9740	J-05S	0.0415	Manual	Т					
679164.8060	3083214.7100	J-06S	0.03875	Manual	Т					
679242.7260	3083326.5280	J-07S	0.385	Manual	Т					
679181.2750	3083178.2880	J-08S	0.038	Manual	Т					
679213.7730	3083224.9730	J-09S	0.813	Manual	Т					
679280.5440	3083305.6810	J-10S	0.038	Manual	Т					
679268.7700	3083200.3260	J-11S	0.043	Manual	Т					
679301.1600	3083254.0340	J-12S	0.192	Manual	Т					
679192.6469	3083183.8817	J-13S	0.0385	Random						

Area: Area 3							
X Coord	Y Coord	Label	Value	Туре	Historical		

679149.4920 3082933.0980 J-13S 0.0385 Manual T 679279.6830 3083075.4290 J-14S 0.041 Manual T 679261.0980 3083016.3510 J-15S 0.0395 Manual T 679223.5600 3082950.4980 J-17S 0.042 Manual T 679360.5700 3083026.4980 J-18S 0.0405 Manual T 679343.5810 3082969.5980 J-19S 0.415 Manual T 679335.0020 3082941.1720 J-21S 0.405 Manual T 679352.7130 3082871.0290 J-22S 0.037 Manual T 679297.0010 3082840.6970 J-23S 0.0375 Manual T 679346.6460 3082549.7640 J-25S 0.04175 Manual T 679149.0760 3082537.3510 J-27S 0.041 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679374.4420 </th <th></th> <th></th> <th></th> <th></th> <th></th> <th></th>						
679261.0980 3083016.3510 J-15S 0.0395 Manual T 679222.6340 3082840.1720 J-16S 0.04 Manual T 679293.5600 3082950.4980 J-17S 0.042 Manual T 679360.5700 3083026.4980 J-18S 0.0405 Manual T 679343.5810 3082969.5980 J-19S 0.415 Manual T 679382.8640 3083009.1130 J-20S 0.37 Manual T 679335.0020 3082941.1720 J-21S 0.405 Manual T 679252.7130 3082781.0290 J-22S 0.039 Manual T 679297.0010 3082840.6970 J-23S 0.0375 Manual T 679394.8070 3082549.7640 J-25S 0.04175 Manual T 679146.6460 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082537.3510 J-27S 0.041 Manual T 679372.4380	679149.4920	3082933.0980	J-13S	0.0385	Manual	Т
679222.6340 3082840.1720 J-16S 0.04 Manual T 679293.5600 3082950.4980 J-17S 0.042 Manual T 679360.5700 3083026.4980 J-18S 0.0405 Manual T 679343.5810 3082969.5980 J-19S 0.415 Manual T 679382.8640 3083009.1130 J-20S 0.37 Manual T 679335.0020 3082941.1720 J-21S 0.405 Manual T 679252.7130 3082781.0290 J-22S 0.039 Manual T 679297.0010 3082840.6970 J-23S 0.0375 Manual T 679394.8070 3082971.8300 J-24S 0.375 Manual T 679146.6460 3082549.7640 J-25S 0.04175 Manual T 679169.0760 3082537.3510 J-27S 0.041 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679470.1490	679279.6830	3083075.4290	J-14S	0.041	Manual	Т
679293.5600 3082950.4980 J-17S 0.042 Manual T 679360.5700 3083026.4980 J-18S 0.0405 Manual T 679343.5810 3082969.5980 J-19S 0.415 Manual T 679382.8640 3083009.1130 J-20S 0.37 Manual T 679335.0020 3082941.1720 J-21S 0.405 Manual T 679252.7130 3082781.0290 J-22S 0.039 Manual T 679297.0010 3082840.6970 J-23S 0.0375 Manual T 679394.8070 3082549.7640 J-25S 0.04175 Manual T 679146.6460 3082549.7640 J-25S 0.04175 Manual T 679169.0760 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082652.6750 J-28S 0.0415 Manual T 679349.4380 3082711.0960 J-29S 0.039 Manual T 679453.4760 </td <td>679261.0980</td> <td>3083016.3510</td> <td>J-15S</td> <td>0.0395</td> <td>Manual</td> <td>Т</td>	679261.0980	3083016.3510	J-15S	0.0395	Manual	Т
679360.5700 3083026.4980 J-18S 0.0405 Manual T 679343.5810 3082969.5980 J-19S 0.415 Manual T 679382.8640 3083009.1130 J-20S 0.37 Manual T 679335.0020 3082941.1720 J-21S 0.405 Manual T 679252.7130 3082781.0290 J-22S 0.039 Manual T 679297.0010 3082840.6970 J-23S 0.0375 Manual T 679394.8070 3082971.8300 J-24S 0.375 Manual T 679146.6460 3082549.7640 J-25S 0.04175 Manual T 679169.0760 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082652.6750 J-28S 0.0415 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679410.1490 3082845.8460 J-31S 0.04025 Manual T 679453.4760 </td <td>679222.6340</td> <td>3082840.1720</td> <td>J-16S</td> <td>0.04</td> <td>Manual</td> <td>Т</td>	679222.6340	3082840.1720	J-16S	0.04	Manual	Т
679343.5810 3082969.5980 J-19S 0.415 Manual T 679382.8640 3083009.1130 J-20S 0.37 Manual T 679335.0020 3082941.1720 J-21S 0.405 Manual T 679252.7130 3082781.0290 J-22S 0.039 Manual T 679297.0010 3082840.6970 J-23S 0.0375 Manual T 679394.8070 3082971.8300 J-24S 0.375 Manual T 679146.6460 3082549.7640 J-25S 0.04175 Manual T 679169.0760 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082652.6750 J-28S 0.0415 Manual T 679374.4420 3082791.3300 J-30S 0.0445 Manual T 679453.4760 3082945.8460 J-31S 0.04025 Manual T 679495.8840 3082940.9730 J-33S 0.0385 Manual T 679382.8900<	679293.5600	3082950.4980	J-17S	0.042	Manual	Т
679382.8640 3083009.1130 J-20S 0.37 Manual T 679335.0020 3082941.1720 J-21S 0.405 Manual T 679252.7130 3082781.0290 J-22S 0.039 Manual T 679297.0010 3082840.6970 J-23S 0.0375 Manual T 679394.8070 3082971.8300 J-24S 0.375 Manual T 679146.6460 3082549.7640 J-25S 0.04175 Manual T 679169.0760 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082652.6750 J-28S 0.0415 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679374.4420 3082791.3300 J-30S 0.0445 Manual T 679453.4760 3082941.1150 J-31S 0.04025 Manual T 679495.8840 3082940.9730 J-33S 0.0385 Manual T 679342.7410<	679360.5700	3083026.4980	J-18S	0.0405	Manual	Т
679335.0020 3082941.1720 J-21S 0.405 Manual T 679252.7130 3082781.0290 J-22S 0.039 Manual T 679297.0010 3082840.6970 J-23S 0.0375 Manual T 679394.8070 3082971.8300 J-24S 0.375 Manual T 679146.6460 3082549.7640 J-25S 0.04175 Manual T 679224.5850 3082683.1400 J-26S 0.03925 Manual T 679169.0760 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082652.6750 J-28S 0.0415 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679374.4420 3082871.3300 J-30S 0.0445 Manual T 679453.4760 3082914.1150 J-31S 0.0445 Manual T 679304.6530 3082548.6880 J-34S 0.04 Manual T 679382.8900<	679343.5810	3082969.5980	J-19S	0.415	Manual	Т
679252.7130 3082781.0290 J-22S 0.039 Manual T 679297.0010 3082840.6970 J-23S 0.0375 Manual T 679394.8070 3082971.8300 J-24S 0.375 Manual T 679146.6460 3082549.7640 J-25S 0.04175 Manual T 679224.5850 3082683.1400 J-26S 0.03925 Manual T 679169.0760 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082652.6750 J-28S 0.0415 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679374.4420 3082791.3300 J-30S 0.0445 Manual T 679453.4760 3082845.8460 J-31S 0.04025 Manual T 679495.8840 3082940.9730 J-33S 0.044 Manual T 679342.7410 3082667.5270 J-36S 0.042 Manual T 679433.945	679382.8640	3083009.1130	J-20S	0.37	Manual	Т
679297.0010 3082840.6970 J-23S 0.0375 Manual T 679394.8070 3082971.8300 J-24S 0.375 Manual T 679146.6460 3082549.7640 J-25S 0.04175 Manual T 679224.5850 3082683.1400 J-26S 0.03925 Manual T 679169.0760 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082652.6750 J-28S 0.0415 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679374.4420 3082791.3300 J-30S 0.0445 Manual T 679410.1490 3082845.8460 J-31S 0.04025 Manual T 679453.4760 3082914.1150 J-32S 0.044 Manual T 679495.8840 3082940.9730 J-33S 0.0385 Manual T 679342.7410 3082667.5270 J-36S 0.042 Manual T 679433.94	679335.0020	3082941.1720	J-21S	0.405	Manual	Т
679394.8070 3082971.8300 J-24S 0.375 Manual T 679146.6460 3082549.7640 J-25S 0.04175 Manual T 679224.5850 3082683.1400 J-26S 0.03925 Manual T 679169.0760 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082652.6750 J-28S 0.0415 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679374.4420 3082791.3300 J-30S 0.0445 Manual T 679410.1490 3082845.8460 J-31S 0.04025 Manual T 679453.4760 3082914.1150 J-32S 0.044 Manual T 679304.6530 3082940.9730 J-33S 0.0385 Manual T 679342.7410 3082605.3190 J-34S 0.04 Manual T 679382.8900 3082667.5270 J-36S 0.042 Manual T 679470.3570	679252.7130	3082781.0290	J-22S	0.039	Manual	Т
679146.6460 3082549.7640 J-25S 0.04175 Manual T 679224.5850 3082683.1400 J-26S 0.03925 Manual T 679169.0760 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082652.6750 J-28S 0.0415 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679374.4420 3082791.3300 J-30S 0.0445 Manual T 679410.1490 3082845.8460 J-31S 0.04025 Manual T 679453.4760 3082914.1150 J-32S 0.044 Manual T 679495.8840 3082940.9730 J-33S 0.0385 Manual T 679304.6530 3082548.6880 J-34S 0.06 Manual T 679382.8900 3082667.5270 J-36S 0.042 Manual T 679470.3570 3082731.6820 J-37S 0.038 Manual T 679497.3310	679297.0010	3082840.6970	J-23S	0.0375	Manual	Т
679224.5850 3082683.1400 J-26S 0.03925 Manual T 679169.0760 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082652.6750 J-28S 0.0415 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679374.4420 3082791.3300 J-30S 0.0445 Manual T 679410.1490 3082845.8460 J-31S 0.04025 Manual T 679453.4760 3082914.1150 J-32S 0.044 Manual T 679495.8840 3082940.9730 J-33S 0.0385 Manual T 679304.6530 3082548.6880 J-34S 0.04 Manual T 679342.7410 3082605.3190 J-35S 0.04 Manual T 679433.9450 3082731.6820 J-37S 0.038 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 </td <td>679394.8070</td> <td>3082971.8300</td> <td>J-24S</td> <td>0.375</td> <td>Manual</td> <td>Т</td>	679394.8070	3082971.8300	J-24S	0.375	Manual	Т
679169.0760 3082537.3510 J-27S 0.041 Manual T 679272.0040 3082652.6750 J-28S 0.0415 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679374.4420 3082791.3300 J-30S 0.0445 Manual T 679410.1490 3082845.8460 J-31S 0.04025 Manual T 679453.4760 3082914.1150 J-32S 0.044 Manual T 679495.8840 3082940.9730 J-33S 0.0385 Manual T 679304.6530 3082548.6880 J-34S 0.06 Manual T 679342.7410 3082605.3190 J-35S 0.04 Manual T 679382.8900 3082667.5270 J-36S 0.042 Manual T 679470.3570 3082731.6820 J-37S 0.038 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679560.6070 <td>679146.6460</td> <td>3082549.7640</td> <td>J-25S</td> <td>0.04175</td> <td>Manual</td> <td>Т</td>	679146.6460	3082549.7640	J-25S	0.04175	Manual	Т
679272.0040 3082652.6750 J-28S 0.0415 Manual T 679329.4380 3082711.0960 J-29S 0.039 Manual T 679374.4420 3082791.3300 J-30S 0.0445 Manual T 679410.1490 3082845.8460 J-31S 0.04025 Manual T 679453.4760 3082914.1150 J-32S 0.044 Manual T 679495.8840 3082940.9730 J-33S 0.0385 Manual T 679304.6530 3082548.6880 J-34S 0.06 Manual T 679342.7410 3082605.3190 J-35S 0.04 Manual T 679382.8900 3082667.5270 J-36S 0.042 Manual T 679470.3570 3082731.6820 J-37S 0.038 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 3082886.8990 J-40S 0.0395 Manual T 679532.9930 <td>679224.5850</td> <td>3082683.1400</td> <td>J-26S</td> <td>0.03925</td> <td>Manual</td> <td>Т</td>	679224.5850	3082683.1400	J-26S	0.03925	Manual	Т
679329.4380 3082711.0960 J-29S 0.039 Manual T 679374.4420 3082791.3300 J-30S 0.0445 Manual T 679410.1490 3082845.8460 J-31S 0.04025 Manual T 679453.4760 3082914.1150 J-32S 0.044 Manual T 679495.8840 3082940.9730 J-33S 0.0385 Manual T 679304.6530 3082548.6880 J-34S 0.06 Manual T 679342.7410 3082605.3190 J-35S 0.04 Manual T 679382.8900 3082667.5270 J-36S 0.042 Manual T 679433.9450 3082731.6820 J-37S 0.038 Manual T 679470.3570 308276.7350 J-38S 0.0375 Manual T 67959497.3310 3082840.3960 J-39S 0.0425 Manual T 679560.6070 3082887.2580 J-40S 0.0395 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T <	679169.0760	3082537.3510	J-27S	0.041	Manual	Т
679374.4420 3082791.3300 J-30S 0.0445 Manual T 679410.1490 3082845.8460 J-31S 0.04025 Manual T 679453.4760 3082914.1150 J-32S 0.044 Manual T 679495.8840 3082940.9730 J-33S 0.0385 Manual T 679304.6530 3082548.6880 J-34S 0.06 Manual T 679342.7410 3082605.3190 J-35S 0.04 Manual T 679382.8900 3082667.5270 J-36S 0.042 Manual T 679433.9450 3082731.6820 J-37S 0.038 Manual T 679470.3570 3082776.7350 J-38S 0.0375 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 3082886.8990 J-40S 0.0395 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679272.0040	3082652.6750	J-28S	0.0415	Manual	Т
679410.1490 3082845.8460 J-31S 0.04025 Manual T 679453.4760 3082914.1150 J-32S 0.044 Manual T 679495.8840 3082940.9730 J-33S 0.0385 Manual T 679304.6530 3082548.6880 J-34S 0.06 Manual T 679342.7410 3082605.3190 J-35S 0.04 Manual T 679382.8900 3082667.5270 J-36S 0.042 Manual T 679433.9450 3082731.6820 J-37S 0.038 Manual T 679470.3570 3082776.7350 J-38S 0.0375 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 3082886.8990 J-40S 0.0395 Manual T 679560.6070 3082897.2580 J-41S 0.0355 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679329.4380	3082711.0960	J-29S	0.039	Manual	Т
679453.4760 3082914.1150 J-32S 0.044 Manual T 679495.8840 3082940.9730 J-33S 0.0385 Manual T 679304.6530 3082548.6880 J-34S 0.06 Manual T 679342.7410 3082605.3190 J-35S 0.04 Manual T 679382.8900 3082667.5270 J-36S 0.042 Manual T 679433.9450 3082731.6820 J-37S 0.038 Manual T 679470.3570 3082776.7350 J-38S 0.0375 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 3082886.8990 J-40S 0.0395 Manual T 679560.6070 3082897.2580 J-41S 0.0355 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679374.4420	3082791.3300	J-30S	0.0445	Manual	Т
679495.8840 3082940.9730 J-33S 0.0385 Manual T 679304.6530 3082548.6880 J-34S 0.06 Manual T 679342.7410 3082605.3190 J-35S 0.04 Manual T 679382.8900 3082667.5270 J-36S 0.042 Manual T 679433.9450 3082731.6820 J-37S 0.038 Manual T 679470.3570 3082776.7350 J-38S 0.0375 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 3082886.8990 J-40S 0.0395 Manual T 679560.6070 3082897.2580 J-41S 0.0355 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679410.1490	3082845.8460	J-31S	0.04025	Manual	Т
679304.6530 3082548.6880 J-34S 0.06 Manual T 679342.7410 3082605.3190 J-35S 0.04 Manual T 679382.8900 3082667.5270 J-36S 0.042 Manual T 679433.9450 3082731.6820 J-37S 0.038 Manual T 679470.3570 3082776.7350 J-38S 0.0375 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 3082886.8990 J-40S 0.0395 Manual T 679560.6070 3082897.2580 J-41S 0.0355 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679453.4760	3082914.1150	J-32S	0.044	Manual	Т
679342.7410 3082605.3190 J-35S 0.04 Manual T 679382.8900 3082667.5270 J-36S 0.042 Manual T 679433.9450 3082731.6820 J-37S 0.038 Manual T 679470.3570 3082776.7350 J-38S 0.0375 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 3082886.8990 J-40S 0.0395 Manual T 679560.6070 3082897.2580 J-41S 0.0355 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679495.8840	3082940.9730	J-33S	0.0385	Manual	Т
679382.8900 3082667.5270 J-36S 0.042 Manual T 679433.9450 3082731.6820 J-37S 0.038 Manual T 679470.3570 3082776.7350 J-38S 0.0375 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 3082886.8990 J-40S 0.0395 Manual T 679560.6070 3082897.2580 J-41S 0.0355 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679304.6530	3082548.6880	J-34S	0.06	Manual	Т
679433.9450 3082731.6820 J-37S 0.038 Manual T 679470.3570 3082776.7350 J-38S 0.0375 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 3082886.8990 J-40S 0.0395 Manual T 679560.6070 3082897.2580 J-41S 0.0355 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679342.7410	3082605.3190	J-35S	0.04	Manual	Т
679470.3570 3082776.7350 J-38S 0.0375 Manual T 679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 3082886.8990 J-40S 0.0395 Manual T 679560.6070 3082897.2580 J-41S 0.0355 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679382.8900	3082667.5270	J-36S	0.042	Manual	Т
679497.3310 3082840.3960 J-39S 0.0425 Manual T 679524.3310 3082886.8990 J-40S 0.0395 Manual T 679560.6070 3082897.2580 J-41S 0.0355 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679433.9450	3082731.6820	J-37S	0.038	Manual	Т
679524.3310 3082886.8990 J-40S 0.0395 Manual T 679560.6070 3082897.2580 J-41S 0.0355 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679470.3570	3082776.7350	J-38S	0.0375	Manual	Т
679560.6070 3082897.2580 J-41S 0.0355 Manual T 679532.9930 3082835.5820 J-42SD 0.049 Manual T	679497.3310	3082840.3960	J-39S	0.0425	Manual	Т
679532.9930 3082835.5820 J-42SD 0.049 Manual T	679524.3310	3082886.8990	J-40S	0.0395	Manual	Т
0.000=10000 000=000100=0 0 1=00 010 10 110 1	679560.6070	3082897.2580	J-41S	0.0355	Manual	Т
679552.9590 3082868.6600 J-43SD 0.06 Manual T	679532.9930	3082835.5820	J-42SD	0.049	Manual	Т
	679552.9590	3082868.6600	J-43SD	0.06	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=10	n	α=	=5	α=	α=10		15	
AL=I	U	s=6	s=3	s=6	s=3	s=6	s=3	
	β=5	391	99	310	78	260	66	
LBGR=90	β=10	310	79	238	60	194	49	
	β=15	261	67	195	50	156	40	
	β=5	99	26	78	21	66	17	
LBGR=80	β=10	79	21	60	16	49	13	
	β=15	67	18	50	13	40	11	
LBGR=70	β=5	45	13	36	10	30	8	

β=10	36	10	28	8	23	6
β=15	31	9	23	7	18	5

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details Per Analysis Per Sample 21 Sample								
Field collection costs		\$100.00	\$2,100.00					
Analytical costs	\$400.00	\$400.00	\$8,400.00					
Sum of Field & Analytical costs		\$500.00	\$10,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$11,500.00					

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.0355	0.0365	0.0375	0.0375	0.038	0.038	0.038	0.0385	0.0385
10	0.0385	0.03875	0.039	0.039	0.03925	0.0395	0.0395	0.04	0.04	0.04025
20	0.0405	0.041	0.041	0.0415	0.0415	0.04175	0.042	0.042	0.0425	0.043
30	0.044	0.044	0.0445	0.049	0.06	0.06	0.1225	0.192	0.37	0.375
40	0.385	0.405	0.415	0.425	0.813					

SUMMARY STATISTICS						
n	45					
Min	0					
Max	0.813					
Range	0.813					
Mean	0.11006					
Median	0.041					
Variance	0.026624					
StdDev	0.16317					
Std Error	0.024324					
Skewness	2.6131					
Interquartile Range	0.015875					

	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.0358	0.0375	0.03863	0.041	0.0545	0.393	0.422	0.813

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST							
k Test Statistic R _k 5% Critical Value C _k Significant?								
	1	4.259	3.08	Yes				

The test statistic 4.259 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS		
1	0.813	

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)		
Shapiro-Wilk Test Statistic	0.5227	
Shapiro-Wilk 5% Critical Value	0.943	

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST		
Shapiro-Wilk Test Statistic	0.5367	
Shapiro-Wilk 5% Critical Value	0.945	

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN		
95% Parametric UCL	0.1509	
95% Non-Parametric (Chebyshev) UCL	0.2161	

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.2161) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=45 data,

AL is the action level or threshold (10),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=44 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST			
t-statistic	Critical Value t _{0.95}	Null Hypothesis	
-406.6	1.6802	Reject	

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test		
Test Statistic (S+)	95% Critical Value	Null Hypothesis
45	28	Reject

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1				
X Coord Y C	Soord Labol	Value	Tuno	Historical
679149.492	3082933.098	J-13S	Type 0.0385	Manual
679279.683	3083075.429	J-13S J-14S	0.0383	Manual
679261.098	3083075.429	J-14S J-15S	0.041	Manual
679201.098	3082840.172	J-13S J-16S	0.0393 0.04 Mar	
679293.56	3082950.498	J-17S	0.042	Manual
679360.57	3083026.498	J-18S	0.0405	Manual
679343.581	3082969.598	J-19S	0.415	Manual
679382.864	3083009.113	J-20S	0.37 Mar	
679335.002	3082941.172	J-21S	0.405	Manual
679252.713	3082781.029	J-22S	0.039	Manual
679297.001	3082840.697	J-23S	0.0375	Manual
679394.807	3082971.83	J-24S	0.375	Manual
679146.646	3082549.764	J-25S	0.04175	Manual
679224.585	3082683.14	J-26S	0.03925	Manual
679169.076	3082537.351	J-27S	0.041	Manual
679272.004	3082652.675	J-28S	0.0415	Manual
679329.438	3082711.096	J-29S	0.039	Manual
679374.442	3082791.33	J-30S	0.0445	Manual
679410.149	3082845.846	J-31S	0.04025	Manual
679453.476	3082914.115	J-32S	0.044	Manual
679495.884	3082940.973	J-33S	0.0385	Manual
679304.653	3082548.688	J-34S	0.06 Mar	
679342.741	3082605.319	J-35S	0.04 Mar	
679382.89	3082667.527	J-36S	0.042	Manual
679433.945	3082731.682	J-37S	0.038	Manual
679470.357	3082776.735	J-38S	0.0375	Manual
679497.331	3082840.396	J-39S	0.0425	Manual
679524.331	3082886.899	J-40S	0.0395	Manual
679560.607	3082897.258	J-41S	0.0355	Manual
679532.993	3082835.582	J-42SD	0.049	Manual
679552.959	3082868.66	J-43SD	0.06 Mar	nual
Area: Area 5				
X Coord Y C	Coord Label	Value	Type	Historical
679133.429	3083306.313	J-01S	0.044	Manual
679104.245	3083223.262	J-02S	0.0365	Manual
679155.074	3083294.696	J-03S	0.1225	Manual
679171.297	3083289.796	J-04S	0.425	Manual
679225.856	3083359.974	J-05S	0.0415	Manual
679164.806	3083214.71	J-06S	0.03875	Manual
679242.726	3083326.528	J-07S	0.385	Manual
679181.275	3083178.288	J-08S	0.038	Manual
679213.773	3083224.973	J-09S	0.813	Manual
679280.544	3083305.681	J-10S	0.038	Manual
679268.77	3083200.326	J-11S	0.043	Manual
679301.16	3083254.034	J-12S	0.192	Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	23
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1								
X Coord	Y Coord	Label	Value	Туре	Historical			
679133.4290	3083306.3130	TW01-01	1.4	Manual	Т			
679104.2450	3083223.2620	TW01-02	1.4	Manual	Т			
679242.7260	3083326.5280	TW01-07	1.4	Manual	Т			
679181.2750	3083178.2880	TW01-08	1.4	Manual	Т			
679268.7700	3083200.3260	TW01-11	1.4	Manual	Т			
679301.1600	3083254.0340	TW01-12	1.4	Manual	Т			
679204.3747	3083219.2557	J-42SD	3.4	Random				

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			
679532.9930	3082835.5820	J-42SD	3.4	Manual	Т			
679552.9590	3082868.6600	J-43SD	1.4	Manual	Т			
679149.4920	3082933.0980	TW01-13	1.4	Manual	Т			
679279.7760	3083075.6320	TW01-14	1.4	Manual	Т			
679293.5600	3082950.4980	TW01-17	1.4	Manual	Т			
679360.5700	3083026.4980	TW01-18	10	Manual	Т			

Т	Manual	1.4	TW01-27	3082537.3510	679169.0760
Т	Manual	1.4	TW01-33	3082940.9730	679495.8840
Т	Manual	19.5	TW01-34	3082548.6880	679304.6530
Т	Manual	1.4	TW01-35	3082605.3190	679342.7410
Т	Manual	1.4	TW01-36	3082667.5270	679382.8900
Т	Manual	8.7	TW01-37	3082731.6820	679433.9450
Т	Manual	5.7	TW01-38	3082776.7350	679470.3570
Т	Manual	7.2	TW01-39	3082840.3960	679497.3310
Т	Manual	4.4	TW01-40	3082886.8990	679524.3310
Т	Manual	1.4	TW01-41	3082897.2580	679560.6110

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .


The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter						
Analyte	11	S	Δ	α	β	$Z_{1-\alpha}$ a	Ζ_{1-β} b	
	21	3	2	0.05	0.1	1.64485	1.28155	

^a This value is automatically calculated by VSP based upon the user defined value of α.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

b This value is automatically calculated by VSP based upon the user defined value of β.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=5.	2	α=	:5	α=	10	α=15	
AL=5.	ა 	s=6 s=3		s=6 s=3		s=6	s=3
	β=5	1389	349	1099	276	922	231
LBGR=90	β=10	1099	276	843	212	690	173
	β=15	923	232	690	173	552	139
	β=5	349	89	276	70	231	59
LBGR=80	β=10	276	70	212	54	173	44
	β=15	232	59	173	44	139	35
	β=5	156	40	123	32	103	27
LBGR=70	β=10	124	32	95	25	78	20
	β=15	104	27	78	20	62	16

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	21 Samples					
Field collection costs		\$100.00	\$2,100.00					
Analytical costs	\$400.00	\$400.00	\$8,400.00					
Sum of Field & Analytical costs		\$500.00	\$10,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$11,500.00					

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	1.4	1.4	1.4	1.4	1.4	1.4	1.4	1.4	1.4
10	1.4	1.4	1.4	1.4	1.4	1.4	3.4	3.4	4.4	5.7
20	7.2	8.7	10	19.5						

SUMMARY STATISTICS

n				24					
	Min				0				
	M	ах				19.5			
	Rai	nge				19.5			
	Me	ean				3.470	8		
	Мес	dian				1.4			
	Variance			18.393					
	Std	Dev		4.2887					
	Std I	Error		0.87542					
	Skew	ness		2.6629					
Interquartile Range				2.75					
		Per	centil	es					
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0	0.35	1.4	1.4	1.4	4.15	9.35	17.13	19.5	

Outlier Test

Dixon's extreme value test was performed to test whether the lowest value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

DIXON'S OUTLIER TEST						
Dixon Test Statistic	0.16092					
Dixon 5% Critical Value	0.421					

The calculated test statistic does not exceed the critical value, so the test cannot reject the null hypothesis that there are no outliers in the data, and concludes that the minimum value 0 is not an outlier at the 5% significance level.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Dixon's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)							
Shapiro-Wilk Test Statistic	0.5897						
Shapiro-Wilk 5% Critical Value	0.911						

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the minimum value 0, do not appear to follow a normal distribution at the 5% level of significance. Dixon's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The

sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution.

The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic	0.6214				
Shapiro-Wilk 5% Critical Value	0.916				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	4.971
95% Non-Parametric (Chebyshev) UCL	7.287

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (7.287) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=24 data,

AL is the action level or threshold (5.3),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=23 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
-2.0895	1.7139	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+) 95% Critical Value Null Hypothesis							
19	16	Reject					

Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1 X Coord Y Coord Label Value Type Historical 679532.993 3082835.582 J-42SD 3.4 Manual J-43SD 1.4 Manual 679552.959 3082868.66 3082933.098 TW01-131.4 Manual 679149.492 679279.776 3083075.632 TW01-141.4 Manual 679293.56 3082950.498 TW01-171.4 Manual 3083026.498 TW01-1810 Manual 679360.57 679169.076 3082537.351 TW01-271.4 Manual 3082940.973 TW01-331.4 Manual 679495.884 3082548.688 TW01-3419.5 Manual 679304.653 679342.741 3082605.319 TW01-351.4 Manual 3082667.527 TW01-361.4 Manual 679382.89 679433.945 3082731.682 TW01-378.7 Manual 679470.357 3082776.735 TW01-385.7 Manual 679497.331 3082840.396 TW01-397.2 Manual 3082886.899 TW01-404.4 Manual 679524.331 679560.611 3082897.258 TW01-411.4 Manual

Area: Area 5

X Coord Y	Coord Label	Value	Туре	e Historical
679133.429	3083306.313	TW01-0	11.4	Manual
679104.245	3083223.262	TW01-0	21.4	Manual
679242.726	3083326.528	TW01-0	71.4	Manual
679181.275	3083178.288	TW01-0	81.4	Manual
679268.77	3083200.326	TW01-1	11.4	Manual
679301.16	3083254.034	TW01-1	21.4	Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	35
Number of samples on map ^a	42
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling ^d	\$18,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1										
X Coord	X Coord Y Coord Label Value Type									
679133.4290	3083306.3130	J-01S	1.9	Manual	Т					
679104.2450	3083223.2620	J-02S	3.8	Manual	Т					
679155.0740	3083294.6960	J-03S	2.4	Manual	Т					
679171.2970	3083289.7960	J-04S	2.3	Manual	Т					
679225.8560	3083359.9740	J-05S	2.7	Manual	Т					
679164.8060	3083214.7100	J-06S	3.2	Manual	Т					
679242.7260	3083326.5280	J-07S	4.3	Manual	Т					
679181.2750	3083178.2880	J-08S	4.1	Manual	Т					
679213.7730	3083224.9730	J-09S	1.5	Manual	Т					
679280.5440	3083305.6810	J-10S	1.7	Manual	Т					
679268.7700	3083200.3260	J-11S	2.3	Manual	Т					
679301.1600	3083254.0340	J-12S	1.3	Manual	Т					
679177.4341	3083211.9079	J-13S	2.8	Random						

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			

679149.4920 3082933.0980 J-13S 2.8 Manual 679279.6830 3083075.4290 J-14S 1.8 Manual 679261.0980 3083016.3510 J-15S 3.5 Manual 679222.6340 3082840.1720 J-16S 2.6 Manual 679293.5600 3082950.4980 J-17S 2.3 Manual 679360.5700 3083026.4980 J-18S 4.2 Manual 679343.5810 3082969.5980 J-19S 26 Manual 679382.8640 3083009.1130 J-20S 2.1 Manual	T T T T T T T
679261.0980 3083016.3510 J-15S 3.5 Manual 679222.6340 3082840.1720 J-16S 2.6 Manual 679293.5600 3082950.4980 J-17S 2.3 Manual 679360.5700 3083026.4980 J-18S 4.2 Manual 679343.5810 3082969.5980 J-19S 26 Manual 679382.8640 3083009.1130 J-20S 2.1 Manual	T T T T
679222.6340 3082840.1720 J-16S 2.6 Manual 679293.5600 3082950.4980 J-17S 2.3 Manual 679360.5700 3083026.4980 J-18S 4.2 Manual 679343.5810 3082969.5980 J-19S 26 Manual 679382.8640 3083009.1130 J-20S 2.1 Manual	T T T T
679293.5600 3082950.4980 J-17S 2.3 Manual 679360.5700 3083026.4980 J-18S 4.2 Manual 679343.5810 3082969.5980 J-19S 26 Manual 679382.8640 3083009.1130 J-20S 2.1 Manual	T T T
679360.5700 3083026.4980 J-18S 4.2 Manual 679343.5810 3082969.5980 J-19S 26 Manual 679382.8640 3083009.1130 J-20S 2.1 Manual	T T T
679343.5810 3082969.5980 J-19S 26 Manual 679382.8640 3083009.1130 J-20S 2.1 Manual	T T
679382.8640 3083009.1130 J-20S 2.1 Manual	T
	Т
	-
679335.0020 3082941.1720 J-21S 1.5 Manual	Т
679252.7130 3082781.0290 J-22S 2.5 Manual	_
679297.0010 3082840.6970 J-23S 3.6 Manual	Т
679394.8070 3082971.8300 J-24S 3.1 Manual	Т
679146.6460 3082549.7640 J-25S 4.2 Manual	Т
679224.5850 3082683.1400 J-26S 1.9 Manual	Т
679169.0760 3082537.3510 J-27S 3.2 Manual	Т
679272.0040 3082652.6750 J-28S 9.3 Manual	Т
679329.4380 3082711.0960 J-29S 2.3 Manual	Т
679374.4420 3082791.3300 J-30S 2.7 Manual	Т
679410.1490 3082845.8460 J-31S 1.7 Manual	Т
679453.4760 3082914.1150 J-32S 2.7 Manual	Т
679495.8840 3082940.9730 J-33S 5.9 Manual	Т
679304.6530 3082548.6880 J-34S 1.9 Manual	Т
679342.7410 3082605.3190 J-35S 2 Manual	Т
679382.8900 3082667.5270 J-36S 6.8 Manual	Т
679433.9450 3082731.6820 J-37S 6 Manual	Т
679470.3570 3082776.7350 J-38S 5.7 Manual	Т
679497.3310 3082840.3960 J-39S 1.6 Manual	Т
679524.3310 3082886.8990 J-40S 2.15 Manual	Т
679560.6070 3082897.2580 J-41S 6.3 Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$.

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_		Parameter							
Analyte	n	S $\Delta \alpha \beta Z_{1-\alpha} Z_{1-\beta}$								
	35	3.9102	2	0.05	0.1	1.64485	1.28155			


 $^{^{\}text{a}}$ This value is automatically calculated by VSP based upon the user defined value of α

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples										
A1 400		α=	=5	α=	:10	α=15				
AL=40	U	s=7.8204	s=3.9102	s=7.8204	s=3.9102	s=7.8204	s=3.9102			
	β=5	2	2	2	1	1	1			
LBGR=90	β=10	2	2	2	1	1	1			
	β=15	2	2	2	1	1	1			
	β=5	2	2	1	1	1	1			
LBGR=80	β=10	2	2	1	1	1	1			
	β=15	2	2	1	1	1	1			
LBGR=70	β=5	2	2	1	1	1	1			

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$18,500.00, which averages out to a per sample cost of \$528.57. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	35 Samples		
Field collection costs		\$100.00	\$3,500.00		
Analytical costs	\$400.00	\$400.00	\$14,000.00		
Sum of Field & Analytical costs		\$500.00	\$17,500.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$18,500.00		

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	1.3	1.5	1.5	1.6	1.7	1.7	1.8	1.9	1.9	1.9
10	2	2.1	2.15	2.3	2.3	2.3	2.3	2.4	2.5	2.6
20	2.7	2.7	2.7	2.8	2.8	3.1	3.2	3.2	3.5	3.6
30	3.8	4.1	4.2	4.2	4.3	5.7	5.9	6	6.3	6.8
40	9.3	26								

SUMMARY STATISTICS				
n	42			
Min	1.3			
Max	26			
Range	24.7			
Mean	3.7298			
Median	2.7			
Variance	15.29			
StdDev	3.9102			
Std Error	0.60336			
Skewness	4.7844			
Interquartile Range	2.15			

	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
1.3	1.5	1.63	1.975	2.7	4.125	6.21	8.925	26

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	5.695	3.06	Yes		

The test statistic 5.695 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS				
1	26			

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.8333				
Shapiro-Wilk 5% Critical Value	0.941				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.4909			
Shapiro-Wilk 5% Critical Value	0.942			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	4.745
95% Non-Parametric (Chebyshev) UCL	6.36

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (6.36) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=42 data,

AL is the action level or threshold (400),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=41 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic	Critical Value t _{0.95}	Null Hypothesis			
-656.77	1.6829	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+)	95% Critical Value	Null Hypothesis				
42	26	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1			
X Coord Y C		Value	Type Historical
679149.492	3082933.098	J-13S	2.8 Manual
679279.683	3083075.429	J-14S	1.8 Manual
679261.098	3083016.351	J-15S	3.5 Manual
679222.634	3082840.172	J-16S	2.6 Manual
679293.56	3082950.498	J-17S	2.3 Manual
679360.57	3083026.498	J-18S	4.2 Manual
679343.581	3082969.598	J-19S	26 Manual
679382.864	3083009.113	J-20S	2.1 Manual
679335.002	3082941.172	J-21S	1.5 Manual
679252.713	3082781.029	J-22S	2.5 Manual
679297.001	3082840.697	J-23S	3.6 Manual
679394.807	3082971.83	J-24S	3.1 Manual
679146.646	3082549.764	J-25S	4.2 Manual
679224.585	3082683.14	J-26S	1.9 Manual
679169.076	3082537.351	J-27S	3.2 Manual
679272.004	3082652.675	J-28S	9.3 Manual
679329.438	3082711.096	J-29S	2.3 Manual
679374.442	3082791.33	J-30S	2.7 Manual
679410.149	3082845.846	J-31S	1.7 Manual
679453.476	3082914.115	J-32S	2.7 Manual
679495.884	3082940.973	J-33S	5.9 Manual
679304.653	3082548.688	J-34S	1.9 Manual
679342.741	3082605.319	J-35S	2 Manual
679382.89	3082667.527	J-36S	6.8 Manual
679433.945	3082731.682	J-37S	6 Manual
679470.357	3082776.735	J-38S	5.7 Manual
679497.331	3082840.396	J-39S	1.6 Manual
679524.331	3082886.899	J-40S	2.15 Manual
679560.607	3082897.258	J-41S	6.3 Manual
Area: Area 5			
X Coord Y C	Coord Label	Value	Type Historical
679133.429	3083306.313	J-01S	1.9 Manual
679104.245	3083223.262	J-02S	3.8 Manual
679155.074	3083294.696	J-03S	2.4 Manual
679171.297	3083289.796	J-04S	2.3 Manual
679225.856	3083359.974	J-05S	2.7 Manual
679164.806	3083214.71	J-06S	3.2 Manual
679242.726	3083326.528	J-07S	4.3 Manual
679181.275	3083178.288	J-08S	4.1 Manual
679213.773	3083224.973	J-09S	1.5 Manual
679280.544	3083305.681	J-10S	1.7 Manual
679268.77	3083200.326	J-11S	2.3 Manual
670201.16	2003200.320	J-115 T-120	1.2 Manual

3083254.034 J-12S

1.3 Manual

679301.16

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	44
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1								
X Coord	Y Coord	Label	Value	Туре	Historical				
679133.4290	3083306.3130	J-01S	7	Manual	Т				
679104.2450	3083223.2620	J-02S	4.6	Manual	Т				
679155.0740	3083294.6960	J-03S	4.4	Manual	Т				
679171.2970	3083289.7960	J-04S	3.6	Manual	Т				
679225.8560	3083359.9740	J-05S	4.8	Manual	Т				
679164.8060	3083214.7100	J-06S	2.15	Manual	Т				
679242.7260	3083326.5280	J-07S	80.6	Manual	Т				
679181.2750	3083178.2880	J-08S	8.3	Manual	Т				
679213.7730	3083224.9730	J-09S	8.9	Manual	Т				
679280.5440	3083305.6810	J-10S	6.9	Manual	Т				
679268.7700	3083200.3260	J-11S	6	Manual	Т				
679301.1600	3083254.0340	J-12S	3.4	Manual	Т				

Area: Area 3							
X Coord Y Coord Label Value Type Historical							
679149.4920	3082933.0980	J-13S	2.6	Manual	Т		

679279.6830 3083075.4290 J-14S 55.8 Manual T 679261.0980 3083016.3510 J-15S 18.9 Manual T 679222.6340 3082840.1720 J-16S 9.8 Manual T 679293.5600 3082950.4980 J-18S 80.7 Manual T 679360.5700 3083026.4980 J-18S 80.7 Manual T 679343.5810 3082969.5980 J-19S 19.75 Manual T 679382.8640 3083009.1130 J-20S 17.1 Manual T 679355.0020 3082941.1720 J-21S 17.7 Manual T 679252.7130 3082840.6970 J-22S 22.45 Manual T 679297.0010 3082840.6970 J-23S 9.9 Manual T 679146.6460 3082549.7640 J-25S 2.45 Manual T 679169.0760 3082537.3510 J-27S 3.7 Manual T 679329.4380 308						
679222.6340 3082840.1720 J-16S 9.8 Manual T 679293.5600 3082950.4980 J-17S 16.1 Manual T 679360.5700 3083026.4980 J-18S 80.7 Manual T 679343.5810 3082969.5980 J-19S 19.75 Manual T 679382.8640 3083009.1130 J-20S 17.1 Manual T 679335.0020 3082941.1720 J-21S 17.7 Manual T 679252.7130 3082781.0290 J-22S 22.45 Manual T 679297.0010 3082840.6970 J-23S 9.9 Manual T 679394.8070 3082971.8300 J-24S 7.2 Manual T 679146.6460 3082549.7640 J-25S 2.45 Manual T 679169.0760 3082537.3510 J-27S 3.7 Manual T 679329.4380 3082711.0960 J-29S 12.7 Manual T 679410.1490 3082	679279.6830	3083075.4290	J-14S	55.8	Manual	Т
679293.5600 3082950.4980 J-17S 16.1 Manual T 679360.5700 3083026.4980 J-18S 80.7 Manual T 679343.5810 3082969.5980 J-19S 19.75 Manual T 679382.8640 3083009.1130 J-20S 17.1 Manual T 679335.0020 3082941.1720 J-21S 17.7 Manual T 679252.7130 3082781.0290 J-22S 22.45 Manual T 679297.0010 3082840.6970 J-23S 9.9 Manual T 679394.8070 3082971.8300 J-24S 7.2 Manual T 679146.6460 3082549.7640 J-25S 2.45 Manual T 679169.0760 3082683.1400 J-26S 2.021 Manual T 679272.0040 3082652.6750 J-28S 6.1 Manual T 679329.4380 3082711.0960 J-29S 12.7 Manual T 679453.4760 30	679261.0980	3083016.3510	J-15S	18.9	Manual	Т
679360.5700 3083026.4980 J-18S 80.7 Manual T 679343.5810 3082969.5980 J-19S 19.75 Manual T 679382.8640 3083009.1130 J-20S 17.1 Manual T 679335.0020 3082941.1720 J-21S 17.7 Manual T 679252.7130 3082781.0290 J-22S 22.45 Manual T 679297.0010 3082840.6970 J-23S 9.9 Manual T 679394.8070 3082971.8300 J-24S 7.2 Manual T 679146.6460 3082549.7640 J-25S 2.45 Manual T 679169.0760 3082683.1400 J-26S 2.021 Manual T 679272.0040 3082652.6750 J-28S 6.1 Manual T 679329.4380 3082711.0960 J-29S 12.7 Manual T 679453.4760 3082945.8460 J-31S 14.75 Manual T 679453.8840 3	679222.6340	3082840.1720	J-16S	9.8	Manual	Т
679343.5810 3082969.5980 J-19S 19.75 Manual T 679382.8640 3083009.1130 J-20S 17.1 Manual T 679335.0020 3082941.1720 J-21S 17.7 Manual T 679252.7130 3082781.0290 J-22S 22.45 Manual T 679297.0010 3082840.6970 J-23S 9.9 Manual T 679394.8070 3082971.8300 J-24S 7.2 Manual T 679146.6460 3082549.7640 J-25S 2.45 Manual T 679169.0760 3082537.3510 J-26S 2.021 Manual T 679272.0040 3082652.6750 J-28S 6.1 Manual T 679374.4420 3082791.3300 J-30S 23.8 Manual T 679410.1490 3082845.8460 J-31S 14.75 Manual T 679495.840 3082914.1150 J-32S 11.6 Manual T 679495.840 308	679293.5600	3082950.4980	J-17S	16.1	Manual	Т
679382.8640 3083009.1130 J-20S 17.1 Manual T 679335.0020 3082941.1720 J-21S 17.7 Manual T 679252.7130 3082781.0290 J-22S 22.45 Manual T 679297.0010 3082840.6970 J-23S 9.9 Manual T 679394.8070 3082971.8300 J-24S 7.2 Manual T 679146.6460 3082549.7640 J-25S 2.45 Manual T 679224.5850 3082683.1400 J-26S 2.021 Manual T 679169.0760 3082537.3510 J-27S 3.7 Manual T 679272.0040 3082652.6750 J-28S 6.1 Manual T 679374.4420 3082791.3300 J-30S 23.8 Manual T 679453.4760 3082914.1150 J-31S 14.75 Manual T 679495.8840 3082914.1150 J-32S 11.6 Manual T 679304.6530 308	679360.5700	3083026.4980	J-18S	80.7	Manual	Т
679335.0020 3082941.1720 J-21S 17.7 Manual T 679252.7130 3082781.0290 J-22S 22.45 Manual T 679297.0010 3082840.6970 J-23S 9.9 Manual T 679394.8070 3082971.8300 J-24S 7.2 Manual T 679146.6460 3082549.7640 J-25S 2.45 Manual T 679224.5850 3082683.1400 J-26S 2.021 Manual T 679272.0040 3082537.3510 J-27S 3.7 Manual T 679272.0040 3082652.6750 J-28S 6.1 Manual T 679329.4380 3082711.0960 J-29S 12.7 Manual T 679374.4420 3082791.3300 J-30S 23.8 Manual T 679410.1490 3082845.8460 J-31S 14.75 Manual T 679453.4760 3082914.1150 J-32S 11.6 Manual T 679304.6530 3082548.6880 J-34S 10.4 Manual T 679342.7410 3082605.3190 J-35S 5.1 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679433.9450 3082731.6820 J-37S 6.7 Manual T 679497.3310 3082840.3960 J-39S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679532.9930 3082886.8600 J-43SD 8.3 Manual T 679532.9930 3082885.5820 J-42SD 4 Manual T 679532.9930 3082886.6600 J-43SD 8.3 Manual T	679343.5810	3082969.5980	J-19S	19.75	Manual	Т
679252.7130 3082781.0290 J-22S 22.45 Manual T 679297.0010 3082840.6970 J-23S 9.9 Manual T 679394.8070 3082971.8300 J-24S 7.2 Manual T 679146.6460 3082549.7640 J-25S 2.45 Manual T 679224.5850 3082683.1400 J-26S 2.021 Manual T 679169.0760 3082537.3510 J-27S 3.7 Manual T 679272.0040 3082652.6750 J-28S 6.1 Manual T 679329.4380 3082711.0960 J-29S 12.7 Manual T 679374.4420 3082791.3300 J-30S 23.8 Manual T 679453.4760 3082845.8460 J-31S 14.75 Manual T 679495.8840 3082940.9730 J-33S 5.4 Manual T 679304.6530 3082548.6880 J-34S 10.4 Manual T 679382.8900 3082	679382.8640	3083009.1130	J-20S	17.1	Manual	Т
679297.0010 3082840.6970 J-23S 9.9 Manual T 679394.8070 3082971.8300 J-24S 7.2 Manual T 679146.6460 3082549.7640 J-25S 2.45 Manual T 679169.0760 3082537.3510 J-27S 3.7 Manual T 679272.0040 3082652.6750 J-28S 6.1 Manual T 679329.4380 3082711.0960 J-29S 12.7 Manual T 679374.4420 3082791.3300 J-30S 23.8 Manual T 679410.1490 3082845.8460 J-31S 14.75 Manual T 679453.4760 3082914.1150 J-32S 11.6 Manual T 679304.6530 3082940.9730 J-33S 5.4 Manual T 679342.7410 3082605.3190 J-35S 5.1 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679470.3570 308276.7350 J-38S 8 Manual T 679470.3570 3082776.7350 J-38S 8 Manual T 679497.3310 3082840.3960 J-39S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679532.9930 3082887.2580 J-41S 9.2 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679335.0020	3082941.1720	J-21S	17.7	Manual	Т
679394.8070 3082971.8300 J-24S 7.2 Manual T 679146.6460 3082549.7640 J-25S 2.45 Manual T 679169.0760 3082537.3510 J-27S 3.7 Manual T 679329.4380 3082711.0960 J-28S 6.1 Manual T 679374.4420 3082791.3300 J-30S 23.8 Manual T 679410.1490 3082845.8460 J-31S 14.75 Manual T 679453.4760 3082914.1150 J-32S 11.6 Manual T 679304.6530 3082548.6880 J-34S 10.4 Manual T 679342.7410 308265.3190 J-35S 5.1 Manual T 679342.7410 308265.3190 J-35S 5.1 Manual T 679342.7410 3082605.3190 J-35S 5.1 Manual T 679470.3570 308276.7350 J-38S 8 Manual T 679497.3310 3082840.3960 J-37S 6.7 Manual T 679524.3310 3082840.3960 J-39S 6.9 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679252.7130	3082781.0290	J-22S	22.45	Manual	Т
679146.6460 3082549.7640 J-25S 2.45 Manual T 679224.5850 3082683.1400 J-26S 2.021 Manual T 679169.0760 3082537.3510 J-27S 3.7 Manual T 679272.0040 3082652.6750 J-28S 6.1 Manual T 679374.4420 3082791.3300 J-30S 23.8 Manual T 679410.1490 3082845.8460 J-31S 14.75 Manual T 679453.4760 3082914.1150 J-32S 11.6 Manual T 679304.6530 3082940.9730 J-33S 5.4 Manual T 679342.7410 3082605.3190 J-35S 5.1 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679470.3570 308276.7350 J-38S 8 Manual T 679470.3570 308276.7350 J-38S 8 Manual T 679524.3310 3082846.8900 J-40S 20.9 Manual T 679532.9930 3082886.8990 J-40S 20.9 Manual T 679532.9930 3082835.5820 J-41S 9.2 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679297.0010	3082840.6970	J-23S	9.9	Manual	Т
679224.5850 3082683.1400 J-26S 2.021 Manual T 679169.0760 3082537.3510 J-27S 3.7 Manual T 679329.4380 3082711.0960 J-29S 12.7 Manual T 679410.1490 3082845.8460 J-31S 14.75 Manual T 679453.4760 3082914.1150 J-32S 11.6 Manual T 679304.6530 3082548.6880 J-34S 10.4 Manual T 679342.7410 3082652.3190 J-35S 5.1 Manual T 679342.7410 3082667.5270 J-36S 18.8 Manual T 679470.3570 308276.7350 J-38S 8 Manual T 679497.3310 3082846.8900 J-37S 6.7 Manual T 679497.3310 3082860.3190 J-36S 18.8 Manual T 679470.3570 3082776.7350 J-38S 8 Manual T 679552.3310 3082886.8990 J-40S 20.9 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679394.8070	3082971.8300	J-24S	7.2	Manual	Т
679169.0760 3082537.3510 J-27S 3.7 Manual T 679372.0040 3082652.6750 J-28S 6.1 Manual T 679374.4420 3082791.3300 J-30S 23.8 Manual T 679410.1490 3082845.8460 J-31S 14.75 Manual T 679453.4760 3082914.1150 J-32S 11.6 Manual T 679495.8840 3082940.9730 J-33S 5.4 Manual T 679304.6530 3082548.6880 J-34S 10.4 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679470.3570 3082776.7350 J-38S 8 Manual T 679497.3310 3082840.3960 J-39S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679532.9930 3082868.6600 J-43SD 8.3 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679146.6460	3082549.7640	J-25S	2.45	Manual	Т
679272.0040 3082652.6750 J-28S 6.1 Manual T 679329.4380 3082711.0960 J-29S 12.7 Manual T 679374.4420 3082791.3300 J-30S 23.8 Manual T 679410.1490 3082845.8460 J-31S 14.75 Manual T 679453.4760 3082914.1150 J-32S 11.6 Manual T 679495.8840 3082940.9730 J-33S 5.4 Manual T 679304.6530 3082548.6880 J-34S 10.4 Manual T 679342.7410 3082605.3190 J-35S 5.1 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679470.3570 308276.7350 J-38S 8 Manual T 679524.3310 3082840.3960 J-39S 6.9 Manual T 679560.6070 3082897.2580 J-41S 9.2 Manual T 679552.9590 3082868.66	679224.5850	3082683.1400	J-26S	2.021	Manual	Т
679329.4380 3082711.0960 J-29S 12.7 Manual T 679374.4420 3082791.3300 J-30S 23.8 Manual T 679410.1490 3082845.8460 J-31S 14.75 Manual T 679453.4760 3082914.1150 J-32S 11.6 Manual T 679495.8840 3082940.9730 J-33S 5.4 Manual T 679304.6530 3082548.6880 J-34S 10.4 Manual T 679342.7410 3082605.3190 J-35S 5.1 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679470.3570 3082776.7350 J-38S 8 Manual T 679497.3310 3082840.3960 J-39S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679532.9930 3082835.5820 J-41S 9.2 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679169.0760	3082537.3510	J-27S	3.7	Manual	Т
679374.4420 3082791.3300 J-30S 23.8 Manual T 679410.1490 3082845.8460 J-31S 14.75 Manual T 679453.4760 3082914.1150 J-32S 11.6 Manual T 679495.8840 3082940.9730 J-33S 5.4 Manual T 679304.6530 3082548.6880 J-34S 10.4 Manual T 679342.7410 3082605.3190 J-35S 5.1 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679433.9450 3082731.6820 J-37S 6.7 Manual T 679470.3570 3082776.7350 J-38S 8 Manual T 679497.3310 3082840.3960 J-39S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679532.9930 3082835.5820 J-41S 9.2 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679272.0040	3082652.6750	J-28S	6.1	Manual	Т
679410.1490 3082845.8460 J-31S 14.75 Manual T 679453.4760 3082914.1150 J-32S 11.6 Manual T 679495.8840 3082940.9730 J-33S 5.4 Manual T 679304.6530 3082548.6880 J-34S 10.4 Manual T 679342.7410 3082605.3190 J-35S 5.1 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679470.3570 3082731.6820 J-37S 6.7 Manual T 679497.3310 3082840.3960 J-38S 8 Manual T 679524.3310 3082840.3960 J-39S 6.9 Manual T 679560.6070 3082897.2580 J-40S 20.9 Manual T 679532.9930 3082868.6600 J-43SD 8.3 Manual T	679329.4380	3082711.0960	J-29S	12.7	Manual	Т
679453.4760 3082914.1150 J-32S 11.6 Manual T 679495.8840 3082940.9730 J-33S 5.4 Manual T 679304.6530 3082548.6880 J-34S 10.4 Manual T 679342.7410 3082605.3190 J-35S 5.1 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679433.9450 3082731.6820 J-37S 6.7 Manual T 679470.3570 3082776.7350 J-38S 8 Manual T 679497.3310 3082840.3960 J-37S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679560.6070 3082897.2580 J-41S 9.2 Manual T 679532.9930 3082835.5820 J-42SD 4 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679374.4420	3082791.3300	J-30S	23.8	Manual	Т
679495.8840 3082940.9730 J-33S 5.4 Manual T 679304.6530 3082548.6880 J-34S 10.4 Manual T 679342.7410 3082605.3190 J-35S 5.1 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679470.3570 3082731.6820 J-37S 6.7 Manual T 679470.3570 3082776.7350 J-38S 8 Manual T 679497.3310 3082840.3960 J-39S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679560.6070 3082897.2580 J-41S 9.2 Manual T 679532.9930 3082868.6600 J-43SD 4 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679410.1490	3082845.8460	J-31S	14.75	Manual	Т
679304.6530 3082548.6880 J-34S 10.4 Manual T 679342.7410 3082605.3190 J-35S 5.1 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679470.3570 3082731.6820 J-37S 6.7 Manual T 679497.3310 3082840.3960 J-38S 8 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679560.6070 3082897.2580 J-41S 9.2 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679453.4760	3082914.1150	J-32S	11.6	Manual	Т
679342.7410 3082605.3190 J-35S 5.1 Manual T 679382.8900 3082667.5270 J-36S 18.8 Manual T 679433.9450 3082731.6820 J-37S 6.7 Manual T 679470.3570 3082776.7350 J-38S 8 Manual T 679497.3310 3082840.3960 J-39S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679560.6070 3082897.2580 J-41S 9.2 Manual T 679532.9930 3082835.5820 J-42SD 4 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679495.8840	3082940.9730	J-33S	5.4	Manual	Т
679382.8900 3082667.5270 J-36S 18.8 Manual T 679433.9450 3082731.6820 J-37S 6.7 Manual T 679470.3570 3082776.7350 J-38S 8 Manual T 679497.3310 3082840.3960 J-39S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679560.6070 3082897.2580 J-41S 9.2 Manual T 679532.9930 3082835.5820 J-42SD 4 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679304.6530	3082548.6880	J-34S	10.4	Manual	Т
679433.9450 3082731.6820 J-37S 6.7 Manual T 679470.3570 3082776.7350 J-38S 8 Manual T 679497.3310 3082840.3960 J-39S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679560.6070 3082897.2580 J-41S 9.2 Manual T 679532.9930 3082835.5820 J-42SD 4 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679342.7410	3082605.3190	J-35S	5.1	Manual	Т
679470.3570 3082776.7350 J-38S 8 Manual T 679497.3310 3082840.3960 J-39S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679560.6070 3082897.2580 J-41S 9.2 Manual T 679532.9930 3082835.5820 J-42SD 4 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679382.8900	3082667.5270	J-36S	18.8	Manual	Т
679497.3310 3082840.3960 J-39S 6.9 Manual T 679524.3310 3082886.8990 J-40S 20.9 Manual T 679560.6070 3082897.2580 J-41S 9.2 Manual T 679532.9930 3082835.5820 J-42SD 4 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679433.9450	3082731.6820	J-37S	6.7	Manual	Т
679524.3310 3082886.8990 J-40S 20.9 Manual T 679560.6070 3082897.2580 J-41S 9.2 Manual T 679532.9930 3082835.5820 J-42SD 4 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679470.3570	3082776.7350	J-38S	8	Manual	Т
679560.6070 3082897.2580 J-41S 9.2 Manual T 679532.9930 3082835.5820 J-42SD 4 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679497.3310	3082840.3960	J-39S	6.9	Manual	Т
679532.9930 3082835.5820 J-42SD 4 Manual T 679552.9590 3082868.6600 J-43SD 8.3 Manual T	679524.3310	3082886.8990	J-40S	20.9	Manual	Т
679552.9590 3082868.6600 J-43SD 8.3 Manual T	679560.6070	3082897.2580	J-41S	9.2	Manual	Т
0.000=10000 000=0010000 0 1000 010 11001100	679532.9930	3082835.5820	J-42SD	4	Manual	Т
679423.8261 3082715.5057 0 Random	679552.9590	3082868.6600	J-43SD	8.3	Manual	Т
	679423.8261	3082715.5057		0	Random	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=10	n	α=	=5	α=	10	α=	15
AL=I	U	s=6	s=3	s=6	s=3	s=6	s=3
	β=5	391	99	310	78	260	66
LBGR=90	β=10	310	79	238	60	194	49
	β=15	261	67	195	50	156	40
	β=5	99	26	78	21	66	17
LBGR=80	β=10	79	21	60	16	49	13
	β=15	67	18	50	13	40	11
LBGR=70	β=5	45	13	36	10	30	8

β=10	36	10	28	8	23	6
β=15	31	9	23	7	18	5

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Sample	21 Samples						
Field collection costs		\$100.00	\$2,100.00					
Analytical costs	\$400.00	\$400.00	\$8,400.00					
Sum of Field & Analytical costs		\$500.00	\$10,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$11,500.00					

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	2.021	2.15	2.45	2.6	2.6	3.4	3.6	3.7	4
10	4.4	4.6	4.8	5.1	5.4	6	6.1	6.7	6.9	6.9
20	7	7.2	8	8.3	8.3	8.9	9.2	9.8	9.9	10.4
30	11.6	12.7	14.75	16.1	17.1	17.7	18.8	18.9	19.75	20.9
40	22.45	23.8	55.8	80.6	80.7					

SUMMARY STATISTICS					
n	45				
Min	0				
Max	80.7				
Range	80.7				
Mean	13.379				
Median	8				
Variance	300.83				
StdDev	17.345				
Std Error	2.5856				
Skewness	3.052				
Interquartile Range	12.1				

	Percentiles								
1% 5% 10% 25% 50% 75% 9						90%	95%	99%	
0	2.06	2.54	4.5	8	16.6	22.99	73.16	80.7	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST								
k	Test Statistic R _k	5% Critical Value C _k	Significant?					
1	3.846	3.08	Yes					

The test statistic 3.846 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	80.7

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION T	EST (excluding outliers)
Shapiro-Wilk Test Statistic	0.6126
Shapiro-Wilk 5% Critical Value	0.943

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.5955			
Shapiro-Wilk 5% Critical Value	0.945			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	17.72
95% Non-Parametric (Chebyshev) UCL	24.65

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (24.65) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=45 data,

AL is the action level or threshold (10),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=44 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesi					
1.307	1.6802	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothesis						
29	28	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

```
Area: Area 1
X Coord Y Coord Label
                          Value
                                   Type
                                            Historical
679149.492
             3082933.098 J-13S
                                   2.6 Manual
679279.683
             3083075.429 J-14S
                                   55.8 Manual
679261.098
             3083016.351 J-15S
                                   18.9 Manual
679222.634
             3082840.172 J-16S
                                   9.8 Manual
679293.56
             3082950.498 J-17S
                                   16.1 Manual
679360.57
             3083026.498 J-18S
                                   80.7 Manual
679343.581
             3082969.598 J-19S
                                   19.75
                                            Manual
             3083009.113 J-20S
                                   17.1 Manual
679382.864
679335.002
             3082941.172 J-21S
                                   17.7 Manual
679252.713
             3082781.029 J-22S
                                   22.45
                                            Manual
679297.001
             3082840.697 J-23S
                                   9.9 Manual
679394.807
             3082971.83
                          J-24S
                                   7.2 Manual
             3082549.764 J-25S
                                   2.45 Manual
679146.646
679224.585
             3082683.14
                          J-26S
                                   2.021
                                           Manual
679169.076
             3082537.351 J-27S
                                   3.7 Manual
679272.004
             3082652.675 J-28S
                                   6.1 Manual
679329.438
             3082711.096 J-29S
                                   12.7 Manual
679374.442
             3082791.33
                          J-30S
                                   23.8 Manual
679410.149
             3082845.846 J-31S
                                   14.75
                                            Manual
679453.476
             3082914.115 J-32S
                                   11.6 Manual
679495.884
             3082940.973 J-33S
                                   5.4 Manual
679304.653
             3082548.688 J-34S
                                   10.4 Manual
679342.741
             3082605.319 J-35S
                                   5.1 Manual
679382.89
             3082667.527 J-36S
                                   18.8 Manual
679433.945
             3082731.682 J-37S
                                   6.7 Manual
679470.357
             3082776.735 J-38S
                                       Manual
             3082840.396 J-39S
679497.331
                                   6.9 Manual
                                   20.9 Manual
679524.331
             3082886.899 J-40S
679560.607
             3082897.258 J-41S
                                   9.2 Manual
679532.993
             3082835.582 J-42SD
                                   4
                                       Manual
679552.959
                          J-43SD
                                   8.3 Manual
             3082868.66
Area: Area 5
X Coord Y Coord Label
                          Value
                                   Type
                                            Historical
679133.429
             3083306.313 J-01S
                                   7
                                       Manual
679104.245
             3083223.262 J-02S
                                   4.6 Manual
679155.074
             3083294.696 J-03S
                                   4.4 Manual
679171.297
             3083289.796 J-04S
                                   3.6 Manual
679225.856
             3083359.974 J-05S
                                   4.8 Manual
679164.806
             3083214.71
                          J-06S
                                   2.15 Manual
679242.726
             3083326.528 J-07S
                                   80.6 Manual
679181.275
             3083178.288 J-08S
                                   8.3 Manual
679213.773
             3083224.973 J-09S
                                   8.9 Manual
679280.544
             3083305.681 J-10S
                                   6.9 Manual
679268.77
             3083200.326 J-11S
                                   6
                                       Manual
```

3083254.034 J-12S

3.4 Manual

679301.16

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	23
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical				
679133.4290	3083306.3130	TW01-01	139	Manual	Т				
679104.2450	3083223.2620	TW01-02	170	Manual	Т				
679242.7260	3083326.5280	TW01-07	111	Manual	Т				
679181.2750	3083178.2880	TW01-08	110	Manual	Т				
679268.7700	3083200.3260	TW01-11	324	Manual	Т				
679301.1600	3083254.0340	TW01-12	146	Manual	Т				
679178.6073	3083375.3828	J-42SD	8.2	Random					

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			
679532.9930	3082835.5820	J-42SD	8.2	Manual	Т			
679552.9590	3082868.6600	J-43SD	11	Manual	Т			
679149.4920	3082933.0980	TW01-13	394	Manual	Т			
679279.7760	3083075.6320	TW01-14	276	Manual	Т			
679293.5600	3082950.4980	TW01-17	452.5	Manual	Т			
679360.5700	3083026.4980	TW01-18	118	Manual	Т			

679169.0760	3082537.3510	TW01-27	352.5	Manual T
679495.8840	3082940.9730	TW01-33	2150	Manual T
679304.6530	3082548.6880	TW01-34	4120	Manual T
679342.7410	3082605.3190	TW01-35	826	Manual T
679382.8900	3082667.5270	TW01-36	2140	Manual T
679433.9450	3082731.6820	TW01-37	994	Manual T
679470.3570	3082776.7350	TW01-38	746	Manual T
679497.3310	3082840.3960	TW01-39	968	Manual T
679524.3310	3082886.8990	TW01-40	776	Manual T
679560.6110	3082897.2580	TW01-41	1010	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,S is the estimated standard

is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .


The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter							
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b		
	21	3	2	0.05	0.1	1.64485	1.28155		

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

b This value is automatically calculated by VSP based upon the user defined value of β.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=1148.8		α:	=5	α=10		α=15	
		s=6	s=3	s=6	s=3	s=6	s=3
	β=5	2	2	1	1	1	1
LBGR=90	β=10	2	2	1	1	1	1
	β=15	2	2	1	1	1	1
	β=5	2	2	1	1	1	1
LBGR=80	β=10	2	2	1	1	1	1
	β=15	2	2	1	1	1	1
LBGR=70	β=5	2	2	1	1	1	1
	β=10	2	2	1	1	1	1
	β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION										
Cost Details	Per Analysis	Per Sample	21 Samples							
Field collection costs		\$100.00	\$2,100.00							
Analytical costs	\$400.00	\$400.00	\$8,400.00							
Sum of Field & Analytical costs		\$500.00	\$10,500.00							
Fixed planning and validation costs			\$1,000.00							
Total cost			\$11,500.00							

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	8.2	8.2	11	110	111	118	139	146	170
10	276	324	352.5	394	452.5	746	776	826	968	994
20	1010	2140	2150	4120						

SUMMARY STATISTICS

n				24				
	Min				0			
	М	ах				4120		
	Ra	nge				4120		
	Ме	an			6	81.27		
	Ме	dian			3	38.25		
	Vari	ance		8.9553e+005				
	Std	Dev		946.32				
	Std	Error		193.17				
	Skev	ness		2.4974				
Inte	erquar	tile Ra	nge	819.75				
Pe				rcentil	es			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	2.05	8.2	112.8	338.3	932.5	2145	3628	4120

Outlier Test

Dixon's extreme value test was performed to test whether the lowest value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

DIXON'S OUTLIER TEST				
Dixon Test Statistic	0.0051402			
Dixon 5% Critical Value	0.421			

The calculated test statistic does not exceed the critical value, so the test cannot reject the null hypothesis that there are no outliers in the data, and concludes that the minimum value 0 is not an outlier at the 5% significance level.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Dixon's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Shapiro-Wilk Test Statistic	0.7045			
Shapiro-Wilk 5% Critical Value	0.911			

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the minimum value 0, do not appear to follow a normal distribution at the 5% level of significance. Dixon's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The

sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution.

The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.6935			
Shapiro-Wilk 5% Critical Value	0.916			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	1012			
95% Non-Parametric (Chebyshev) UCL	1523			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (1523) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=24 data,

AL is the action level or threshold (1148.8),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=23 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic	Critical Value t _{0.95}	Null Hypothesis		
-2.4204	1.7139	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+)	95% Critical Value	Null Hypothesis		
21	16	Reject		

Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1 X Coord Y Coord Label Value Type Historical 3082835.582 J-42SD 8.2 Manual 679532.993 679552.959 3082868.66 J-43SD 11 Manual 679149.492 3082933.098 TW01-13394 Manual 3083075.632 TW01-14276 Manual 679279.776 679293.56 3082950.498 TW01-17452.5 Manual 3083026.498 TW01-18118 Manual 679360.57 679169.076 3082537.351 TW01-27352.5 Manual 3082940.973 TW01-332150 679495.884 Manual 3082548.688 TW01-344120 Manual 679304.653 3082605.319 TW01-35826 Manual 679342.741 3082667.527 TW01-362140 Manual 679382.89 679433.945 3082731.682 TW01-37994 Manual 3082776.735 TW01-38746 Manual 679470.357 679497.331 3082840.396 TW01-39968 Manual 3082886.899 TW01-40776 Manual 679524.331 679560.611 3082897.258 TW01-411010 Manual

Area: Area 5

X Coord Y C	Coord Label	Value	Type	Historical
679133.429	3083306.313	TW01-0	1139 M a	ınual
679104.245	3083223.262	TW01-0	2170 Ma	ınual
679242.726	3083326.528	TW01-0	7111 Ma	ınual
679181.275	3083178.288	TW01-0	8110 M a	ınual
679268.77	3083200.326	TW01-1	1324 Ma	ınual
679301.16	3083254.034	TW01-1	2 146 Ma	nual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	2
Number of samples on map ^a	42
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling ^d	\$2,000.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679133.4290	3083306.3130	J-01S	0.055	Manual	Т	
679104.2450	3083223.2620	J-02S	0.019	Manual	Т	
679155.0740	3083294.6960	J-03S	0.0051	Manual	Т	
679171.2970	3083289.7960	J-04S	0.00043	Manual	Т	
679225.8560	3083359.9740	J-05S	0.0021	Manual	Т	
679164.8060	3083214.7100	J-06S	0.033	Manual	Т	
679242.7260	3083326.5280	J-07S	0.012	Manual	Т	
679181.2750	3083178.2880	J-08S	0.048	Manual	Т	
679213.7730	3083224.9730	J-09S	0.00036	Manual	Т	
679280.5440	3083305.6810	J-10S	0.00038	Manual	Т	
679268.7700	3083200.3260	J-11S	0.0017	Manual	Т	
679301.1600	3083254.0340	J-12S	0.59	Manual	Т	
679166.5462	3083359.9694	J-13S	0.0073	Random		

Area: Area 3					
X Coord	Y Coord	Label	Value	Туре	Historical

679149.4920	3082933.0980	J-13S	0.0073	Manual	Т
679279.6830	3083075.4290	J-14S	0.00038	Manual	Т
679261.0980	3083016.3510	J-15S	0.013	Manual	Т
679222.6340	3082840.1720	J-16S	0.0025	Manual	Т
679293.5600	3082950.4980	J-17S	0.055	Manual	Т
679360.5700	3083026.4980	J-18S	0.0048	Manual	Т
679343.5810	3082969.5980	J-19S	0.0065	Manual	Т
679382.8640	3083009.1130	J-20S	0.00044	Manual	Т
679335.0020	3082941.1720	J-21S	0.00038	Manual	Т
679252.7130	3082781.0290	J-22S	0.0045	Manual	Т
679297.0010	3082840.6970	J-23S	0.0077	Manual	Т
679394.8070	3082971.8300	J-24S	0.012	Manual	Т
679146.6460	3082549.7640	J-25S	0.01	Manual	Т
679224.5850	3082683.1400	J-26S	0.011	Manual	Т
679169.0760	3082537.3510	J-27S	0.0072	Manual	Т
679272.0040	3082652.6750	J-28S	0.054	Manual	Т
679329.4380	3082711.0960	J-29S	0.0024	Manual	Т
679374.4420	3082791.3300	J-30S	0.0043	Manual	Т
679410.1490	3082845.8460	J-31S	0.0026	Manual	Т
679453.4760	3082914.1150	J-32S	0.000365	Manual	Т
679495.8840	3082940.9730	J-33S	0.0048	Manual	Т
679304.6530	3082548.6880	J-34S	0.000385	Manual	Т
679342.7410	3082605.3190	J-35S	0.0038	Manual	Т
679382.8900	3082667.5270	J-36S	0.008	Manual	Т
679433.9450	3082731.6820	J-37S	0.00035	Manual	Т
679470.3570	3082776.7350	J-38S	0.0013	Manual	Т
679497.3310	3082840.3960	J-39S	0.014	Manual	Т
679524.3310	3082886.8990	J-40S	0.0046	Manual	Т
679560.6070	3082897.2580	J-41S	0.0053	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is $1-\beta$.

The values of these inputs that result in the calculated number of sampling locations are:

Analyte	_			Para	ame	ter	
	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	2	0.090701	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

^b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=2.1		α=5		α=	:10	α=15		
		s=0.181402	s=0.090701	s=0.181402	s=0.090701	s=0.181402	s=0.090701	
	β=5	10	4	8	3	6	2	
LBGR=90	β=10	8	3	6	3	5	2	
	β=15	7	3	5	2	4	2	
	β=5	4	2	3	2	2	1	
LBGR=80	β=10	3	2	3	2	2	1	
	β=15	3	2	2	2	2	1	
LBGR=70	β=5	3	2	2	1	2	1	

β=10	3	2	2	1	1	1
β=15	2	2	2	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION							
Cost Details	Per Analysis	Per Sample	2 Samples				
Field collection costs		\$100.00	\$200.00				
Analytical costs	\$400.00	\$400.00	\$800.00				
Sum of Field & Analytical costs		\$500.00	\$1,000.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$2,000.00				

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0.00035	0.00036	0.000365	0.00038	0.00038	0.00038	0.000385	0.00043	0.00044	0.0013
10	0.0017	0.0021	0.0024	0.0025	0.0026	0.0038	0.0043	0.0045	0.0046	0.0048
20	0.0048	0.0051	0.0053	0.0065	0.0072	0.0073	0.0073	0.0077	0.008	0.01
30	0.011	0.012	0.012	0.013	0.014	0.019	0.033	0.048	0.054	0.055
40	0.055	0.59								

SUMMARY STATISTICS			
n	42		
Min	0.00035		
Max	0.59		
Range	0.58965		
Mean	0.024364		
Median	0.00495		
Variance	0.0082266		
StdDev	0.090701		
Std Error	0.013995		
Skewness	6.2046		
Interquartile Range	0.0104		

Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.00035	0.0003608	0.00038	0.0016	0.00495	0.012	0.0522	0.055	0.59

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST						
k	Test Statistic R _k	5% Critical Value C _k	Significant?			
1	6.236	3.06	Yes			

The test statistic 6.236 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	0.59

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.6339				
Shapiro-Wilk 5% Critical Value	0.941				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic	0.2569				
Shapiro-Wilk 5% Critical Value	0.942				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.04792
95% Non-Parametric (Chebyshev) UCL	0.08537

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.08537) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=42 data,

AL is the action level or threshold (2.1),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=41 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic	Critical Value t _{0.95}	Null Hypothesis					
-148.31	1.6829	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test								
Test Statistic (S+)	95% Critical Value	Null Hypothesis						
42	26	Reject						

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1				
X Coord Y C	loord Lobal	Value	Type	Historical
679149.492	3082933.098	J-13S	Type 0.0073	Manual
679279.683	3083075.429	J-14S	0.00038	Manual
679261.098	3083016.351	J-15S	0.013	Manual
679222.634	3082840.172	J-16S	0.0025	Manual
679293.56	3082950.498	J-17S	0.055	Manual
679360.57	3083026.498	J-18S	0.0048	Manual
679343.581	3082969.598	J-19S	0.0065	Manual
679382.864	3083009.113	J-20S	0.00044	Manual
679335.002	3082941.172	J-21S	0.00038	Manual
679252.713	3082781.029	J-22S	0.0045	Manual
679297.001	3082840.697	J-23S	0.0077	Manual
679394.807	3082971.83	J-24S	0.012	Manual
679146.646	3082549.764	J-25S	0.01 Man	ual
679224.585	3082683.14	J-26S	0.011	Manual
679169.076	3082537.351	J-27S	0.0072	Manual
679272.004	3082652.675	J-28S	0.054	Manual
679329.438	3082711.096	J-29S	0.0024	Manual
679374.442	3082791.33	J-30S	0.0043	Manual
679410.149	3082845.846	J-31S	0.0026	Manual
679453.476	3082914.115	J-32S	0.000365	
679495.884	3082940.973	J-33S	0.0048	Manual
679304.653	3082548.688	J-34S	0.000385	
679342.741	3082605.319	J-35S	0.0038	Manual
679382.89	3082667.527	J-36S	0.0038	Manual
679433.945	3082731.682	J-30S J-37S	0.00035	Manual
679470.357	3082776.735	J-37S J-38S	0.00033	Manual
679497.331	3082840.396	J-36S J-39S	0.0013	Manual
679524.331	3082886.899	J-40S	0.0046	Manual
679560.607	3082897.258	J-41S	0.0053	Manual
Area: Area 5				
X Coord Y C	Coord Label	Value	Type	Historical
679133.429	3083306.313	J-01S	0.055	Manual
679104.245	3083223.262	J-02S	0.019	Manual
679155.074	3083294.696	J-03S	0.0051	Manual
679171.297	3083289.796	J-04S	0.00043	Manual
679225.856	3083359.974	J-05S	0.00043	Manual
679164.806	3083214.71	J-05S	0.0021	Manual
679242.726	3083326.528	J-00S J-07S	0.033	Manual
679181.275				
	3083178.288	J-08S	0.048	Manual Manual
679213.773	3083224.973	J-09S	0.00036	Manual
679280.544	3083305.681	J-10S	0.00038	Manual
679268.77	3083200.326	J-11S	0.0017	Manual
679301.16	3083254.034	J-12S	0.59 Man	lual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN								
Primary Objective of Design	Compare a site mean to a fixed threshold							
Type of Sampling Design	Parametric							
Sample Placement (Location) in the Field	Simple random sampling							
Working (Null) Hypothesis	The mean value at the site exceeds the threshold							
Formula for calculating number of sampling locations	Student's t-test							
Calculated total number of samples	21							
Number of samples on map ^a	44							
Number of selected sample areas b	2							
Specified sampling area ^c	188054.34 m ²							
Total cost of sampling d	\$11,500.00							

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1											
X Coord	Y Coord	Label	Value	Туре	Historical							
679133.4290	3083306.3130	J-01S	0.0083	Manual	Т							
679104.2450	3083223.2620	J-02S	0.0069	Manual	Т							
679155.0740	3083294.6960	J-03S	0.0096	Manual	Т							
679171.2970	3083289.7960	J-04S	0.007	Manual	Т							
679225.8560	3083359.9740	J-05S	0.0014	Manual	Т							
679164.8060	3083214.7100	J-06S	0.00535	Manual	Т							
679242.7260	3083326.5280	J-07S	0.74	Manual	Т							
679181.2750	3083178.2880	J-08S	0.0014	Manual	Т							
679213.7730	3083224.9730	J-09S	0.013	Manual	Т							
679280.5440	3083305.6810	J-10S	0.0047	Manual	Т							
679268.7700	3083200.3260	J-11S	0.0037	Manual	Т							
679301.1600	3083254.0340	J-12S	0.0065	Manual	Т							
679220.2467	3083287.1150	J-13S	0.000385	Random								

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			

679149.4920 3082933.0980 J-13S 0.000385 Manual T 679279.6830 3083075.4290 J-14S 0.0054 Manual T 679261.0980 3083016.3510 J-15S 0.011 Manual T 679293.5600 3082840.1720 J-16S 0.034 Manual T 679360.5700 3083026.4980 J-17S 0.024 Manual T 679343.5810 3082969.5980 J-19S 0.049 Manual T 679382.8640 3083009.1130 J-20S 0.013 Manual T 679335.0020 3082941.1720 J-21S 0.016 Manual T 679297.0010 3082841.0290 J-22S 0.034 Manual T 679394.8070 3082971.8300 J-24S 0.026 Manual T 679146.6460 3082549.7640 J-25S 0.0073 Manual T 679169.0760 3082537.3510 J-27S 0.016 Manual T 679329.4380 <th></th> <th></th> <th></th> <th></th> <th></th>					
679261.0980 3083016.3510 J-15S 0.011 Manual T 679222.6340 3082840.1720 J-16S 0.034 Manual T 679293.5600 3082950.4980 J-17S 0.024 Manual T 679360.5700 3083026.4980 J-18S 0.0088 Manual T 679382.8640 3083009.1130 J-20S 0.013 Manual T 679335.0020 3082941.1720 J-21S 0.016 Manual T 679252.7130 3082781.0290 J-22S 0.034 Manual T 679297.0010 3082840.6970 J-23S 0.012 Manual T 679394.8070 3082971.8300 J-24S 0.026 Manual T 679146.6460 3082549.7640 J-25S 0.0095 Manual T 679272.0040 3082652.6750 J-28S 0.0073 Manual T 679329.4380 3082711.0960 J-29S 0.014 Manual T 679453.4760	679149.4920	3082933.0980	J-13S	0.000385	Manual T
679222.6340 3082840.1720 J-16S 0.034 Manual T 679293.5600 3082950.4980 J-17S 0.024 Manual T 679360.5700 3083026.4980 J-18S 0.0088 Manual T 679343.5810 3082969.5980 J-19S 0.049 Manual T 679382.8640 3083009.1130 J-20S 0.013 Manual T 679335.0020 3082941.1720 J-21S 0.016 Manual T 679252.7130 3082781.0290 J-22S 0.034 Manual T 679297.0010 3082840.6970 J-23S 0.012 Manual T 679394.8070 3082971.8300 J-24S 0.026 Manual T 679146.6460 3082549.7640 J-25S 0.0095 Manual T 679169.0760 3082537.3510 J-27S 0.016 Manual T 679329.4380 3082711.0960 J-29S 0.014 Manual T 679453.4760	679279.6830	3083075.4290	J-14S	0.0054	Manual T
679293.5600 3082950.4980 J-17S 0.024 Manual T 679360.5700 3083026.4980 J-18S 0.0088 Manual T 679343.5810 3082969.5980 J-19S 0.049 Manual T 679382.8640 3083009.1130 J-20S 0.013 Manual T 679335.0020 3082941.1720 J-21S 0.016 Manual T 679252.7130 3082781.0290 J-22S 0.034 Manual T 679297.0010 3082840.6970 J-23S 0.012 Manual T 679394.8070 3082971.8300 J-24S 0.026 Manual T 679146.6460 3082549.7640 J-25S 0.0095 Manual T 679169.0760 3082537.3510 J-27S 0.016 Manual T 679272.0040 3082652.6750 J-28S 0.0093 Manual T 6793410.1490 3082845.8460 J-31S 0.0215 Manual T 679453.4760 <td>679261.0980</td> <td>3083016.3510</td> <td>J-15S</td> <td>0.011</td> <td>Manual T</td>	679261.0980	3083016.3510	J-15S	0.011	Manual T
679360.5700 3083026.4980 J-18S 0.0088 Manual T 679343.5810 3082969.5980 J-19S 0.049 Manual T 679382.8640 3083009.1130 J-20S 0.013 Manual T 679335.0020 3082941.1720 J-21S 0.016 Manual T 679252.7130 3082781.0290 J-22S 0.034 Manual T 679297.0010 3082840.6970 J-23S 0.012 Manual T 679394.8070 3082971.8300 J-24S 0.026 Manual T 679146.6460 3082549.7640 J-25S 0.0095 Manual T 679169.0760 3082537.3510 J-27S 0.016 Manual T 679272.0040 3082652.6750 J-28S 0.0093 Manual T 679374.4420 3082791.3300 J-30S 0.024 Manual T 679453.4760 3082914.1150 J-32S 0.007 Manual T 679342.7410	679222.6340	3082840.1720	J-16S	0.034	Manual T
679343.5810 3082969.5980 J-19S 0.049 Manual T 679382.8640 3083009.1130 J-20S 0.013 Manual T 679335.0020 3082941.1720 J-21S 0.016 Manual T 679252.7130 3082781.0290 J-22S 0.034 Manual T 679297.0010 3082840.6970 J-23S 0.012 Manual T 679394.8070 3082971.8300 J-24S 0.026 Manual T 679146.6460 3082549.7640 J-25S 0.0095 Manual T 679169.0760 3082537.3510 J-26S 0.0073 Manual T 679272.0040 3082652.6750 J-28S 0.0093 Manual T 679374.4420 3082791.3300 J-29S 0.014 Manual T 679453.4760 3082941.1150 J-31S 0.0215 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679342.7410 <td>679293.5600</td> <td>3082950.4980</td> <td>J-17S</td> <td>0.024</td> <td>Manual T</td>	679293.5600	3082950.4980	J-17S	0.024	Manual T
679382.8640 3083009.1130 J-20S 0.013 Manual T 679335.0020 3082941.1720 J-21S 0.016 Manual T 679252.7130 3082781.0290 J-22S 0.034 Manual T 679297.0010 3082840.6970 J-23S 0.012 Manual T 679394.8070 3082971.8300 J-24S 0.026 Manual T 679146.6460 3082549.7640 J-25S 0.0095 Manual T 679169.0760 3082537.3510 J-26S 0.0073 Manual T 679272.0040 3082652.6750 J-28S 0.0093 Manual T 679329.4380 3082711.0960 J-29S 0.014 Manual T 679374.4420 3082791.3300 J-30S 0.024 Manual T 679453.4760 3082914.1150 J-31S 0.0215 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679342.7410 <td>679360.5700</td> <td>3083026.4980</td> <td>J-18S</td> <td>0.0088</td> <td>Manual T</td>	679360.5700	3083026.4980	J-18S	0.0088	Manual T
679335.0020 3082941.1720 J-21S 0.016 Manual T 679252.7130 3082781.0290 J-22S 0.034 Manual T 679297.0010 3082840.6970 J-23S 0.012 Manual T 679394.8070 3082971.8300 J-24S 0.026 Manual T 679146.6460 3082549.7640 J-25S 0.0095 Manual T 679224.5850 3082683.1400 J-26S 0.0073 Manual T 679169.0760 3082537.3510 J-27S 0.016 Manual T 679272.0040 3082652.6750 J-28S 0.0093 Manual T 679329.4380 3082711.0960 J-29S 0.014 Manual T 679374.4420 30828791.3300 J-30S 0.024 Manual T 679453.4760 3082914.1150 J-32S 0.007 Manual T 679304.6530 3082940.9730 J-33S 0.0076 Manual T 679382.8900 <td>679343.5810</td> <td>3082969.5980</td> <td>J-19S</td> <td>0.049</td> <td>Manual T</td>	679343.5810	3082969.5980	J-19S	0.049	Manual T
679252.7130 3082781.0290 J-22S 0.034 Manual T 679297.0010 3082840.6970 J-23S 0.012 Manual T 679394.8070 3082971.8300 J-24S 0.026 Manual T 679146.6460 3082549.7640 J-25S 0.0095 Manual T 679224.5850 3082683.1400 J-26S 0.0073 Manual T 679169.0760 3082537.3510 J-27S 0.016 Manual T 679272.0040 3082652.6750 J-28S 0.0093 Manual T 679329.4380 3082711.0960 J-29S 0.014 Manual T 679374.4420 3082791.3300 J-30S 0.024 Manual T 679453.4760 3082914.1150 J-31S 0.0215 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679304.6530 3082548.6880 J-34S 0.0079 Manual T 679382.8900 </td <td>679382.8640</td> <td>3083009.1130</td> <td>J-20S</td> <td>0.013</td> <td>Manual T</td>	679382.8640	3083009.1130	J-20S	0.013	Manual T
679297.0010 3082840.6970 J-23S 0.012 Manual T 679394.8070 3082971.8300 J-24S 0.026 Manual T 679146.6460 3082549.7640 J-25S 0.0095 Manual T 679224.5850 3082683.1400 J-26S 0.0073 Manual T 679169.0760 3082537.3510 J-27S 0.016 Manual T 679272.0040 3082652.6750 J-28S 0.0093 Manual T 679329.4380 3082711.0960 J-29S 0.014 Manual T 679374.4420 3082791.3300 J-30S 0.024 Manual T 679410.1490 3082845.8460 J-31S 0.0215 Manual T 679453.4760 3082914.1150 J-32S 0.007 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679342.7410 3082605.3190 J-35S 0.0072 Manual T 679433.9450 </td <td>679335.0020</td> <td>3082941.1720</td> <td>J-21S</td> <td>0.016</td> <td>Manual T</td>	679335.0020	3082941.1720	J-21S	0.016	Manual T
679394.8070 3082971.8300 J-24S 0.026 Manual T 679146.6460 3082549.7640 J-25S 0.0095 Manual T 679224.5850 3082683.1400 J-26S 0.0073 Manual T 679169.0760 3082537.3510 J-27S 0.016 Manual T 679272.0040 3082652.6750 J-28S 0.0093 Manual T 679329.4380 3082711.0960 J-29S 0.014 Manual T 679374.4420 3082791.3300 J-30S 0.024 Manual T 679410.1490 3082845.8460 J-31S 0.0215 Manual T 679453.4760 3082914.1150 J-32S 0.007 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679342.7410 3082605.3190 J-35S 0.0072 Manual T 679382.8900 3082667.5270 J-36S 0.0013 Manual T 679470.3570<	679252.7130	3082781.0290	J-22S	0.034	Manual T
679146.6460 3082549.7640 J-25S 0.0095 Manual T 679224.5850 3082683.1400 J-26S 0.0073 Manual T 679169.0760 3082537.3510 J-27S 0.016 Manual T 679272.0040 3082652.6750 J-28S 0.0093 Manual T 679329.4380 3082711.0960 J-29S 0.014 Manual T 679374.4420 3082791.3300 J-30S 0.024 Manual T 679410.1490 3082845.8460 J-31S 0.0215 Manual T 679453.4760 3082941.1150 J-32S 0.007 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679304.6530 3082548.6880 J-34S 0.079 Manual T 679382.8900 3082605.3190 J-35S 0.0072 Manual T 679470.3570 3082731.6820 J-37S 0.0013 Manual T 679524.3310<	679297.0010	3082840.6970	J-23S	0.012	Manual T
679224.5850 3082683.1400 J-26S 0.0073 Manual T 679169.0760 3082537.3510 J-27S 0.016 Manual T 679272.0040 3082652.6750 J-28S 0.0093 Manual T 679329.4380 3082711.0960 J-29S 0.014 Manual T 679374.4420 3082791.3300 J-30S 0.024 Manual T 679410.1490 3082845.8460 J-31S 0.0215 Manual T 679453.4760 3082914.1150 J-32S 0.007 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679304.6530 3082548.6880 J-34S 0.0079 Manual T 679342.7410 3082605.3190 J-35S 0.0072 Manual T 679382.8900 3082667.5270 J-36S 0.0031 Manual T 679470.3570 3082731.6820 J-37S 0.0013 Manual T 679524.3310	679394.8070	3082971.8300	J-24S	0.026	Manual T
679169.0760 3082537.3510 J-27S 0.016 Manual T 679272.0040 3082652.6750 J-28S 0.0093 Manual T 679329.4380 3082711.0960 J-29S 0.014 Manual T 679374.4420 3082791.3300 J-30S 0.024 Manual T 679410.1490 3082845.8460 J-31S 0.0215 Manual T 679453.4760 3082914.1150 J-32S 0.007 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679304.6530 3082548.6880 J-34S 0.079 Manual T 679342.7410 3082605.3190 J-35S 0.0072 Manual T 679382.8900 3082667.5270 J-36S 0.0031 Manual T 679470.3570 3082731.6820 J-37S 0.0013 Manual T 679524.3310 3082840.3960 J-39S 0.019 Manual T 679560.6070 </td <td>679146.6460</td> <td>3082549.7640</td> <td>J-25S</td> <td>0.0095</td> <td>Manual T</td>	679146.6460	3082549.7640	J-25S	0.0095	Manual T
679272.0040 3082652.6750 J-28S 0.0093 Manual T 679329.4380 3082711.0960 J-29S 0.014 Manual T 679374.4420 3082791.3300 J-30S 0.024 Manual T 679410.1490 3082845.8460 J-31S 0.0215 Manual T 679453.4760 3082914.1150 J-32S 0.007 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679304.6530 3082548.6880 J-34S 0.079 Manual T 679342.7410 3082605.3190 J-35S 0.0072 Manual T 679382.8900 3082667.5270 J-36S 0.0031 Manual T 679433.9450 3082731.6820 J-37S 0.0013 Manual T 679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679532.9930<	679224.5850	3082683.1400	J-26S	0.0073	Manual T
679329.4380 3082711.0960 J-29S 0.014 Manual T 679374.4420 3082791.3300 J-30S 0.024 Manual T 679410.1490 3082845.8460 J-31S 0.0215 Manual T 679453.4760 3082914.1150 J-32S 0.007 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679304.6530 3082548.6880 J-34S 0.079 Manual T 679342.7410 3082605.3190 J-35S 0.0072 Manual T 679382.8900 3082667.5270 J-36S 0.0031 Manual T 679470.3570 3082731.6820 J-37S 0.0013 Manual T 679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679169.0760	3082537.3510	J-27S	0.016	Manual T
679374.4420 3082791.3300 J-30S 0.024 Manual T 679410.1490 3082845.8460 J-31S 0.0215 Manual T 679453.4760 3082914.1150 J-32S 0.007 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679304.6530 3082548.6880 J-34S 0.079 Manual T 679342.7410 3082605.3190 J-35S 0.0072 Manual T 679382.8900 3082667.5270 J-36S 0.0031 Manual T 679433.9450 3082731.6820 J-37S 0.0013 Manual T 679470.3570 3082776.7350 J-38S 0.0054 Manual T 679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679272.0040	3082652.6750	J-28S	0.0093	Manual T
679410.1490 3082845.8460 J-31S 0.0215 Manual T 679453.4760 3082914.1150 J-32S 0.007 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679304.6530 3082548.6880 J-34S 0.079 Manual T 679342.7410 3082605.3190 J-35S 0.0072 Manual T 679382.8900 3082667.5270 J-36S 0.0031 Manual T 679433.9450 3082731.6820 J-37S 0.0013 Manual T 679470.3570 3082776.7350 J-38S 0.0054 Manual T 679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679329.4380	3082711.0960	J-29S	0.014	Manual T
679453.4760 3082914.1150 J-32S 0.007 Manual T 679495.8840 3082940.9730 J-33S 0.0076 Manual T 679304.6530 3082548.6880 J-34S 0.079 Manual T 679342.7410 3082605.3190 J-35S 0.0072 Manual T 679382.8900 3082667.5270 J-36S 0.0031 Manual T 679433.9450 3082731.6820 J-37S 0.0013 Manual T 679470.3570 308276.7350 J-38S 0.0054 Manual T 679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679374.4420	3082791.3300	J-30S	0.024	Manual T
679495.8840 3082940.9730 J-33S 0.0076 Manual T 679304.6530 3082548.6880 J-34S 0.079 Manual T 679342.7410 3082605.3190 J-35S 0.0072 Manual T 679382.8900 3082667.5270 J-36S 0.0031 Manual T 679433.9450 3082731.6820 J-37S 0.0013 Manual T 679470.3570 3082776.7350 J-38S 0.0054 Manual T 679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679410.1490	3082845.8460	J-31S	0.0215	Manual T
679304.6530 3082548.6880 J-34S 0.079 Manual T 679342.7410 3082605.3190 J-35S 0.0072 Manual T 679382.8900 3082667.5270 J-36S 0.0031 Manual T 679433.9450 3082731.6820 J-37S 0.0013 Manual T 679470.3570 3082776.7350 J-38S 0.0054 Manual T 679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679453.4760	3082914.1150	J-32S	0.007	Manual T
679342.7410 3082605.3190 J-35S 0.0072 Manual T 679382.8900 3082667.5270 J-36S 0.0031 Manual T 679433.9450 3082731.6820 J-37S 0.0013 Manual T 679470.3570 3082776.7350 J-38S 0.0054 Manual T 679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679495.8840	3082940.9730	J-33S	0.0076	Manual T
679382.8900 3082667.5270 J-36S 0.0031 Manual T 679433.9450 3082731.6820 J-37S 0.0013 Manual T 679470.3570 3082776.7350 J-38S 0.0054 Manual T 679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679304.6530	3082548.6880	J-34S	0.079	Manual T
679433.9450 3082731.6820 J-37S 0.0013 Manual T 679470.3570 3082776.7350 J-38S 0.0054 Manual T 679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679342.7410	3082605.3190	J-35S	0.0072	Manual T
679470.3570 3082776.7350 J-38S 0.0054 Manual T 679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679382.8900	3082667.5270	J-36S	0.0031	Manual T
679497.3310 3082840.3960 J-39S 0.019 Manual T 679524.3310 3082886.8990 J-40S 0.0079 Manual T 679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679433.9450	3082731.6820	J-37S	0.0013	Manual T
679524.3310 3082886.8990 J-40S 0.0079 Manual T 679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679470.3570	3082776.7350	J-38S	0.0054	Manual T
679560.6070 3082897.2580 J-41S 0.013 Manual T 679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679497.3310	3082840.3960	J-39S	0.019	Manual T
679532.9930 3082835.5820 J-42SD 0.0011 Manual T	679524.3310	3082886.8990	J-40S	0.0079	Manual T
0.000=10000 000=001100=0 1.0011 1.1001100	679560.6070	3082897.2580	J-41S	0.013	Manual T
679552.9590 3082868.6600 J-43SD 0.0022 Manual T	679532.9930	3082835.5820	J-42SD	0.0011	Manual T
	679552.9590	3082868.6600	J-43SD	0.0022	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	Analyte n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples										
A1 _1	n	α=	=5	α=	10	α=	α=15			
AL=10		s=6	s=3	s=6	s=3	s=6	s=3			
	β=5	391	99	310	78	260	66			
LBGR=90	β=10	310	79	238	60	194	49			
	β=15	261	67	195	50	156	40			
	β=5	99	26	78	21	66	17			
LBGR=80	β=10	79	21	60	16	49	13			
	β=15	67	18	50	13	40	11			
LBGR=70	β=5	45	13	36	10	30	8			

β=10	36	10	28	8	23	6
β=15	31	9	23	7	18	5

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	21 Samples						
Field collection costs		\$100.00	\$2,100.00						
Analytical costs	\$400.00	\$400.00	\$8,400.00						
Sum of Field & Analytical costs		\$500.00	\$10,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$11,500.00						

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0.000385	0.000385	0.0011	0.0013	0.0014	0.0014	0.0022	0.0031	0.0037	0.0047
10	0.00535	0.0054	0.0054	0.0065	0.0069	0.007	0.007	0.0072	0.0073	0.0076
20	0.0079	0.0083	0.0088	0.0093	0.0095	0.0096	0.011	0.012	0.013	0.013
30	0.013	0.014	0.016	0.016	0.019	0.0215	0.024	0.024	0.026	0.034
40	0.034	0.049	0.079	0.74						

SUMMARY STATISTICS			
n	44		
Min	0.000385		
Max	0.74		
Range	0.73962		
Mean	0.029482		
Median	0.00855		
Variance	0.012219		
StdDev	0.11054		
Std Error	0.016664		
Skewness	6.4649		
Interquartile Range	0.010638		

Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.000385	0.0005638	0.00135	0.005363	0.00855	0.016	0.034	0.0715	0.74

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	6.428	3.08	Yes		

The test statistic 6.428 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS			
1	0.74		

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.7202				
Shapiro-Wilk 5% Critical Value	0.943				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST			
Shapiro-Wilk Test Statistic	0.2336		
Shapiro-Wilk 5% Critical Value	0.944		

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	0.0575			
95% Non-Parametric (Chebyshev) UCL	0.1021			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.1021) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=44 data,

AL is the action level or threshold (10),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=43 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-598.31	1.6811	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+) 95% Critical Value Null Hypothesi				
44	27	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1				
X Coord Y C	loord Labol	Value	Type	Historical
679149.492	3082933.098	J-13S	Type 0.000385	
679279.683	3082933.098	J-13S J-14S	0.000383	Manual
679261.098	3083075.429	J-14S J-15S	0.0034	
				Manual
679222.634	3082840.172	J-16S	0.034	Manual
679293.56	3082950.498	J-17S	0.024	Manual
679360.57	3083026.498	J-18S	0.0088	Manual
679343.581	3082969.598	J-19S	0.049	Manual
679382.864	3083009.113	J-20S	0.013	Manual
679335.002	3082941.172	J-21S	0.016	Manual
679252.713	3082781.029	J-22S	0.034	Manual
679297.001	3082840.697	J-23S	0.012	Manual
679394.807	3082971.83	J-24S	0.026	Manual
679146.646	3082549.764	J-25S	0.0095	Manual
679224.585	3082683.14	J-26S	0.0073	Manual
679169.076	3082537.351	J-27S	0.016	Manual
679272.004	3082652.675	J-28S	0.0093	Manual
679329.438	3082711.096	J-29S	0.014	Manual
679374.442	3082791.33	J-30S	0.024	Manual
679410.149	3082845.846	J-31S	0.0215	Manual
679453.476	3082914.115	J-32S	0.007	Manual
679495.884	3082940.973	J-33S	0.0076	Manual
679304.653	3082548.688	J-34S	0.079	Manual
679342.741	3082605.319	J-35S	0.0072	Manual
679382.89	3082667.527	J-36S	0.0031	Manual
679433.945	3082731.682	J-37S	0.0013	Manual
679470.357	3082776.735	J-38S	0.0054	Manual
679497.331	3082840.396	J-39S	0.019	Manual
679524.331	3082886.899	J-40S	0.0079	Manual
679560.607	3082897.258	J-41S	0.013	Manual
679532.993	3082835.582	J-42SD	0.0011	Manual
679552.959	3082868.66	J-43SD	0.0022	Manual
Area: Area 5				
X Coord Y C		Value	Type	Historical
679133.429	3083306.313	J-01S	0.0083	Manual
679104.245	3083223.262	J-02S	0.0069	Manual
679155.074	3083294.696	J-03S	0.0096	Manual
679171.297	3083289.796	J-04S	0.007	Manual
679225.856	3083359.974	J-05S	0.0014	Manual
679164.806	3083214.71	J-06S	0.00535	Manual
679242.726	3083326.528	J-07S	0.74 Man	ual
679181.275	3083178.288	J-08S	0.0014	Manual
679213.773	3083224.973	J-09S	0.013	Manual
679280.544	3083305.681	J-10S	0.0047	Manual
679268.77	3083200.326	J-11S	0.0037	Manual
679301.16	3083254.034	J-12S	0.0065	Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN				
Primary Objective of Design	Compare a site mean to a fixed threshold			
Type of Sampling Design	Parametric			
Sample Placement (Location) in the Field	Simple random sampling			
Working (Null) Hypothesis	The mean value at the site exceeds the threshold			
Formula for calculating number of sampling locations	Student's t-test			
Calculated total number of samples	21			
Number of samples on map ^a	23			
Number of selected sample areas b	2			
Specified sampling area ^c	188054.34 m ²			
Total cost of sampling ^d	\$11,500.00			

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679133.4290	3083306.3130	TW01-01	4.8	Manual	Т	
679104.2450	3083223.2620	TW01-02	5.1	Manual	Т	
679242.7260	3083326.5280	TW01-07	5.1	Manual	Т	
679181.2750	3083178.2880	TW01-08	6.2	Manual	Т	
679268.7700	3083200.3260	TW01-11	6.7	Manual	Т	
679301.1600	3083254.0340	TW01-12	4.8	Manual	Т	
679268.6582	3083218.6677	J-42SD	2.9	Random		

Area: Area 3							
X Coord	Y Coord	Label	Value	Туре	Historical		
679532.9930	3082835.5820	J-42SD	2.9	Manual	Т		
679552.9590	3082868.6600	J-43SD	2.7	Manual	Т		
679149.4920	3082933.0980	TW01-13	3.5	Manual	Т		
679279.7760	3083075.6320	TW01-14	2.7	Manual	Т		
679293.5600	3082950.4980	TW01-17	2.9	Manual	Т		
679360.5700	3083026.4980	TW01-18	2.7	Manual	Т		

Т	Manual	3.5	TW01-27	3082537.3510	679169.0760
Т	Manual	3.7	TW01-33	3082940.9730	679495.8840
Т	Manual	4.2	TW01-34	3082548.6880	679304.6530
Т	Manual	4.8	TW01-35	3082605.3190	679342.7410
Т	Manual	2.7	TW01-36	3082667.5270	679382.8900
Т	Manual	2.7	TW01-37	3082731.6820	679433.9450
Т	Manual	2.7	TW01-38	3082776.7350	679470.3570
Т	Manual	2.7	TW01-39	3082840.3960	679497.3310
Т	Manual	2.7	TW01-40	3082886.8990	679524.3310
T	Manual	4.1	TW01-41	3082897.2580	679560.6110

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .


The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter					
Analyte	n	S	Δ	α	β	Z _{1-α} ^a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

b This value is automatically calculated by VSP based upon the user defined value of β.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=2	,	α=	=5	α=	10	α=15		
AL=Z	i	s=6	s=3	s=6 s=3		s=6	s=3	
	β=5	9742	2437	7709	1928	6471	1619	
LBGR=90	β=10	7709	1929	5914	1479	4837	1210	
	β=15	6472	1619	4837	1210	3868	968	
	β=5	2437	611	1928	483	1619	405	
LBGR=80	β=10	1929	484	1479	371	1210	303	
	β=15	1619	406	1210	304	968	243	
	β=5	1084	272	858	215	720	181	
LBGR=70	β=10	858	216	658	166	538	135	
	β=15	721	182	539	136	431	108	

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	21 Samples			
Field collection costs		\$100.00	\$2,100.00			
Analytical costs	\$400.00	\$400.00	\$8,400.00			
Sum of Field & Analytical costs		\$500.00	\$10,500.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$11,500.00			

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	2.7	2.7	2.7	2.7	2.7	2.7	2.7	2.7	2.9	2.9
10	2.9	3.5	3.5	3.7	4.1	4.2	4.8	4.8	4.8	5.1
20	5.1	6.2	6.7							

SUMMARY STATISTICS

	ı	n		23				
	M	lin		2.7				
	М	ах				6.7		
	Rai	nge				4		
	Me	ean			;	3.7739	9	
	Мес	dian				3.5		
	Vari	ance		1.5038				
	Std	Dev		1.2263				
	Std I	Error			0.2557			
Skewness				0	.9555	6		
Inte	erquar	tile Ra	nge	2.1				
			Perc	centiles				
1%	5%	10%	25%	50%	75%	90%	95%	99%
2.7	2.7	2.7	2.7	3.5	4.8	5.76	6.6	6.7

Outlier Test

Dixon's extreme value test was performed to test whether the lowest value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

DIXON'S OUTLIER TEST				
Dixon Test Statistic	0			
Dixon 5% Critical Value	0.421			

The calculated test statistic does not exceed the critical value, so the test cannot reject the null hypothesis that there are no outliers in the data, and concludes that the minimum value 2.7 is not an outlier at the 5% significance level.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Dixon's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.8488				
Shapiro-Wilk 5% Critical Value	0.911				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the minimum value 2.7, do not appear to follow a normal distribution at the 5% level of significance. Dixon's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The

sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution.

The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.834			
Shapiro-Wilk 5% Critical Value	0.914			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	4.213			
95% Non-Parametric (Chebyshev) UCL	4.888			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (4.888) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=23 data.

AL is the action level or threshold (2),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=22 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic	Critical Value t _{0.95}	Null Hypothesis		
6.9374	1.7171	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+)	95% Critical Value	Null Hypothesis			
0	15	Cannot Reject			

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp
Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1 X Coord Y Coord Label Value Type Historical 3082835.582 J-42SD 2.9 Manual 679532.993 679552.959 3082868.66 J-43SD 2.7 Manual 3082933.098 TW01-133.5 Manual 679149.492 679279.776 3083075.632 TW01-142.7 Manual 679293.56 3082950.498 TW01-172.9 Manual 3083026.498 TW01-182.7 Manual 679360.57 679169.076 3082537.351 TW01-273.5 Manual 679495.884 3082940.973 TW01-333.7 Manual 3082548.688 TW01-344.2 Manual 679304.653 679342.741 3082605.319 TW01-354.8 Manual 3082667.527 TW01-362.7 Manual 679382.89 679433.945 3082731.682 TW01-372.7 Manual 679470.357 3082776.735 TW01-382.7 Manual 679497.331 3082840.396 TW01-392.7 Manual 3082886.899 TW01-402.7 Manual 679524.331 679560.611 3082897.258 TW01-414.1 Manual

Area: Area 5

X Coord Y	Coord Label	Value	Туре	e Historical
679133.429	3083306.313	TW01-0	14.8	Manual
679104.245	3083223.262	TW01-0	25.1	Manual
679242.726	3083326.528	TW01-0	75.1	Manual
679181.275	3083178.288	TW01-0	86.2	Manual
679268.77	3083200.326	TW01-1	16.7	Manual
679301.16	3083254.034	TW01-1	24.8	Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN			
Primary Objective of Design	Compare a site mean to a fixed threshold		
Type of Sampling Design	Parametric		
Sample Placement (Location) in the Field	Simple random sampling		
Working (Null) Hypothesis	The mean value at the site exceeds the threshold		
Formula for calculating number of sampling locations	Student's t-test		
Calculated total number of samples	27		
Number of samples on map ^a	42		
Number of selected sample areas b	2		
Specified sampling area ^c	188054.34 m ²		
Total cost of sampling d	\$14,500.00		

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical					
679133.4290	3083306.3130	J-01S	0.97	Manual	Т					
679104.2450	3083223.2620	J-02S	5	Manual	Т					
679155.0740	3083294.6960	J-03S	1.7	Manual	Т					
679171.2970	3083289.7960	J-04S	1	Manual	Т					
679225.8560	3083359.9740	J-05S	0.77	Manual	Т					
679164.8060	3083214.7100	J-06S	5.3	Manual	Т					
679242.7260	3083326.5280	J-07S	7.1	Manual	Т					
679181.2750	3083178.2880	J-08S	5.7	Manual	Т					
679213.7730	3083224.9730	J-09S	0.95	Manual	Т					
679280.5440	3083305.6810	J-10S	0.83	Manual	Т					
679268.7700	3083200.3260	J-11S	0.89	Manual	Т					
679301.1600	3083254.0340	J-12S	0.65	Manual	Т					

Area: Area 3						
X Coord Y Coord Label Value Type Historical						
679149.4920	3082933.0980	J-13S	6.9	Manual	Т	

679279.6830	3083075.4290	J-14S	1.3	Manual	Т
679261.0980	3083016.3510	J-15S	4.4	Manual	Т
679222.6340	3082840.1720	J-16S	4.5	Manual	Т
679293.5600	3082950.4980	J-17S	2.1	Manual	Т
679360.5700	3083026.4980	J-18S	3.6	Manual	Т
679343.5810	3082969.5980	J-19S	3.2	Manual	Т
679382.8640	3083009.1130	J-20S	1.8	Manual	Т
679335.0020	3082941.1720	J-21S	1.1	Manual	Т
679252.7130	3082781.0290	J-22S	2.3	Manual	Т
679297.0010	3082840.6970	J-23S	6.7	Manual	Т
679394.8070	3082971.8300	J-24S	1.2	Manual	Т
679146.6460	3082549.7640	J-25S	13.7	Manual	Т
679224.5850	3082683.1400	J-26S	2.9	Manual	Т
679169.0760	3082537.3510	J-27S	6	Manual	Т
679272.0040	3082652.6750	J-28S	13	Manual	Т
679329.4380	3082711.0960	J-29S	3.8	Manual	Т
679374.4420	3082791.3300	J-30S	2.4	Manual	Т
679410.1490	3082845.8460	J-31S	1.7	Manual	Т
679453.4760	3082914.1150	J-32S	3.7	Manual	Т
679495.8840	3082940.9730	J-33S	2	Manual	Т
679304.6530	3082548.6880	J-34S	2.4	Manual	Т
679342.7410	3082605.3190	J-35S	3.1	Manual	Т
679382.8900	3082667.5270	J-36S	11	Manual	Т
679433.9450	3082731.6820	J-37S	12.1	Manual	Т
679470.3570	3082776.7350	J-38S	5.8	Manual	Т
679497.3310	3082840.3960	J-39S	2.4	Manual	Т
679524.3310	3082886.8990	J-40S	1.95	Manual	Т
679560.6070	3082897.2580	J-41S	4.3	Manual	Т
679324.2903	3083020.9402		0	Random	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is $1-\beta$.

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter $S \qquad \Delta \alpha \qquad \beta \qquad Z_{1-\alpha}^{ a} \qquad Z_{1-\beta}^{ b}$					
Analyte	n						
	27	3.4098	3 2 0.05 0.1 1.64485 1.2		1.28155		


 $^{\text{a}}$ This value is automatically calculated by VSP based upon the user defined value of α

^b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	Number of Samples								
A1 -20	.4	α=	=5	α=	:10	α=	:15		
AL=29	' I	s=6.8196	s=3.4098	s=6.8196	s=3.4098	s=6.8196	s=3.4098		
	β=5	2	2	2	1	1	1		
LBGR=90	β=10	2	2	2	1	1	1		
	β=15	2	2	2	1	1	1		
	β=5	2	2	1	1	1	1		
LBGR=80	β=10	2	2	1	1	1	1		
	β=15	2	2	1	1	1	1		
LBGR=70	β=5	2	2	1	1	1	1		

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$14,500.00, which averages out to a per sample cost of \$537.04. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	27 Samples					
Field collection costs		\$100.00	\$2,700.00					
Analytical costs	\$400.00	\$400.00	\$10,800.00					
Sum of Field & Analytical costs		\$500.00	\$13,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$14,500.00					

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.65	0.77	0.83	0.89	0.95	0.97	1	1.1	1.2
10	1.3	1.7	1.7	1.8	1.95	2	2.1	2.3	2.4	2.4
20	2.4	2.9	3.1	3.2	3.6	3.7	3.8	4.3	4.4	4.5
30	5	5.3	5.7	5.8	6	6.7	6.9	7.1	11	12.1
40	13	13.7								

SUMMARY ST	ATISTICS
n	42
Min	0
Max	13.7
Range	13.7
Mean	3.8621
Median	2.65
Variance	11.626
StdDev	3.4098
Std Error	0.52614
Skewness	1.5405
Interquartile Range	4.125

	Percentiles									
1%	1% 5% 10% 25% 50% 75% 90% 95% 99%									
0	0.668	0.848	1.275	2.65	5.4	9.83	12.87	13.7		

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST							
k	k Test Statistic R _k 5% Critical Value C _k Significant							
1		2.885	3.06	No				

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION T	EST (excluding outliers)
Shapiro-Wilk Test Statistic	0.8408
Shapiro-Wilk 5% Critical Value	0.941

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic	0.7913				
Shapiro-Wilk 5% Critical Value	0.942				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that

assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	4.748
95% Non-Parametric (Chebyshev) UCL	6.156

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (6.156) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=42 data, AL is the action level or threshold (291),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=41 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic	Null Hypothesis				
-545.75	1.6829	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothesis						
42	26	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

 $\ensuremath{^{\star}}$ - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1			
X Coord Y C	land I ahal	Value	True Historical
			Type Historical
679149.492	3082933.098	J-13S	6.9 Manual
679279.683	3083075.429	J-14S	1.3 Manual
679261.098	3083016.351	J-15S	4.4 Manual
679222.634	3082840.172	J-16S	4.5 Manual
679293.56	3082950.498	J-17S	2.1 Manual
679360.57	3083026.498	J-18S	3.6 Manual
679343.581	3082969.598	J-19S	3.2 Manual
679382.864	3083009.113	J-20S	1.8 Manual
679335.002	3082941.172	J-21S	1.1 Manual
679252.713	3082781.029	J-22S	2.3 Manual
679297.001	3082840.697	J-23S	6.7 Manual
679394.807	3082971.83	J-24S	1.2 Manual
679146.646	3082549.764	J-25S	13.7 Manual
679224.585	3082683.14	J-26S	2.9 Manual
679169.076	3082537.351	J-27S	6 Manual
679272.004	3082652.675	J-28S	13 Manual
679329.438	3082711.096	J-29S	3.8 Manual
679374.442	3082791.33	J-30S	2.4 Manual
679410.149	3082845.846	J-31S	1.7 Manual
679453.476	3082914.115	J-32S	3.7 Manual
679495.884	3082940.973	J-33S	2 Manual
679304.653	3082548.688	J-34S	2.4 Manual
679342.741	3082605.319	J-34S J-35S	3.1 Manual
679382.89	3082667.527	J-36S	11 Manual
679433.945	3082731.682	J-30S J-37S	12.1 Manual
	3082776.735	J-37S J-38S	
679470.357			
679497.331	3082840.396	J-39S	2.4 Manual
679524.331	3082886.899	J-40S	1.95 Manual
679560.607	3082897.258	J-41S	4.3 Manual
Area: Area 5			
X Coord Y C	Coord Label	Value	Type Historical
679133.429	3083306.313	J-01S	0.97 Manual
679104.245	3083223.262	J-02S	5 Manual
679155.074	3083294.696	J-03S	1.7 Manual
679171.297	3083289.796	J-04S	1 Manual
679225.856	3083359.974	J-05S	0.77 Manual
679164.806	3083214.71	J-05S J-06S	5.3 Manual
679242.726	3083326.528	J-07S	
679181.275	3083178.288	J-08S	5.7 Manual
679213.773	3083224.973	J-09S	0.95 Manual
679280.544	3083305.681	J-10S	0.83 Manual
679268.77	3083200.326	J-11S	0.89 Manual
679301.16	3083254.034	J-12S	0.65 Manual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold				
Type of Sampling Design	Parametric				
Sample Placement (Location) in the Field	Simple random sampling				
Working (Null) Hypothesis	The mean value at the site exceeds the threshold				
Formula for calculating number of sampling locations	Student's t-test				
Calculated total number of samples	21				
Number of samples on map ^a	44				
Number of selected sample areas b	2				
Specified sampling area ^c	188054.34 m ²				
Total cost of sampling d	\$11,500.00				

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1										
X Coord	Historical									
679133.4290	3083306.3130	J-01S	4.7	Manual	Т					
679104.2450	3083223.2620	J-02S	1.1	Manual	Т					
679155.0740	3083294.6960	J-03S	1.15	Manual	Т					
679171.2970	3083289.7960	J-04S	1.3	Manual	Т					
679225.8560	3083359.9740	J-05S	1.7	Manual	Т					
679164.8060	3083214.7100	J-06S	0.985	Manual	Т					
679242.7260	3083326.5280	J-07S	5.1	Manual	Т					
679181.2750	3083178.2880	J-08S	6.1	Manual	Т					
679213.7730	3083224.9730	J-09S	7.7	Manual	Т					
679280.5440	3083305.6810	J-10S	2.4	Manual	Т					
679268.7700	3083200.3260	J-11S	22.3	Manual	Т					
679301.1600	3083254.0340	J-12S	5.1	Manual	Т					
679132.4126	3083226.0123	J-13S	2.4	Random						

Area: Area 3						
X Coord	Y Coord	Label	Value	Туре	Historical	

679149.4920	3082933.0980	J-13S	2.4	Manual T
679279.6830	3083075.4290	J-14S	4.1	Manual T
679261.0980	3083016.3510	J-15S	2.1	Manual T
679222.6340	3082840.1720	J-16S	4.5	Manual T
679293.5600	3082950.4980	J-17S	10.6	Manual T
679360.5700	3083026.4980	J-18S	4.1	Manual T
679343.5810	3082969.5980	J-19S	5.25	Manual T
679382.8640	3083009.1130	J-20S	5.8	Manual T
679335.0020	3082941.1720	J-21S	4.9	Manual T
679252.7130	3082781.0290	J-22S	6.85	Manual T
679297.0010	3082840.6970	J-23S	9.6	Manual T
679394.8070	3082971.8300	J-24S	2.3	Manual T
679146.6460	3082549.7640	J-25S	1.6	Manual T
679224.5850	3082683.1400	J-26S	2.925	Manual T
679169.0760	3082537.3510	J-27S	3.5	Manual T
679272.0040	3082652.6750	J-28S	6.6	Manual T
679329.4380	3082711.0960	J-29S	12.8	Manual T
679374.4420	3082791.3300	J-30S	16.6	Manual T
679410.1490	3082845.8460	J-31S	17.25	Manual T
679453.4760	3082914.1150	J-32S	16.2	Manual T
679495.8840	3082940.9730	J-33S	4.8	Manual T
679304.6530	3082548.6880	J-34S	29.3	Manual T
679342.7410	3082605.3190	J-35S	9.1	Manual T
679382.8900	3082667.5270	J-36S	10.5	Manual T
679433.9450	3082731.6820	J-37S	13.2	Manual T
679470.3570	3082776.7350	J-38S	16	Manual T
679497.3310	3082840.3960	J-39S	7.8	Manual T
679524.3310	3082886.8990	J-40S	15.8	Manual T
679560.6070	3082897.2580	J-41S	7	Manual T
679532.9930	3082835.5820	J-42SD	3.6	Manual T
679552.9590	3082868.6600	J-43SD	10.5	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter						
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b	
	21	3	2	0.05	0.1	1.64485	1.28155	


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples									
AL=10		α=	=5	α=	α=10		α=15		
		s=6	s=3	s=6	s=3	s=6	s=3		
	β=5	391	99	310	78	260	66		
LBGR=90	β=10	310	79	238	60	194	49		
	β=15	261	67	195	50	156	40		
	β=5	99	26	78	21	66	17		
LBGR=80	β=10	79	21	60	16	49	13		
	β=15	67	18	50	13	40	11		
LBGR=70	β=5	45	13	36	10	30	8		

β=10	36	10	28	8	23	6
β=15	31	9	23	7	18	5

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION				
Cost Details	Per Analysis	Per Sample	21 Samples	
Field collection costs		\$100.00	\$2,100.00	
Analytical costs	\$400.00	\$400.00	\$8,400.00	
Sum of Field & Analytical costs		\$500.00	\$10,500.00	
Fixed planning and validation costs			\$1,000.00	
Total cost			\$11,500.00	

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.985	1.1	1.15	1.3	1.6	1.7	2.1	2.3	2.4
10	2.4	2.4	2.925	3.5	3.6	4.1	4.1	4.5	4.7	4.8
20	4.9	5.1	5.1	5.25	5.8	6.1	6.6	6.85	7	7.7
30	7.8	9.1	9.6	10.5	10.5	10.6	12.8	13.2	15.8	16
40	16.2	16.6	17.25	22.3	29.3					

SUMMARY STATISTICS		
n	45	
Min	0	
Max	29.3	
Range	29.3	
Mean	7.3247	
Median	5.1	
Variance	39.388	
StdDev	6.276	
Std Error	0.93556	
Skewness	1.4901	
Interquartile Range	8.1	

	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	1.02	1.24	2.4	5.1	10.5	16.36	20.79	29.3

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST				
k	Test Statistic R _k	5% Critical Value C _k	Significant?	
1	3.469	3.08	Yes	

The test statistic 3.469 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS	
1	29.3

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)			
Shapiro-Wilk Test Statistic	0.8963		
Shapiro-Wilk 5% Critical Value	0.943		

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST		
Shapiro-Wilk Test Statistic	0.8603	
Shapiro-Wilk 5% Critical Value	0.945	

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	8.897
95% Non-Parametric (Chebyshev) UCL	11.4

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (11.4) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=45 data,

AL is the action level or threshold (10),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=44 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST			
t-statistic Critical Value $t_{0.95}$ Null Hypothesis			
-2.8596	1.6802	Reject	

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test			
Test Statistic (S+) 95% Critical Value Null Hypothesis			
33	28	Reject	

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

```
Area: Area 1
X Coord Y Coord Label
                          Value
                                   Type
                                            Historical
                                   2.4 Manual
679149.492
             3082933.098 J-13S
                                   4.1 Manual
679279.683
             3083075.429 J-14S
679261.098
             3083016.351 J-15S
                                   2.1 Manual
679222.634
             3082840.172 J-16S
                                   4.5 Manual
679293.56
             3082950.498 J-17S
                                   10.6 Manual
679360.57
             3083026.498 J-18S
                                   4.1 Manual
679343.581
             3082969.598 J-19S
                                   5.25 Manual
             3083009.113 J-20S
679382.864
                                   5.8 Manual
679335.002
             3082941.172 J-21S
                                   4.9 Manual
679252.713
             3082781.029 J-22S
                                   6.85 Manual
679297.001
             3082840.697 J-23S
                                   9.6 Manual
679394.807
             3082971.83
                          J-24S
                                   2.3 Manual
             3082549.764 J-25S
                                   1.6 Manual
679146.646
679224.585
             3082683.14
                          J-26S
                                   2.925
                                            Manual
679169.076
             3082537.351 J-27S
                                   3.5 Manual
679272.004
             3082652.675 J-28S
                                   6.6 Manual
679329.438
             3082711.096 J-29S
                                   12.8 Manual
679374.442
             3082791.33
                          J-30S
                                   16.6 Manual
679410.149
             3082845.846 J-31S
                                   17.25
                                            Manual
679453.476
             3082914.115 J-32S
                                   16.2 Manual
679495.884
             3082940.973 J-33S
                                   4.8 Manual
679304.653
             3082548.688 J-34S
                                   29.3 Manual
679342.741
             3082605.319 J-35S
                                   9.1 Manual
679382.89
             3082667.527 J-36S
                                   10.5 Manual
679433.945
             3082731.682 J-37S
                                   13.2 Manual
679470.357
             3082776.735 J-38S
                                       Manual
679497.331
             3082840.396 J-39S
                                   7.8 Manual
                                   15.8 Manual
679524.331
             3082886.899 J-40S
679560.607
             3082897.258 J-41S
                                   7
                                       Manual
679532.993
             3082835.582 J-42SD
                                   3.6 Manual
679552.959
                          J-43SD
                                   10.5 Manual
             3082868.66
Area: Area 5
                          Value
X Coord Y Coord Label
                                   Type
                                            Historical
679133.429
             3083306.313 J-01S
                                   4.7 Manual
679104.245
             3083223.262 J-02S
                                   1.1 Manual
679155.074
             3083294.696 J-03S
                                   1.15 Manual
679171.297
             3083289.796 J-04S
                                   1.3 Manual
                                   1.7 Manual
679225.856
             3083359.974 J-05S
679164.806
             3083214.71
                          J-06S
                                   0.985
                                            Manual
679242.726
             3083326.528 J-07S
                                   5.1 Manual
679181.275
             3083178.288 J-08S
                                   6.1
                                       Manual
             3083224.973 J-09S
679213.773
                                   7.7
                                       Manual
679280.544
             3083305.681 J-10S
                                   2.4 Manual
679268.77
             3083200.326 J-11S
                                   22.3 Manual
```

3083254.034 J-12S

5.1 Manual

679301.16

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	23
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1										
X Coord	Y Coord	Label	Value	Туре	Historical					
679133.4290	3083306.3130	TW01-01	14	Manual	Т					
679104.2450	3083223.2620	TW01-02	21.5	Manual	Т					
679242.7260	3083326.5280	TW01-07	16.5	Manual	Т					
679181.2750	3083178.2880	TW01-08	15.1	Manual	Т					
679268.7700	3083200.3260	TW01-11	14.3	Manual	Т					
679301.1600	3083254.0340	TW01-12	13.3	Manual	Т					

Area: Area 3									
X Coord	Y Coord	Label	Value	Туре	Historical				
679532.9930	3082835.5820	J-42SD	20.2	Manual	Т				
679552.9590	3082868.6600	J-43SD	56	Manual	Т				
679149.4920	3082933.0980	TW01-13	15.5	Manual	Т				
679279.7760	3083075.6320	TW01-14	21.6	Manual	Т				
679293.5600	3082950.4980	TW01-17	16.65	Manual	Т				
679360.5700	3083026.4980	TW01-18	15.6	Manual	Т				
679169.0760	3082537.3510	TW01-27	16.95	Manual	Т				

679495.8840	3082940.9730	TW01-33	12.8	Manual	Т
679304.6530	3082548.6880	TW01-34	196	Manual	Т
679342.7410	3082605.3190	TW01-35	12.7	Manual	Т
679382.8900	3082667.5270	TW01-36	15.5	Manual	Т
679433.9450	3082731.6820	TW01-37	48.4	Manual	Т
679470.3570	3082776.7350	TW01-38	49.5	Manual	Т
679497.3310	3082840.3960	TW01-39	55.2	Manual	Т
679524.3310	3082886.8990	TW01-40	56.4	Manual	Т
679560.6110	3082897.2580	TW01-41	12.3	Manual	Т
679275.6424	3082643.6065		0	Random	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,S is the estimated standard

is the estimated standard deviation of the measured values including analytical error,

 Λ is the width of the gray region.

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .


The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_						
Analyte	n	S	Δ	α	β	Z _{1-α} ^a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

b This value is automatically calculated by VSP based upon the user defined value of β.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=8	4	α	=5	α=	α=10		α=15	
AL=04	+	s=6	s=3	s=6 s=3		s=6 s=3		
	β=5	7	3	6	2	5	2	
LBGR=90	β=10	6	3	5	2	4	2	
	β=15	6	3	4	2	3	2	
	β=5	3	2	2	2	2	1	
LBGR=80	β=10	3	2	2	2	2	1	
	β=15	3	2	2	1	2	1	
LBGR=70	β=5	2	2	2	1	1	1	
	β=10	2	2	2	1	1	1	
	β=15	2	2	2	1	1	1	

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	21 Samples						
Field collection costs		\$100.00	\$2,100.00						
Analytical costs	\$400.00	\$400.00	\$8,400.00						
Sum of Field & Analytical costs		\$500.00	\$10,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$11,500.00						

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	12.3	12.7	12.8	13.3	14	14.3	15.1	15.5	15.5
10	15.6	16.5	16.65	16.95	20.2	21.5	21.6	48.4	49.5	55.2
20	56	56.4	196							

SUMMARY STATISTICS

		23							
		0							
	М	ах				196			
	Ra	nge				196			
	Ме	ean				31.13			
	Ме	dian				16.5			
	Variance				1566.5				
	Std	Dev		39.579					
	Std	Error		8.2528					
	Skev	ewness 3.57							
Inte	erquar	tile Ra	nge	34.4					
Percentiles									
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0	2.46	12.46	14	16.5	48.4	56.24	168.1	196	

Outlier Test

Dixon's extreme value test was performed to test whether the lowest value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

DIXON'S OUTLIER TEST					
Dixon Test Statistic	0.22679				
Dixon 5% Critical Value	0.421				

The calculated test statistic does not exceed the critical value, so the test cannot reject the null hypothesis that there are no outliers in the data, and concludes that the minimum value 0 is not an outlier at the 5% significance level.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Dixon's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)							
Shapiro-Wilk Test Statistic	0.5126						
Shapiro-Wilk 5% Critical Value	0.911						

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the minimum value 0, do not appear to follow a normal distribution at the 5% level of significance. Dixon's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The

sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution.

The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic	0.5401				
Shapiro-Wilk 5% Critical Value	0.914				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	45.3
95% Non-Parametric (Chebyshev) UCL	67.1

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (67.1) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=23 data,

AL is the action level or threshold (84),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=22 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic	Critical Value t _{0.95}	Null Hypothesis					
-6.4063	1.7171	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+)	95% Critical Value	Null Hypothesis					
22	15	Reject					

Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Area: Area 1 Type X Coord Y Coord Label Value Historical 679532.993 3082835.582 J-42SD 20.2 Manual 679552.959 3082868.66 J-43SD 56 Manual 679149.492 3082933.098 TW01-1315.5 Manual 679279.776 3083075.632 TW01-1421.6 Manual 679293.56 3082950.498 TW01-1716.65 Manual 3083026.498 TW01-1815.6 Manual 679360.57 679169.076 3082537.351 TW01-2716.95 Manual 3082940.973 TW01-3312.8 Manual 679495.884 3082548.688 TW01-34196 Manual 679304.653 679342.741 3082605.319 TW01-3512.7 Manual 3082667.527 TW01-3615.5 Manual 679382.89 679433.945 3082731.682 TW01-3748.4 Manual 679470.357 3082776.735 TW01-3849.5 Manual 679497.331 3082840.396 TW01-3955.2 Manual 3082886.899 TW01-4056.4 Manual 679524.331 679560.611 3082897.258 TW01-4112.3 Manual

Area: Area 5

X Coord Y C	Coord Label	Value	Type	Historical
679133.429	3083306.313	TW01-0	114 Ma	anual
679104.245	3083223.262	TW01-0	221.5 Ma	anual
679242.726	3083326.528	TW01-0	7 16.5 Ma	anual
679181.275	3083178.288	TW01-0	8 15.1 Ma	anual
679268.77	3083200.326	TW01-1	114.3 Ma	anual
679301.16	3083254.034	TW01-1	213.3 Ma	anual

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	44
Number of selected sample areas b	2
Specified sampling area ^c	188054.34 m ²
Total cost of sampling d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical				
679133.4290	3083306.3130	J-01S	40.7	Manual	Т				
679104.2450	3083223.2620	J-02S	23.6	Manual	Т				
679155.0740	3083294.6960	J-03S	11.8	Manual	Т				
679171.2970	3083289.7960	J-04S	8.7	Manual	Т				
679225.8560	3083359.9740	J-05S	10.4	Manual	Т				
679164.8060	3083214.7100	J-06S	3.1	Manual	Т				
679242.7260	3083326.5280	J-07S	232	Manual	Т				
679181.2750	3083178.2880	J-08S	80.3	Manual	Т				
679213.7730	3083224.9730	J-09S	16.6	Manual	Т				
679280.5440	3083305.6810	J-10S	22.8	Manual	Т				
679268.7700	3083200.3260	J-11S	25.2	Manual	Т				
679301.1600	3083254.0340	J-12S	6.1	Manual	Т				
679181.7603	3083351.9665	J-13S	17.2	Random					

Area: Area 3							
X Coord	Y Coord	Label	Value	Туре	Historical		

679149.4920 3082933.0980 J-13S 17.2 Manual T 679279.6830 3083075.4290 J-14S 92.6 Manual T 679261.0980 3083016.3510 J-15S 31.1 Manual T 679222.6340 3082840.1720 J-16S 129 Manual T 679293.5600 3082950.4980 J-17S 143 Manual T 679360.5700 3083026.4980 J-18S 35 Manual T 679343.5810 3082969.5980 J-19S 26.15 Manual T 679382.8640 3083009.1130 J-20S 30.2 Manual T 679382.8640 3083009.1130 J-20S 30.2 Manual T 679382.8640 3082971.8300 J-22S 40.65 Manual T 679297.0010 3082840.6970 J-23S 44.1 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679224.5850 308265					
679261.0980 3083016.3510 J-15S 31.1 Manual T 679222.6340 3082840.1720 J-16S 129 Manual T 679293.5600 3082950.4980 J-17S 143 Manual T 679360.5700 3083026.4980 J-18S 35 Manual T 679343.5810 3082969.5980 J-19S 26.15 Manual T 679382.8640 3083009.1130 J-20S 30.2 Manual T 679355.0020 3082941.1720 J-21S 39.5 Manual T 679257.7130 3082781.0290 J-22S 40.65 Manual T 679297.0010 3082840.6970 J-23S 44.1 Manual T 679346.6460 3082549.7640 J-25S 59 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679374.4420 3082711.0960 J-28S 48 Manual T 679470.3460 3082914.	679149.4920	3082933.0980	J-13S	17.2	Manual T
679222.6340 3082840.1720 J-16S 129 Manual T 679293.5600 3082950.4980 J-17S 143 Manual T 679360.5700 3083026.4980 J-18S 35 Manual T 679343.5810 3082969.5980 J-19S 26.15 Manual T 679382.8640 3083009.1130 J-20S 30.2 Manual T 679355.0020 3082941.1720 J-21S 39.5 Manual T 679252.7130 3082781.0290 J-22S 40.65 Manual T 679297.0010 3082840.6970 J-23S 44.1 Manual T 679394.8070 3082549.7640 J-25S 59 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679374.4420 308271.0960 J-29S 48 Manual T 679374.4420 308271.300 J-30S 79 Manual T 679453.4760 3082941.1150 J-32S 59 Manual T 679453.4760 3082941.1150 J-32S 59 Manual T 679304.6530 3082652.6750 J-38S 48 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679453.4760 3082940.9730 J-31S 26.05 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679342.7410 3082695.3190 J-35S 20.1 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679433.9450 308276.7350 J-38S 29.8 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679470.3570 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679560.6070 3082897.2580 J-42SD 28.1 Manual T	679279.6830	3083075.4290	J-14S	92.6	Manual T
679293.5600 3082950.4980 J-17S 143 Manual T 679360.5700 3083026.4980 J-18S 35 Manual T 679343.5810 3082969.5980 J-19S 26.15 Manual T 679382.8640 3083009.1130 J-20S 30.2 Manual T 679352.020 3082941.1720 J-21S 39.5 Manual T 679297.0010 3082840.6970 J-22S 40.65 Manual T 679394.8070 3082971.8300 J-24S 22.2 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679224.5850 3082683.1400 J-26S 24.33 Manual T 679272.0040 3082537.3510 J-27S 29.4 Manual T 679329.4380 3082711.0960 J-29S 48 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082941.1150 J-32S 59 Manual T 679453.4760 3082941.1150 J-32S 59 Manual T 679342.7410 308265.3190 J-35S 20.1 Manual T 679342.7410 308265.3190 J-35S 20.1 Manual T 679342.7410 3082667.5270 J-36S 40.2 Manual T 679342.7410 3082667.5270 J-36S 40.2 Manual T 679343.9450 308276.7350 J-38S 29.8 Manual T 679470.3570 3082840.3960 J-39S 25.9 Manual T 679560.6070 3082887.2580 J-42SD 28.1 Manual T 679560.6070 3082887.2580 J-42SD 28.1 Manual T 679560.6070 3082887.2580 J-42SD 28.1 Manual T	679261.0980	3083016.3510	J-15S	31.1	Manual T
679360.5700 3083026.4980 J-18S 35 Manual T 679343.5810 3082969.5980 J-19S 26.15 Manual T 679382.8640 3083009.1130 J-20S 30.2 Manual T 679335.0020 3082941.1720 J-21S 39.5 Manual T 679252.7130 3082781.0290 J-22S 40.65 Manual T 679297.0010 3082840.6970 J-23S 44.1 Manual T 679394.8070 3082971.8300 J-24S 22.2 Manual T 679394.8070 3082549.7640 J-25S 59 Manual T 679146.6460 3082549.7640 J-26S 24.33 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679372.0040 3082652.6750 J-28S 48 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679495.8840 3082940	679222.6340	3082840.1720	J-16S	129	Manual T
679343.5810 3082969.5980 J-19S 26.15 Manual T 679382.8640 3083009.1130 J-20S 30.2 Manual T 679335.0020 3082941.1720 J-21S 39.5 Manual T 679252.7130 3082781.0290 J-22S 40.65 Manual T 679297.0010 3082840.6970 J-23S 44.1 Manual T 679394.8070 3082971.8300 J-24S 22.2 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082941.1150 J-31S 26.05 Manual T 679495.8840 30829	679293.5600	3082950.4980	J-17S	143	Manual T
679382.8640 3083009.1130 J-20S 30.2 Manual T 679335.0020 3082941.1720 J-21S 39.5 Manual T 679252.7130 3082781.0290 J-22S 40.65 Manual T 679297.0010 3082840.6970 J-23S 44.1 Manual T 679394.8070 3082971.8300 J-24S 22.2 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082591.3300 J-30S 79 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679495.8840 3082914.1150 J-32S 59 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679470.3570 308276.7350 J-38S 29.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679532.9930 3082886.8990 J-40S 31.8 Manual T 679532.9930 3082887.2580 J-42SD 28.1 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679360.5700	3083026.4980	J-18S	35	Manual T
679335.0020 3082941.1720 J-21S 39.5 Manual T 679252.7130 3082781.0290 J-22S 40.65 Manual T 679297.0010 3082840.6970 J-23S 44.1 Manual T 679394.8070 3082971.8300 J-24S 22.2 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679169.0760 3082683.1400 J-26S 24.33 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679342.7410 3082667	679343.5810	3082969.5980	J-19S	26.15	Manual T
679252.7130 3082781.0290 J-22S 40.65 Manual T 679297.0010 3082840.6970 J-23S 44.1 Manual T 679394.8070 3082971.8300 J-24S 22.2 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679224.5850 3082683.1400 J-26S 24.33 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679374.4420 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679453.4760 3082941.1150 J-31S 26.05 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679382.8900 308266	679382.8640	3083009.1130	J-20S	30.2	Manual T
679297.0010 3082840.6970 J-23S 44.1 Manual T 679394.8070 3082971.8300 J-24S 22.2 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679224.5850 3082683.1400 J-26S 24.33 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679382.8900 3082667.5	679335.0020	3082941.1720	J-21S	39.5	Manual T
679394.8070 3082971.8300 J-24S 22.2 Manual T 679146.6460 3082549.7640 J-25S 59 Manual T 679224.5850 3082683.1400 J-26S 24.33 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679470.3570 3082776.7	679252.7130	3082781.0290	J-22S	40.65	Manual T
679146.6460 3082549.7640 J-25S 59 Manual T 679224.5850 3082683.1400 J-26S 24.33 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679470.3570 3082731.6820 J-37S 48.5 Manual T 679524.3310 3082886.8	679297.0010	3082840.6970	J-23S	44.1	Manual T
679224.5850 3082683.1400 J-26S 24.33 Manual T 679169.0760 3082537.3510 J-27S 29.4 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679532.9930	679394.8070	3082971.8300	J-24S	22.2	Manual T
679169.0760 3082537.3510 J-27S 29.4 Manual T 679272.0040 3082652.6750 J-28S 48 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679532.9930 3082897.	679146.6460	3082549.7640	J-25S	59	Manual T
679272.0040 3082652.6750 J-28S 48 Manual T 679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679433.9450 3082667.5270 J-36S 40.2 Manual T 679470.3570 3082731.6820 J-37S 48.5 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679224.5850	3082683.1400	J-26S	24.33	Manual T
679329.4380 3082711.0960 J-29S 19.7 Manual T 679374.4420 3082791.3300 J-30S 79 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679433.9450 3082731.6820 J-37S 48.5 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679169.0760	3082537.3510	J-27S	29.4	Manual T
679374.4420 3082791.3300 J-30S 79 Manual T 679410.1490 3082845.8460 J-31S 26.05 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679470.3570 3082731.6820 J-37S 48.5 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679272.0040	3082652.6750	J-28S	48	Manual T
679410.1490 3082845.8460 J-31S 26.05 Manual T 679453.4760 3082914.1150 J-32S 59 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679470.3570 3082731.6820 J-37S 48.5 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679329.4380	3082711.0960	J-29S	19.7	Manual T
679453.4760 3082914.1150 J-32S 59 Manual T 679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679433.9450 3082731.6820 J-37S 48.5 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679374.4420	3082791.3300	J-30S	79	Manual T
679495.8840 3082940.9730 J-33S 11.1 Manual T 679304.6530 3082548.6880 J-34S 156 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679433.9450 3082731.6820 J-37S 48.5 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679410.1490	3082845.8460	J-31S	26.05	Manual T
679304.6530 3082548.6880 J-34S 156 Manual T 679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679433.9450 3082731.6820 J-37S 48.5 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679453.4760	3082914.1150	J-32S	59	Manual T
679342.7410 3082605.3190 J-35S 20.1 Manual T 679382.8900 3082667.5270 J-36S 40.2 Manual T 679433.9450 3082731.6820 J-37S 48.5 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679495.8840	3082940.9730	J-33S	11.1	Manual T
679382.8900 3082667.5270 J-36S 40.2 Manual T 679433.9450 3082731.6820 J-37S 48.5 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679304.6530	3082548.6880	J-34S	156	Manual T
679433.9450 3082731.6820 J-37S 48.5 Manual T 679470.3570 3082776.7350 J-38S 29.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679342.7410	3082605.3190	J-35S	20.1	Manual T
679470.3570 3082776.7350 J-38S 29.8 Manual T 679497.3310 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679382.8900	3082667.5270	J-36S	40.2	Manual T
679497.3310 3082840.3960 J-39S 25.9 Manual T 679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679433.9450	3082731.6820	J-37S	48.5	Manual T
679524.3310 3082886.8990 J-40S 31.8 Manual T 679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679470.3570	3082776.7350	J-38S	29.8	Manual T
679560.6070 3082897.2580 J-41S 85.3 Manual T 679532.9930 3082835.5820 J-42SD 28.1 Manual T	679497.3310	3082840.3960	J-39S	25.9	Manual T
679532.9930 3082835.5820 J-42SD 28.1 Manual T	679524.3310	3082886.8990	J-40S	31.8	Manual T
07 000210000 000200010020 0 1200 2011 Maintain 1	679560.6070	3082897.2580	J-41S	85.3	Manual T
679552.9590 3082868.6600 J-43SD 144 Manual T	679532.9930	3082835.5820	J-42SD	28.1	Manual T
	679552.9590	3082868.6600	J-43SD	144	Manual T

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples									
AL=9921.5		α	=5	α=10		α=15			
		s=6	s=3	s=6	s=3	s=6	s=3		
	β=5	2	2	1	1	1	1		
LBGR=90	β=10	2	2	1	1	1	1		
	β=15	2	2	1	1	1	1		
	β=5	2	2	1	1	1	1		
LBGR=80	β=10	2	2	1	1	1	1		
	β=15	2	2	1	1	1	1		
LBGR=70	β=5	2	2	1	1	1	1		

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	21 Samples						
Field collection costs		\$100.00	\$2,100.00						
Analytical costs	\$400.00	\$400.00	\$8,400.00						
Sum of Field & Analytical costs		\$500.00	\$10,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$11,500.00						

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	3.1	6.1	8.7	10.4	11.1	11.8	16.6	17.2	17.2	19.7
10	20.1	22.2	22.8	23.6	24.33	25.2	25.9	26.05	26.15	28.1
20	29.4	29.8	30.2	31.1	31.8	35	39.5	40.2	40.65	40.7
30	44.1	48	48.5	59	59	79	80.3	85.3	92.6	129
40	143	144	156	232						

SUMMARY STATISTICS			
n 44			
Min	3.1		
Max	232		
Range	228.9		
Mean	48.056		
Median	30		
Variance	2246.5		
StdDev	47.397		
Std Error	7.1454		
Skewness	2.1279		
Interquartile Range	35.75		

	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
3.1	6.75	10.75	20.63	30	56.38	136	153	232

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST				
k	Test Statistic R _k	5% Critical Value C _k	Significant?	
1	3.881	3.08	Yes	

The test statistic 3.881 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS		
1	232	

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)			
Shapiro-Wilk Test Statistic	0.7802		
Shapiro-Wilk 5% Critical Value	0.943		

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5

times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST			
Shapiro-Wilk Test Statistic	0.7482		
Shapiro-Wilk 5% Critical Value	0.944		

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the

data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN			
95% Parametric UCL	60.07		
95% Non-Parametric (Chebyshev) UC	L 79.2		

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (79.2) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=44 data,

AL is the action level or threshold (9921.5),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=43 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST			
t-statistic	Critical Value t _{0.95}	Null Hypothesis	
-1381.8	1.6811	Reject	

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+)	95% Critical Value	Null Hypothesis		
44	27	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

```
Area: Area 1
X Coord Y Coord Label
                          Value
                                   Type
                                            Historical
                                   17.2 Manual
679149.492
             3082933.098 J-13S
679279.683
             3083075.429 J-14S
                                   92.6 Manual
679261.098
                                   31.1 Manual
             3083016.351 J-15S
679222.634
             3082840.172 J-16S
                                   129 Manual
679293.56
             3082950.498 J-17S
                                   143 Manual
679360.57
             3083026.498 J-18S
                                        Manual
                                   35
                                   26.15
679343.581
             3082969.598 J-19S
                                            Manual
             3083009.113 J-20S
679382.864
                                   30.2 Manual
679335.002
             3082941.172 J-21S
                                   39.5 Manual
679252.713
             3082781.029 J-22S
                                   40.65
                                            Manual
679297.001
             3082840.697 J-23S
                                   44.1 Manual
679394.807
             3082971.83
                          J-24S
                                   22.2 Manual
             3082549.764 J-25S
                                       Manual
679146.646
                                   59
679224.585
             3082683.14
                          J-26S
                                   24.33
                                            Manual
679169.076
             3082537.351 J-27S
                                   29.4 Manual
679272.004
             3082652.675 J-28S
                                   48
                                       Manual
                                   19.7 Manual
679329.438
             3082711.096 J-29S
679374.442
             3082791.33
                          J-30S
                                   79
                                        Manual
                                   26.05
679410.149
             3082845.846 J-31S
                                            Manual
679453.476
             3082914.115 J-32S
                                   59
                                        Manual
679495.884
             3082940.973 J-33S
                                   11.1 Manual
679304.653
             3082548.688 J-34S
                                   156 Manual
679342.741
             3082605.319 J-35S
                                   20.1 Manual
679382.89
             3082667.527 J-36S
                                   40.2 Manual
679433.945
             3082731.682 J-37S
                                   48.5 Manual
679470.357
             3082776.735 J-38S
                                   29.8 Manual
679497.331
             3082840.396 J-39S
                                   25.9 Manual
679524.331
             3082886.899 J-40S
                                   31.8 Manual
679560.607
             3082897.258 J-41S
                                   85.3 Manual
679532.993
             3082835.582 J-42SD
                                   28.1 Manual
                          J-43SD
679552.959
             3082868.66
                                   144 Manual
Area: Area 5
X Coord Y Coord Label
                          Value
                                            Historical
                                   Type
679133.429
             3083306.313 J-01S
                                   40.7 Manual
679104.245
             3083223.262 J-02S
                                   23.6 Manual
679155.074
             3083294.696 J-03S
                                   11.8 Manual
679171.297
             3083289.796 J-04S
                                   8.7 Manual
             3083359.974
                                   10.4 Manual
679225.856
                         J-05S
679164.806
             3083214.71
                          J-06S
                                   3.1 Manual
679242.726
             3083326.528 J-07S
                                   232 Manual
679181.275
             3083178.288 J-08S
                                   80.3 Manual
                                   16.6 Manual
679213.773
             3083224.973
                         J-09S
             3083305.681 J-10S
679280.544
                                   22.8 Manual
679268.77
             3083200.326 J-11S
                                   25.2 Manual
```

3083254.034 J-12S

6.1 Manual

679301.16